

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Mercury (Total) Concentration (ng/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
									300			
Target Air Quality Levels												
EPA Site Specific Trigger Levels									3,000			
TotalHg-ST1-1/6/06	06BR0030-01	Southwest Area (sidewalk bridge level)	1/6/06	0.58	Mercury	EPA 324/1631	BRL	1/10/06	< 26.0	No	No	
TotalHg-ST2-1/6/06	06BR0030-02	Southeast Area (sidewalk bridge level)	1/6/06	0.57	Mercury	EPA 324/1631	BRL	1/10/06	< 26.0	No	No	
TotalHg-ST4-1/6/06	06BR0030-03	Northwest Area (street-level)	1/6/06	0.58	Mercury	EPA 324/1631	BRL	1/10/06	< 26.0	No	No	
TotalHg-ST5-1/6/06	06BR0030-04	Firehouse #10 (roof level)	1/6/06	0.58	Mercury	EPA 324/1631	BRL	1/10/06	< 26.0	No	No	
TotalHg-ST10-1/6/06	06BR0030-05	North Side Sidewalk Bridge	1/6/06	0.57	Mercury	EPA 324/1631	BRL	1/10/06	< 26.0	No	No	
TotalHg-ST100-1/6/06-FD	06BR0030-13	Station 10 Field Duplicate	1/6/06	0.58	Mercury	EPA 324/1631	BRL	1/10/06	< 26.0	No	No	
TotalHg-ST11-1/6/06	06BR0030-06	90 Trinity Place (roof level)	1/6/06	0.59	Mercury	EPA 324/1631	BRL	1/10/06	< 25.0	No	No	
TotalHg-ST12-1/6/06	06BR0030-07	110 Greenwich Street (roof level)	1/6/06	0.62	Mercury	EPA 324/1631	BRL	1/10/06	< 24.0	No	No	
TotalHg-ST13-1/6/06	06BR0030-08	Marriott Hotel, 38th Floor (roof level)	1/6/06	0.60	Mercury	EPA 324/1631	BRL	1/10/06	< 25.0	No	No	
TotalHg-ST14-1/6/06	06BR0030-09	West Face - South end at corner (scaffolding level)	1/6/06	0.54	Mercury	EPA 324/1631	BRL	1/10/06	< 28.0	No	No	
TotalHg-ST15-1/6/06	06BR0030-10	South Face - East end at corner (scaffolding level)	1/6/06	0.54	Mercury	EPA 324/1631	BRL	1/10/06	< 28.0	No	No	
TotalHg-ST16-1/6/06	06BR0030-11	East Face - North end at corner (scaffolding level)	1/6/06	0.54	Mercury	EPA 324/1631	BRL	1/10/06	< 28.0	No	No	
TotalHg-ST17-1/6/06	06BR0030-12	North Face - West end at corner (scaffolding level)	1/6/06	0.54	Mercury	EPA 324/1631	BRL	1/10/06	< 28.0	No	No	
TotalHg-ST1-1/7/06	06BR0031-01	Southwest Area (sidewalk bridge level)	1/7/06	0.57	Mercury	EPA 324/1631	BRL	1/10/06	< 26.0	No	No	
TotalHg-ST2-1/7/06	06BR0031-02	Southeast Area (sidewalk bridge level)	1/7/06	0.56	Mercury	EPA 324/1631	BRL	1/10/06	< 27.0	No	No	
TotalHg-ST4-1/7/06	06BR0031-03	Northwest Area (street-level)	1/7/06	0.56	Mercury	EPA 324/1631	BRL	1/10/06	< 27.0	No	No	
TotalHg-ST5-1/7/06	06BR0031-04	Firehouse #10 (roof level)	1/7/06	0.57	Mercury	EPA 324/1631	BRL	1/10/06	< 26.0	No	No	
TotalHg-ST10-1/7/06	06BR0031-05	North Side Sidewalk Bridge	1/7/06	0.56	Mercury	EPA 324/1631	BRL	1/10/06	< 27.0	No	No	
TotalHg-ST11-1/7/06	06BR0031-06	90 Trinity Place (roof level)	1/7/06	0.57	Mercury	EPA 324/1631	BRL	1/10/06	< 26.0	No	No	
TotalHg-ST12-1/7/06	06BR0031-07	110 Greenwich Street (roof level)	1/7/06	0.53	Mercury	EPA 324/1631	BRL	1/10/06	< 28.0	No	No	
TotalHg-ST13-1/7/06	06BR0031-08	Marriott Hotel, 38th Floor (roof level)	1/7/06	0.52	Mercury	EPA 324/1631	BRL	1/10/06	< 29.0	No	No	
TotalHg-ST14-1/7/06	06BR0031-09	West Face - South end at corner (scaffolding level)	1/7/06	0.57	Mercury	EPA 324/1631	BRL	1/10/06	< 26.0	No	No	
TotalHg-ST15-1/7/06	06BR0031-10	South Face - East end at corner (scaffolding level)	1/7/06	0.56	Mercury	EPA 324/1631	BRL	1/10/06	< 27.0	No	No	
TotalHg-ST16-1/7/06	06BR0031-11	East Face - North end at corner (scaffolding level)	1/7/06	0.56	Mercury	EPA 324/1631	BRL	1/10/06	< 27.0	No	No	
TotalHg-ST17-1/7/06	06BR0031-12	North Face - West end at corner (scaffolding level)	1/7/06	0.56	Mercury	EPA 324/1631	BRL	1/10/06	< 27.0	No	No	
TotalHg-ST1-1/8/06	06BR0032-01	Southwest Area (sidewalk bridge level)	1/8/06	0.58	Mercury	EPA 324/1631	BRL	1/10/06	< 26.0	No	No	
TotalHg-ST2-1/8/06	06BR0032-02	Southeast Area (sidewalk bridge level)	1/8/06	0.58	Mercury	EPA 324/1631	BRL	1/10/06	< 26.0	No	No	
TotalHg-ST4-1/8/06	06BR0032-03	Northwest Area (street-level)	1/8/06	0.59	Mercury	EPA 324/1631	BRL	1/10/06	< 25.0	No	No	
TotalHg-ST5-1/8/06	06BR0032-04	Firehouse #10 (roof level)	1/8/06	0.57	Mercury	EPA 324/1631	BRL	1/10/06	< 26.0	No	No	
TotalHg-ST10-1/8/06	06BR0032-05	North Side Sidewalk Bridge	1/8/06	0.59	Mercury	EPA 324/1631	BRL	1/10/06	< 25.0	No	No	
TotalHg-ST11-1/8/06	06BR0032-06	90 Trinity Place (roof level)	1/8/06	0.56	Mercury	EPA 324/1631	BRL	1/10/06	< 27.0	No	No	
TotalHg-ST12-1/8/06	06BR0032-07	110 Greenwich Street (roof level)	1/8/06	0.57	Mercury	EPA 324/1631	BRL	1/10/06	< 26.0	No	No	
TotalHg-ST13-1/8/06	06BR0032-08	Marriott Hotel, 38th Floor (roof level)	1/8/06	0.58	Mercury	EPA 324/1631	BRL	1/10/06	< 26.0	No	No	
TotalHg-ST14-1/8/06	06BR0032-09	West Face - South end at corner (scaffolding level)	1/8/06	0.61	Mercury	EPA 324/1631	BRL	1/10/06	< 25.0	No	No	
TotalHg-ST15-1/8/06	06BR0032-10	South Face - East end at corner (scaffolding level)	1/8/06	0.60	Mercury	EPA 324/1631	BRL	1/10/06	< 25.0	No	No	
TotalHg-ST16-1/8/06	06BR0032-11	East Face - North end at corner (scaffolding level)	1/8/06	0.60	Mercury	EPA 324/1631	BRL	1/10/06	< 25.0	No	No	
TotalHg-ST17-1/8/06	06BR0032-12	North Face - West end at corner (scaffolding level)	1/8/06	0.60	Mercury	EPA 324/1631	BRL	1/10/06	< 25.0	No	No	