

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Mercury (Total) Concentration (ng/m ³)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
									300			
Target Air Quality Levels												
EPA Site Specific Trigger Levels									3,000			
TotalHg-ST1-1/7/09	0902034-01	Southwest Area (sidewalk bridge level)	1/7/09	0.54	Mercury	EPA 324/1631	BRL	1/9/09	< 28.0	No	No	
TotalHg-ST2-1/7/09	0902034-02	Southeast Area (sidewalk bridge level)	1/7/09	0.54	Mercury	EPA 324/1631	BRL	1/9/09	< 28.0	No	No	
TotalHg-ST5-1/7/09	0902034-03	Firehouse #10 (roof level)	1/7/09	0.56	Mercury	EPA 324/1631	BRL	1/9/09	< 27.0	No	No	
TotalHg-ST10-1/7/09	0902034-04	North Side Sidewalk Bridge	1/7/09	0.52	Mercury	EPA 324/1631	BRL	1/9/09	< 29.0	No	No	
TotalHg-ST11-1/7/09	0902034-05	90 Trinity Place (roof level)	1/7/09	0.57	Mercury	EPA 324/1631	BRL	1/9/09	< 26.0	No	No	
TotalHg-ST12-1/7/09	0902034-06	110 Greenwich Street (roof level)	1/7/09	0.56	Mercury	EPA 324/1631	BRL	1/9/09	< 27.0	No	No	
TotalHg-ST13-1/7/09	0902034-07	Marriott Hotel, 38th Floor (roof level)	1/7/09	0.58	Mercury	EPA 324/1631	BRL	1/9/09	< 26.0	No	No	
TotalHg-ST14-1/7/09	0902034-08	West Face - South end at corner (scaffolding level)	1/7/09	0.58	Mercury	EPA 324/1631	BRL	1/9/09	< 26.0	No	No	
TotalHg-ST15-1/7/09	0902034-09	South Face - East end at corner (scaffolding level)	1/7/09	0.54	Mercury	EPA 324/1631	BRL	1/9/09	< 28.0	No	No	
TotalHg-ST16-1/7/09	0902034-10	East Face - North end at corner (scaffolding level)	1/7/09	0.54	Mercury	EPA 324/1631	BRL	1/9/09	< 28.0	No	No	
TotalHg-ST17-1/7/09	0902034-11	North Face - West end at corner (scaffolding level)	1/7/09	0.58	Mercury	EPA 324/1631	BRL	1/9/09	< 26.0	No	No	
TotalHg-ST1-1/8/09	0902042-01	Southwest Area (sidewalk bridge level)	1/8/09	0.61	Mercury	EPA 324/1631	BRL	1/10/09	< 25.0	No	No	
TotalHg-ST2-1/8/09	0902042-02	Southeast Area (sidewalk bridge level)	1/8/09	0.56	Mercury	EPA 324/1631	BRL	1/10/09	< 27.0	No	No	
TotalHg-ST4-1/8/09	0902042-03	Northwest Area (street-level)	1/8/09	0.61	Mercury	EPA 324/1631	BRL	1/10/09	< 25.0	No	No	
TotalHg-ST5-1/8/09	0902042-04	Firehouse #10 (roof level)	1/8/09	0.58	Mercury	EPA 324/1631	BRL	1/10/09	< 26.0	No	No	
TotalHg-ST10-1/8/09	0902042-05	North Side Sidewalk Bridge	1/8/09	0.54	Mercury	EPA 324/1631	BRL	1/10/09	< 28.0	No	No	
TotalHg-ST11-1/8/09	0902042-06	90 Trinity Place (roof level)	1/8/09	0.60	Mercury	EPA 324/1631	BRL	1/10/09	< 25.0	No	No	
TotalHg-ST12-1/8/09	0902042-07	110 Greenwich Street (roof level)	1/8/09	0.55	Mercury	EPA 324/1631	BRL	1/10/09	< 27.0	No	No	
TotalHg-ST13-1/8/09	0902042-08	Marriott Hotel, 38th Floor (roof level)	1/8/09	0.57	Mercury	EPA 324/1631	BRL	1/10/09	< 26.0	No	No	
TotalHg-ST14-1/8/09	0902042-09	West Face - South end at corner (scaffolding level)	1/8/09	0.58	Mercury	EPA 324/1631	BRL	1/10/09	< 26.0	No	No	
TotalHg-ST15-1/8/09	0902042-10	South Face - East end at corner (scaffolding level)	1/8/09	0.58	Mercury	EPA 324/1631	BRL	1/10/09	< 26.0	No	No	
TotalHg-ST16-1/8/09	0902042-11	East Face - North end at corner (scaffolding level)	1/8/09	0.57	Mercury	EPA 324/1631	BRL	1/10/09	< 26.0	No	No	
TotalHg-ST17-1/8/09	0902042-12	North Face - West end at corner (scaffolding level)	1/8/09	0.56	Mercury	EPA 324/1631	BRL	1/10/09	< 27.0	No	No	
TotalHg-ST1-1/9/09	0903001-01	Southwest Area (sidewalk bridge level)	1/9/09	0.61	Mercury	EPA 324/1631	BRL	1/12/09	< 25.0	No	No	
TotalHg-ST2-1/9/09	0903001-02	Southeast Area (sidewalk bridge level)	1/9/09	0.60	Mercury	EPA 324/1631	BRL	1/12/09	< 25.0	No	No	
TotalHg-ST4-1/9/09	0903001-03	Northwest Area (street-level)	1/9/09	0.57	Mercury	EPA 324/1631	BRL	1/12/09	< 26.0	No	No	
TotalHg-ST5-1/9/09	0903001-04	Firehouse #10 (roof level)	1/9/09	0.55	Mercury	EPA 324/1631	BRL	1/12/09	< 27.0	No	No	
TotalHg-ST10-1/9/09	0903001-05	North Side Sidewalk Bridge	1/9/09	0.58	Mercury	EPA 324/1631	BRL	1/12/09	< 26.0	No	No	
TotalHg-ST11-1/9/09	0903001-06	90 Trinity Place (roof level)	1/9/09	0.54	Mercury	EPA 324/1631	BRL	1/12/09	< 28.0	No	No	
TotalHg-ST12-1/9/09	0903001-07	110 Greenwich Street (roof level)	1/9/09	0.56	Mercury	EPA 324/1631	BRL	1/12/09	< 27.0	No	No	
TotalHg-ST13-1/9/09	0903001-08	Marriott Hotel, 38th Floor (roof level)	1/9/09	0.56	Mercury	EPA 324/1631	BRL	1/12/09	< 27.0	No	No	
TotalHg-ST14-1/9/09	0903001-09	West Face - South end at corner (scaffolding level)	1/9/09	0.55	Mercury	EPA 324/1631	BRL	1/12/09	< 27.0	No	No	
TotalHg-ST15-1/9/09	0903001-10	South Face - East end at corner (scaffolding level)	1/9/09	0.54	Mercury	EPA 324/1631	BRL	1/12/09	< 28.0	No	No	
TotalHg-ST16-1/9/09	0903001-11	East Face - North end at corner (scaffolding level)	1/9/09	0.54	Mercury	EPA 324/1631	BRL	1/12/09	< 28.0	No	No	
TotalHg-ST17-1/9/09	0903001-12	North Face - West end at corner (scaffolding level)	1/9/09	0.53	Mercury	EPA 324/1631	BRL	1/12/09	< 28.0	No	No	

Note:

1. The mercury sample from Station 4 (Northwest Area [street-level]) on January 7, 2009 was not available for analysis on account of a power failure.