

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m <sup>3</sup> )	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Mercury (Total) Concentration (ng/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
									300			
									3,000			
TotalHg-ST1-1/24/06	06BR0116-01	Southwest Area (sidewalk bridge level)	1/24/06	0.57	Mercury	EPA 324/1631	BRL	1/26/06	< 26.0	No	No	
TotalHg-ST2-1/24/06	06BR0116-02	Southeast Area (sidewalk bridge level)	1/24/06	0.57	Mercury	EPA 324/1631	BRL	1/26/06	< 26.0	No	No	
TotalHg-ST4-1/24/06	06BR0116-03	Northwest Area (street-level)	1/24/06	0.56	Mercury	EPA 324/1631	BRL	1/26/06	< 27.0	No	No	
TotalHg-ST5-1/24/06	06BR0116-04	Firehouse #10 (roof level)	1/24/06	0.57	Mercury	EPA 324/1631	BRL	1/26/06	< 26.0	No	No	
TotalHg-ST10-1/24/06	06BR0116-05	North Side Sidewalk Bridge	1/24/06	0.56	Mercury	EPA 324/1631	BRL	1/26/06	< 27.0	No	No	
TotalHg-ST100-1/24/06-FD	06BR0116-13	Station 10 Field Duplicate	1/24/06	0.56	Mercury	EPA 324/1631	BRL	1/26/06	< 27.0	No	No	
TotalHg-ST11-1/24/06	06BR0116-06	90 Trinity Place (roof level)	1/24/06	0.57	Mercury	EPA 324/1631	BRL	1/26/06	< 26.0	No	No	
TotalHg-ST12-1/24/06	06BR0116-07	110 Greenwich Street (roof level)	1/24/06	0.57	Mercury	EPA 324/1631	BRL	1/26/06	< 26.0	No	No	
TotalHg-ST13-1/24/06	06BR0116-08	Marriott Hotel, 38th Floor (roof level)	1/24/06	0.54	Mercury	EPA 324/1631	BRL	1/26/06	< 28.0	No	No	
TotalHg-ST14-1/24/06	06BR0116-09	West Face - South end at corner (scaffolding level)	1/24/06	0.56	Mercury	EPA 324/1631	BRL	1/26/06	< 27.0	No	No	
TotalHg-ST15-1/24/06	06BR0116-10	South Face - East end at corner (scaffolding level)	1/24/06	0.56	Mercury	EPA 324/1631	BRL	1/26/06	< 27.0	No	No	
TotalHg-ST16-1/24/06	06BR0116-11	East Face - North end at corner (scaffolding level)	1/24/06	0.56	Mercury	EPA 324/1631	BRL	1/26/06	< 27.0	No	No	
TotalHg-ST17-1/24/06	06BR0116-12	North Face - West end at corner (scaffolding level)	1/24/06	0.56	Mercury	EPA 324/1631	BRL	1/26/06	< 27.0	No	No	
TotalHg-ST1-1/25/06	06BR0125-01	Southwest Area (sidewalk bridge level)	1/25/06	0.57	Mercury	EPA 324/1631	BRL	1/27/06	< 26.0	No	No	
TotalHg-ST2-1/25/06	06BR0125-02	Southeast Area (sidewalk bridge level)	1/25/06	0.57	Mercury	EPA 324/1631	BRL	1/27/06	< 26.0	No	No	
TotalHg-ST4-1/25/06	06BR0125-03	Northwest Area (street-level)	1/25/06	0.56	Mercury	EPA 324/1631	BRL	1/27/06	< 27.0	No	No	
TotalHg-ST5-1/25/06	06BR0125-04	Firehouse #10 (roof level)	1/25/06	0.57	Mercury	EPA 324/1631	BRL	1/27/06	< 26.0	No	No	
TotalHg-ST10-1/25/06	06BR0125-05	North Side Sidewalk Bridge	1/25/06	0.57	Mercury	EPA 324/1631	BRL	1/27/06	< 26.0	No	No	
TotalHg-ST11-1/25/06	06BR0125-06	90 Trinity Place (roof level)	1/25/06	0.57	Mercury	EPA 324/1631	BRL	1/27/06	< 26.0	No	No	
TotalHg-ST12-1/25/06	06BR0125-07	110 Greenwich Street (roof level)	1/25/06	0.56	Mercury	EPA 324/1631	BRL	1/27/06	< 27.0	No	No	
TotalHg-ST13-1/25/06	06BR0125-08	Marriott Hotel, 38th Floor (roof level)	1/25/06	0.57	Mercury	EPA 324/1631	BRL	1/27/06	< 26.0	No	No	
TotalHg-ST14-1/25/06	06BR0125-09	West Face - South end at corner (scaffolding level)	1/25/06	0.56	Mercury	EPA 324/1631	BRL	1/27/06	< 27.0	No	No	
TotalHg-ST15-1/25/06	06BR0125-10	South Face - East end at corner (scaffolding level)	1/25/06	0.56	Mercury	EPA 324/1631	BRL	1/27/06	< 27.0	No	No	
TotalHg-ST16-1/25/06	06BR0125-11	East Face - North end at corner (scaffolding level)	1/25/06	0.56	Mercury	EPA 324/1631	BRL	1/27/06	< 27.0	No	No	
TotalHg-ST17-1/25/06	06BR0125-12	North Face - West end at corner (scaffolding level)	1/25/06	0.56	Mercury	EPA 324/1631	BRL	1/27/06	< 27.0	No	No	
TotalHg-ST1-1/26/06	06BR0135-01	Southwest Area (sidewalk bridge level)	1/26/06	0.57	Mercury	EPA 324/1631	BRL	1/28/06	< 26.0	No	No	
TotalHg-ST2-1/26/06	06BR0135-02	Southeast Area (sidewalk bridge level)	1/26/06	0.57	Mercury	EPA 324/1631	BRL	1/28/06	< 26.0	No	No	
TotalHg-ST4-1/26/06	06BR0135-03	Northwest Area (street-level)	1/26/06	0.56	Mercury	EPA 324/1631	BRL	1/28/06	< 27.0	No	No	
TotalHg-ST5-1/26/06	06BR0135-04	Firehouse #10 (roof level)	1/26/06	0.57	Mercury	EPA 324/1631	BRL	1/28/06	< 26.0	No	No	
TotalHg-ST10-1/26/06	06BR0135-05	North Side Sidewalk Bridge	1/26/06	0.57	Mercury	EPA 324/1631	BRL	1/28/06	< 26.0	No	No	
TotalHg-ST11-1/26/06	06BR0135-06	90 Trinity Place (roof level)	1/26/06	0.57	Mercury	EPA 324/1631	BRL	1/28/06	< 26.0	No	No	
TotalHg-ST12-1/26/06	06BR0135-07	110 Greenwich Street (roof level)	1/26/06	0.57	Mercury	EPA 324/1631	BRL	1/28/06	< 26.0	No	No	
TotalHg-ST13-1/26/06	06BR0135-08	Marriott Hotel, 38th Floor (roof level)	1/26/06	0.56	Mercury	EPA 324/1631	BRL	1/28/06	< 27.0	No	No	
TotalHg-ST14-1/26/06	06BR0135-09	West Face - South end at corner (scaffolding level)	1/26/06	0.58	Mercury	EPA 324/1631	BRL	1/28/06	< 26.0	No	No	
TotalHg-ST15-1/26/06	06BR0135-10	South Face - East end at corner (scaffolding level)	1/26/06	0.58	Mercury	EPA 324/1631	BRL	1/28/06	< 26.0	No	No	
TotalHg-ST16-1/26/06	06BR0135-11	East Face - North end at corner (scaffolding level)	1/26/06	0.57	Mercury	EPA 324/1631	BRL	1/28/06	< 26.0	No	No	
TotalHg-ST17-1/26/06	06BR0135-12	North Face - West end at corner (scaffolding level)	1/26/06	0.56	Mercury	EPA 324/1631	BRL	1/28/06	< 26.0	No	No	