

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Mercury (Total) Concentration (ng/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
									300			
Target Air Quality Levels												
EPA Site Specific Trigger Levels									3,000			
TotalHg-ST1-1/26/09	0905013-01	Southwest Area (sidewalk bridge level)	1/26/09	0.58	Mercury	EPA 324/1631	BRL	1/28/09	< 26.0	No	No	
TotalHg-ST2-1/26/09	0905013-02	Southeast Area (sidewalk bridge level)	1/26/09	0.59	Mercury	EPA 324/1631	BRL	1/28/09	< 25.0	No	No	
TotalHg-ST4-1/26/09	0905013-03	Northwest Area (street-level)	1/26/09	0.54	Mercury	EPA 324/1631	BRL	1/28/09	< 28.0	No	No	
TotalHg-ST5-1/26/09	0905013-04	Firehouse #10 (roof level)	1/26/09	0.58	Mercury	EPA 324/1631	BRL	1/28/09	< 26.0	No	No	
TotalHg-ST10-1/26/09	0905013-05	North Side Sidewalk Bridge	1/26/09	0.53	Mercury	EPA 324/1631	BRL	1/28/09	< 28.0	No	No	
TotalHg-ST11-1/26/09	0905013-06	90 Trinity Place (roof level)	1/26/09	0.54	Mercury	EPA 324/1631	BRL	1/28/09	< 28.0	No	No	
TotalHg-ST12-1/26/09	0905013-07	110 Greenwich Street (roof level)	1/26/09	0.56	Mercury	EPA 324/1631	BRL	1/28/09	< 27.0	No	No	
TotalHg-ST13-1/26/09	0905013-08	Marriott Hotel, 38th Floor (roof level)	1/26/09	0.56	Mercury	EPA 324/1631	BRL	1/28/09	< 27.0	No	No	
TotalHg-ST14-1/26/09	0905013-09	West Face - South end at corner (scaffolding level)	1/26/09	0.58	Mercury	EPA 324/1631	BRL	1/28/09	< 26.0	No	No	
TotalHg-ST15-1/26/09	0905013-10	South Face - East end at corner (scaffolding level)	1/26/09	0.54	Mercury	EPA 324/1631	BRL	1/28/09	< 28.0	No	No	
TotalHg-ST16-1/26/09	0905013-11	East Face - North end at corner (scaffolding level)	1/26/09	0.52	Mercury	EPA 324/1631	BRL	1/28/09	< 29.0	No	No	
TotalHg-ST17-1/26/09	0905013-12	North Face - West end at corner (scaffolding level)	1/26/09	0.55	Mercury	EPA 324/1631	BRL	1/28/09	< 27.0	No	No	
TotalHg-ST1-1/27/09	0905019-01	Southwest Area (sidewalk bridge level)	1/27/09	0.62	Mercury	EPA 324/1631	BRL	1/29/09	< 24.0	No	No	
TotalHg-ST2-1/27/09	0905019-02	Southeast Area (sidewalk bridge level)	1/27/09	0.55	Mercury	EPA 324/1631	BRL	1/29/09	< 27.0	No	No	
TotalHg-ST4-1/27/09	0905019-03	Northwest Area (street-level)	1/27/09	0.62	Mercury	EPA 324/1631	BRL	1/29/09	< 24.0	No	No	
TotalHg-ST5-1/27/09	0905019-04	Firehouse #10 (roof level)	1/27/09	0.54	Mercury	EPA 324/1631	BRL	1/29/09	< 28.0	No	No	
TotalHg-ST10-1/27/09	0905019-05	North Side Sidewalk Bridge	1/27/09	0.56	Mercury	EPA 324/1631	BRL	1/29/09	< 27.0	No	No	
TotalHg-ST11-1/27/09	0905019-06	90 Trinity Place (roof level)	1/27/09	0.57	Mercury	EPA 324/1631	BRL	1/29/09	< 26.0	No	No	
TotalHg-ST12-1/27/09	0905019-07	110 Greenwich Street (roof level)	1/27/09	0.56	Mercury	EPA 324/1631	BRL	1/29/09	< 27.0	No	No	
TotalHg-ST13-1/27/09	0905019-08	Marriott Hotel, 38th Floor (roof level)	1/27/09	0.59	Mercury	EPA 324/1631	BRL	1/29/09	< 25.0	No	No	
TotalHg-ST14-1/27/09	0905019-09	West Face - South end at corner (scaffolding level)	1/27/09	0.56	Mercury	EPA 324/1631	BRL	1/29/09	< 27.0	No	No	
TotalHg-ST15-1/27/09	0905019-10	South Face - East end at corner (scaffolding level)	1/27/09	0.57	Mercury	EPA 324/1631	BRL	1/29/09	< 26.0	No	No	
TotalHg-ST16-1/27/09	0905019-11	East Face - North end at corner (scaffolding level)	1/27/09	0.57	Mercury	EPA 324/1631	BRL	1/29/09	< 26.0	No	No	
TotalHg-ST17-1/27/09	0905019-12	North Face - West end at corner (scaffolding level)	1/27/09	0.56	Mercury	EPA 324/1631	BRL	1/29/09	< 27.0	No	No	
TotalHg-ST1-1/28/09	0905023-01	Southwest Area (sidewalk bridge level)	1/28/09	0.62	Mercury	EPA 324/1631	BRL	1/30/09	< 24.0	No	No	
TotalHg-ST2-1/28/09	0905023-02	Southeast Area (sidewalk bridge level)	1/28/09	0.57	Mercury	EPA 324/1631	BRL	1/30/09	< 26.0	No	No	
TotalHg-ST5-1/28/09	0905023-03	Firehouse #10 (roof level)	1/28/09	0.53	Mercury	EPA 324/1631	BRL	1/30/09	< 28.0	No	No	
TotalHg-ST10-1/28/09	0905023-04	North Side Sidewalk Bridge	1/28/09	0.50	Mercury	EPA 324/1631	BRL	1/30/09	< 30.0	No	No	
TotalHg-ST11-1/28/09	0905023-05	90 Trinity Place (roof level)	1/28/09	0.57	Mercury	EPA 324/1631	BRL	1/30/09	< 26.0	No	No	
TotalHg-ST12-1/28/09	0905023-06	110 Greenwich Street (roof level)	1/28/09	0.59	Mercury	EPA 324/1631	BRL	1/30/09	< 25.0	No	No	
TotalHg-ST13-1/28/09	0905023-07	Marriott Hotel, 38th Floor (roof level)	1/28/09	0.56	Mercury	EPA 324/1631	BRL	1/30/09	< 27.0	No	No	
TotalHg-ST14-1/28/09	0905023-08	West Face - South end at corner (scaffolding level)	1/28/09	0.60	Mercury	EPA 324/1631	BRL	1/30/09	< 25.0	No	No	
TotalHg-ST15-1/28/09	0905023-09	South Face - East end at corner (scaffolding level)	1/28/09	0.53	Mercury	EPA 324/1631	BRL	1/30/09	< 28.0	No	No	
TotalHg-ST16-1/28/09	0905023-10	East Face - North end at corner (scaffolding level)	1/28/09	0.57	Mercury	EPA 324/1631	BRL	1/30/09	< 26.0	No	No	
TotalHg-ST17-1/28/09	0905023-11	North Face - West end at corner (scaffolding level)	1/28/09	0.60	Mercury	EPA 324/1631	BRL	1/30/09	< 25.0	No	No	

Note:

1. The mercury sample from Station 4 (Northwest Area [street-level]) on January 28, 2009 was not available for analysis on account of power failure.