

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m <sup>3</sup> )	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Mercury (Total) Concentration (ng/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
									300			
									3,000			
TotalHg-ST1-1/30/06	06BR0145-01	Southwest Area (sidewalk bridge level)	1/30/06	0.58	Mercury	EPA 324/1631	BRL	2/1/06	< 26.0	No	No	
TotalHg-ST2-1/30/06	06BR0145-02	Southeast Area (sidewalk bridge level)	1/30/06	0.58	Mercury	EPA 324/1631	BRL	2/1/06	< 26.0	No	No	
TotalHg-ST4-1/30/06	06BR0145-03	Northwest Area (street-level)	1/30/06	0.56	Mercury	EPA 324/1631	BRL	2/1/06	< 27.0	No	No	
TotalHg-ST5-1/30/06	06BR0145-04	Firehouse #10 (roof level)	1/30/06	0.57	Mercury	EPA 324/1631	BRL	2/1/06	< 26.0	No	No	
TotalHg-ST10-1/30/06	06BR0145-05	North Side Sidewalk Bridge	1/30/06	0.56	Mercury	EPA 324/1631	BRL	2/1/06	< 27.0	No	No	
TotalHg-ST11-1/30/06	06BR0145-06	90 Trinity Place (roof level)	1/30/06	0.58	Mercury	EPA 324/1631	BRL	2/1/06	< 26.0	No	No	
TotalHg-ST12-1/30/06	06BR0145-07	110 Greenwich Street (roof level)	1/30/06	0.59	Mercury	EPA 324/1631	BRL	2/1/06	< 25.0	No	No	
TotalHg-ST13-1/30/06	06BR0145-08	Marriott Hotel, 38th Floor (roof level)	1/30/06	0.60	Mercury	EPA 324/1631	BRL	2/1/06	< 25.0	No	No	
TotalHg-ST14-1/30/06	06BR0145-09	West Face - South end at corner (scaffolding level)	1/30/06	0.57	Mercury	EPA 324/1631	BRL	2/1/06	< 26.0	No	No	
TotalHg-ST15-1/30/06	06BR0145-10	South Face - East end at corner (scaffolding level)	1/30/06	0.57	Mercury	EPA 324/1631	BRL	2/1/06	< 26.0	No	No	
TotalHg-ST16-1/30/06	06BR0145-11	East Face - North end at corner (scaffolding level)	1/30/06	0.57	Mercury	EPA 324/1631	BRL	2/1/06	< 26.0	No	No	
TotalHg-ST17-1/30/06	06BR0145-12	North Face - West end at corner (scaffolding level)	1/30/06	0.57	Mercury	EPA 324/1631	BRL	2/1/06	< 26.0	No	No	
TotalHg-ST1-1/31/06	06BR0148-01	Southwest Area (sidewalk bridge level)	1/31/06	0.57	Mercury	EPA 324/1631	BRL	2/2/06	< 26.0	No	No	
TotalHg-ST2-1/31/06	06BR0148-02	Southeast Area (sidewalk bridge level)	1/31/06	0.58	Mercury	EPA 324/1631	BRL	2/2/06	< 26.0	No	No	
TotalHg-ST4-1/31/06	06BR0148-03	Northwest Area (street-level)	1/31/06	0.58	Mercury	EPA 324/1631	BRL	2/2/06	< 26.0	No	No	
TotalHg-ST5-1/31/06	06BR0148-04	Firehouse #10 (roof level)	1/31/06	0.55	Mercury	EPA 324/1631	BRL	2/2/06	< 27.0	No	No	
TotalHg-ST10-1/31/06	06BR0148-05	North Side Sidewalk Bridge	1/31/06	0.57	Mercury	EPA 324/1631	BRL	2/2/06	< 26.0	No	No	
TotalHg-ST11-1/31/06	06BR0148-06	90 Trinity Place (roof level)	1/31/06	0.55	Mercury	EPA 324/1631	BRL	2/2/06	< 27.0	No	No	
TotalHg-ST12-1/31/06	06BR0148-07	110 Greenwich Street (roof level)	1/31/06	0.56	Mercury	EPA 324/1631	BRL	2/2/06	< 27.0	No	No	
TotalHg-ST13-1/31/06	06BR0148-08	Marriott Hotel, 38th Floor (roof level)	1/31/06	0.55	Mercury	EPA 324/1631	BRL	2/2/06	< 27.0	No	No	
TotalHg-ST14-1/31/06	06BR0148-09	West Face - South end at corner (scaffolding level)	1/31/06	0.58	Mercury	EPA 324/1631	BRL	2/2/06	< 26.0	No	No	
TotalHg-ST15-1/31/06	06BR0148-10	South Face - East end at corner (scaffolding level)	1/31/06	0.58	Mercury	EPA 324/1631	BRL	2/2/06	< 26.0	No	No	
TotalHg-ST16-1/31/06	06BR0148-11	East Face - North end at corner (scaffolding level)	1/31/06	0.58	Mercury	EPA 324/1631	BRL	2/2/06	< 26.0	No	No	
TotalHg-ST17-1/31/06	06BR0148-12	North Face - West end at corner (scaffolding level)	1/31/06	0.58	Mercury	EPA 324/1631	BRL	2/2/06	< 26.0	No	No	