

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Mercury (Total) Concentration (ng/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
									300			
									3,000			
TotalHg-ST1-2/3/06	06BR0170-01	Southwest Area (sidewalk bridge level)	2/3/06	0.57	Mercury	EPA 324/1631	BRL	2/7/06	< 26.0	No	No	
TotalHg-ST2-2/3/06	06BR0170-02	Southeast Area (sidewalk bridge level)	2/3/06	0.57	Mercury	EPA 324/1631	BRL	2/7/06	< 26.0	No	No	
TotalHg-ST4-2/3/06	06BR0170-03	Northwest Area (street-level)	2/3/06	0.55	Mercury	EPA 324/1631	BRL	2/7/06	< 27.0	No	No	
TotalHg-ST5-2/3/06	06BR0170-04	Firehouse #10 (roof level)	2/3/06	0.57	Mercury	EPA 324/1631	BRL	2/7/06	< 26.0	No	No	
TotalHg-ST10-2/3/06	06BR0170-05	North Side Sidewalk Bridge	2/3/06	0.55	Mercury	EPA 324/1631	BRL	2/7/06	< 27.0	No	No	
TotalHg-ST11-2/3/06	06BR0170-06	90 Trinity Place (roof level)	2/3/06	0.58	Mercury	EPA 324/1631	BRL	2/7/06	< 26.0	No	No	
TotalHg-ST12-2/3/06	06BR0170-07	110 Greenwich Street (roof level)	2/3/06	0.55	Mercury	EPA 324/1631	BRL	2/7/06	< 27.0	No	No	
TotalHg-ST13-2/3/06	06BR0170-08	Marriott Hotel, 38th Floor (roof level)	2/3/06	0.52	Mercury	EPA 324/1631	BRL	2/7/06	< 29.0	No	No	
TotalHg-ST14-2/3/06	06BR0170-09	West Face - South end at corner (scaffolding level)	2/3/06	0.52	Mercury	EPA 324/1631	BRL	2/7/06	< 29.0	No	No	
TotalHg-ST15-2/3/06	06BR0170-10	South Face - East end at corner (scaffolding level)	2/3/06	0.52	Mercury	EPA 324/1631	BRL	2/7/06	< 29.0	No	No	
TotalHg-ST16-2/3/06	06BR0170-11	East Face - North end at corner (scaffolding level)	2/3/06	0.53	Mercury	EPA 324/1631	BRL	2/7/06	< 28.0	No	No	
TotalHg-ST17-2/3/06	06BR0170-12	North Face - West end at corner (scaffolding level)	2/3/06	0.51	Mercury	EPA 324/1631	BRL	2/7/06	< 29.0	No	No	
TotalHg-ST1-2/4/06	06BR0171-01	Southwest Area (sidewalk bridge level)	2/4/06	0.57	Mercury	EPA 324/1631	BRL	2/7/06	< 26.0	No	No	
TotalHg-ST2-2/4/06	06BR0171-02	Southeast Area (sidewalk bridge level)	2/4/06	0.57	Mercury	EPA 324/1631	BRL	2/7/06	< 26.0	No	No	
TotalHg-ST4-2/4/06	06BR0171-03	Northwest Area (street-level)	2/4/06	0.58	Mercury	EPA 324/1631	BRL	2/7/06	< 26.0	No	No	
TotalHg-ST5-2/4/06	06BR0171-04	Firehouse #10 (roof level)	2/4/06	0.56	Mercury	EPA 324/1631	BRL	2/7/06	< 27.0	No	No	
TotalHg-ST10-2/4/06	06BR0171-05	North Side Sidewalk Bridge	2/4/06	0.58	Mercury	EPA 324/1631	BRL	2/7/06	< 26.0	No	No	
TotalHg-ST11-2/4/06	06BR0171-06	90 Trinity Place (roof level)	2/4/06	0.58	Mercury	EPA 324/1631	BRL	2/7/06	< 26.0	No	No	
TotalHg-ST12-2/4/06	06BR0171-07	110 Greenwich Street (roof level)	2/4/06	0.55	Mercury	EPA 324/1631	BRL	2/7/06	< 27.0	No	No	
TotalHg-ST13-2/4/06	06BR0171-08	Marriott Hotel, 38th Floor (roof level)	2/4/06	0.59	Mercury	EPA 324/1631	BRL	2/7/06	< 25.0	No	No	
TotalHg-ST14-2/4/06	06BR0171-09	West Face - South end at corner (scaffolding level)	2/4/06	0.57	Mercury	EPA 324/1631	BRL	2/7/06	< 26.0	No	No	
TotalHg-ST15-2/4/06	06BR0171-10	South Face - East end at corner (scaffolding level)	2/4/06	0.56	Mercury	EPA 324/1631	BRL	2/7/06	< 27.0	No	No	
TotalHg-ST16-2/4/06	06BR0171-11	East Face - North end at corner (scaffolding level)	2/4/06	0.57	Mercury	EPA 324/1631	BRL	2/7/06	< 26.0	No	No	
TotalHg-ST17-2/4/06	06BR0171-12	North Face - West end at corner (scaffolding level)	2/4/06	0.57	Mercury	EPA 324/1631	BRL	2/7/06	< 26.0	No	No	
TotalHg-ST2-2/5/06	06BR0172-01	Southeast Area (sidewalk bridge level)	2/5/06	0.57	Mercury	EPA 324/1631	BRL	2/7/06	< 26.0	No	No	
TotalHg-ST4-2/5/06	06BR0172-02	Northwest Area (street-level)	2/5/06	0.58	Mercury	EPA 324/1631	BRL	2/7/06	< 26.0	No	No	
TotalHg-ST5-2/5/06	06BR0172-03	Firehouse #10 (roof level)	2/5/06	0.59	Mercury	EPA 324/1631	BRL	2/7/06	< 25.0	No	No	
TotalHg-ST10-2/5/06	06BR0172-04	North Side Sidewalk Bridge	2/5/06	0.60	Mercury	EPA 324/1631	BRL	2/7/06	< 25.0	No	No	
TotalHg-ST11-2/5/06	06BR0172-05	90 Trinity Place (roof level)	2/5/06	0.56	Mercury	EPA 324/1631	BRL	2/7/06	< 27.0	No	No	
TotalHg-ST12-2/5/06	06BR0172-06	110 Greenwich Street (roof level)	2/5/06	0.56	Mercury	EPA 324/1631	BRL	2/7/06	< 27.0	No	No	
TotalHg-ST13-2/5/06	06BR0172-07	Marriott Hotel, 38th Floor (roof level)	2/5/06	0.56	Mercury	EPA 324/1631	BRL	2/7/06	< 27.0	No	No	
TotalHg-ST14-2/5/06	06BR0172-08	West Face - South end at corner (scaffolding level)	2/5/06	0.62	Mercury	EPA 324/1631	BRL	2/7/06	< 24.0	No	No	
TotalHg-ST15-2/5/06	06BR0172-09	South Face - East end at corner (scaffolding level)	2/5/06	0.62	Mercury	EPA 324/1631	BRL	2/7/06	< 24.0	No	No	
TotalHg-ST16-2/5/06	06BR0172-10	East Face - North end at corner (scaffolding level)	2/5/06	0.62	Mercury	EPA 324/1631	BRL	2/7/06	< 24.0	No	No	
TotalHg-ST17-2/5/06	06BR0172-11	North Face - West end at corner (scaffolding level)	2/5/06	0.62	Mercury	EPA 324/1631	BRL	2/7/06	< 24.0	No	No	

Notes:

- Mercury sample at Station 1 (Southwest Area [sidewalk bridge level]) on February 5, 2006 was not available for analysis on account of pump failure.