

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Mercury (Total) Concentration (ng/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
									300			
									3,000			
TotalHg-ST1-2/24/06	06BR0285-01	Southwest Area (sidewalk bridge level)	2/24/06	0.59	Mercury	EPA 324/1631	BRL	2/28/06	< 25.0	No	No	
TotalHg-ST2-2/24/06	06BR0285-02	Southeast Area (sidewalk bridge level)	2/24/06	0.59	Mercury	EPA 324/1631	BRL	2/28/06	< 25.0	No	No	
TotalHg-ST4-2/24/06	06BR0285-03	Northwest Area (street-level)	2/24/06	0.59	Mercury	EPA 324/1631	BRL	2/28/06	< 25.0	No	No	
TotalHg-ST5-2/24/06	06BR0285-04	Firehouse #10 (roof level)	2/24/06	0.57	Mercury	EPA 324/1631	BRL	2/28/06	< 26.0	No	No	
TotalHg-ST10-2/24/06	06BR0285-05	North Side Sidewalk Bridge	2/24/06	0.59	Mercury	EPA 324/1631	BRL	2/28/06	< 25.0	No	No	
TotalHg-ST11-2/24/06	06BR0285-06	90 Trinity Place (roof level)	2/24/06	0.57	Mercury	EPA 324/1631	BRL	2/28/06	< 26.0	No	No	
TotalHg-ST13-2/24/06	06BR0285-07	Marriott Hotel, 38th Floor (roof level)	2/24/06	0.59	Mercury	EPA 324/1631	BRL	2/28/06	< 25.0	No	No	
TotalHg-ST14-2/24/06	06BR0285-08	West Face - South end at corner (scaffolding level)	2/24/06	0.54	Mercury	EPA 324/1631	BRL	2/28/06	< 28.0	No	No	
TotalHg-ST15-2/24/06	06BR0285-09	South Face - East end at corner (scaffolding level)	2/24/06	0.54	Mercury	EPA 324/1631	BRL	2/28/06	< 28.0	No	No	
TotalHg-ST16-2/24/06	06BR0285-10	East Face - North end at corner (scaffolding level)	2/24/06	0.55	Mercury	EPA 324/1631	BRL	2/28/06	< 27.0	No	No	
TotalHg-ST17-2/24/06	06BR0285-11	North Face - West end at corner (scaffolding level)	2/24/06	0.54	Mercury	EPA 324/1631	BRL	2/28/06	< 28.0	No	No	
TotalHg-ST1-2/25/06	06BR0287-01	Southwest Area (sidewalk bridge level)	2/25/06	0.58	Mercury	EPA 324/1631	BRL	2/28/06	< 26.0	No	No	
TotalHg-ST2-2/25/06	06BR0287-02	Southeast Area (sidewalk bridge level)	2/25/06	0.58	Mercury	EPA 324/1631	BRL	2/28/06	< 26.0	No	No	
TotalHg-ST4-2/25/06	06BR0287-03	Northwest Area (street-level)	2/25/06	0.57	Mercury	EPA 324/1631	BRL	2/28/06	< 26.0	No	No	
TotalHg-ST5-2/25/06	06BR0287-04	Firehouse #10 (roof level)	2/25/06	0.57	Mercury	EPA 324/1631	BRL	2/28/06	< 26.0	No	No	
TotalHg-ST10-2/25/06	06BR0287-05	North Side Sidewalk Bridge	2/25/06	0.58	Mercury	EPA 324/1631	BRL	2/28/06	< 26.0	No	No	
TotalHg-ST11-2/25/06	06BR0287-06	90 Trinity Place (roof level)	2/25/06	0.57	Mercury	EPA 324/1631	BRL	2/28/06	< 26.0	No	No	
TotalHg-ST12-2/25/06	06BR0287-07	110 Greenwich Street (roof level)	2/25/06	0.56	Mercury	EPA 324/1631	BRL	2/28/06	< 27.0	No	No	
TotalHg-ST13-2/25/06	06BR0287-08	Marriott Hotel, 38th Floor (roof level)	2/25/06	0.55	Mercury	EPA 324/1631	BRL	2/28/06	< 27.0	No	No	
TotalHg-ST1-2/26/06	06BR0286-01	Southwest Area (sidewalk bridge level)	2/26/06	0.56	Mercury	EPA 324/1631	BRL	2/28/06	< 27.0	No	No	
TotalHg-ST2-2/26/06	06BR0286-02	Southeast Area (sidewalk bridge level)	2/26/06	0.56	Mercury	EPA 324/1631	BRL	2/28/06	< 27.0	No	No	
TotalHg-ST4-2/26/06	06BR0286-03	Northwest Area (street-level)	2/26/06	0.57	Mercury	EPA 324/1631	BRL	2/28/06	< 26.0	No	No	
TotalHg-ST5-2/26/06	06BR0286-04	Firehouse #10 (roof level)	2/26/06	0.57	Mercury	EPA 324/1631	BRL	2/28/06	< 26.0	No	No	
TotalHg-ST10-2/26/06	06BR0286-05	North Side Sidewalk Bridge	2/26/06	0.57	Mercury	EPA 324/1631	BRL	2/28/06	< 26.0	No	No	
TotalHg-ST11-2/26/06	06BR0286-06	90 Trinity Place (roof level)	2/26/06	0.56	Mercury	EPA 324/1631	BRL	2/28/06	< 27.0	No	No	
TotalHg-ST12-2/26/06	06BR0286-07	110 Greenwich Street (roof level)	2/26/06	0.60	Mercury	EPA 324/1631	BRL	2/28/06	< 25.0	No	No	
TotalHg-ST13-2/26/06	06BR0286-08	Marriott Hotel, 38th Floor (roof level)	2/26/06	0.56	Mercury	EPA 324/1631	BRL	2/28/06	< 27.0	No	No	

Notes:

- Mercury sample was not available for analysis at Station 12 (110 Greenwich Street [roof level]) on February 24, 2006, on account of pump failure.
- Mercury samples were not available for analysis on February 25 and 26, 2006 at the following locations: Station 14 (West Face - South end at corner [scaffolding level]), Station 15 (South Face - East end at corner [scaffolding level]), Station 16 (East Face - North end at corner [scaffolding level]), and Station 17 (North Face - West end at corner [scaffolding level]). The elevator was out of service on February 26, 2006, rendering the scaffolding stations inaccessible on these dates.