

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Mercury (Total) Concentration (ng/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
									300			
Target Air Quality Levels												
EPA Site Specific Trigger Levels									3,000			
TotalHg-ST1-3/6/06	06BR0333-01	Southwest Area (sidewalk bridge level)	3/6/06	0.59	Mercury	EPA 324/1631	BRL	3/8/06	< 25.0	No	No	
TotalHg-ST2-3/6/06	06BR0333-02	Southeast Area (sidewalk bridge level)	3/6/06	0.59	Mercury	EPA 324/1631	BRL	3/8/06	< 25.0	No	No	
TotalHg-ST4-3/6/06	06BR0333-03	Northwest Area (street-level)	3/6/06	0.57	Mercury	EPA 324/1631	BRL	3/8/06	< 26.0	No	No	
TotalHg-ST5-3/6/06	06BR0333-04	Firehouse #10 (roof level)	3/6/06	0.58	Mercury	EPA 324/1631	BRL	3/8/06	< 26.0	No	No	
TotalHg-ST10-3/6/06	06BR0333-05	North Side Sidewalk Bridge	3/6/06	0.58	Mercury	EPA 324/1631	BRL	3/8/06	< 26.0	No	No	
TotalHg-ST11-3/6/06	06BR0333-06	90 Trinity Place (roof level)	3/6/06	0.58	Mercury	EPA 324/1631	BRL	3/8/06	< 26.0	No	No	
TotalHg-ST12-3/6/06	06BR0333-07	110 Greenwich Street (roof level)	3/6/06	0.58	Mercury	EPA 324/1631	BRL	3/8/06	< 26.0	No	No	
TotalHg-ST13-3/6/06	06BR0333-08	Marriott Hotel, 38th Floor (roof level)	3/6/06	0.58	Mercury	EPA 324/1631	BRL	3/8/06	< 26.0	No	No	
TotalHg-ST14-3/6/06	06BR0333-09	West Face - South end at corner (scaffolding level)	3/6/06	0.58	Mercury	EPA 324/1631	BRL	3/8/06	< 26.0	No	No	
TotalHg-ST15-3/6/06	06BR0333-10	South Face - East end at corner (scaffolding level)	3/6/06	0.58	Mercury	EPA 324/1631	BRL	3/8/06	< 26.0	No	No	
TotalHg-ST16-3/6/06	06BR0333-11	East Face - North end at corner (scaffolding level)	3/6/06	0.57	Mercury	EPA 324/1631	BRL	3/8/06	< 26.0	No	No	
TotalHg-ST17-3/6/06	06BR0333-12	North Face - West end at corner (scaffolding level)	3/6/06	0.58	Mercury	EPA 324/1631	BRL	3/8/06	< 26.0	No	No	
TotalHg-ST1-3/7/06	06BR0342-01	Southwest Area (sidewalk bridge level)	3/7/06	0.57	Mercury	EPA 324/1631	BRL	3/9/06	< 26.0	No	No	
TotalHg-ST2-3/7/06	06BR0342-02	Southeast Area (sidewalk bridge level)	3/7/06	0.58	Mercury	EPA 324/1631	BRL	3/9/06	< 26.0	No	No	
TotalHg-ST4-3/7/06	06BR0342-03	Northwest Area (street-level)	3/7/06	0.57	Mercury	EPA 324/1631	BRL	3/9/06	< 26.0	No	No	
TotalHg-ST5-3/7/06	06BR0342-04	Firehouse #10 (roof level)	3/7/06	0.57	Mercury	EPA 324/1631	BRL	3/9/06	< 26.0	No	No	
TotalHg-ST11-3/7/06	06BR0342-05	90 Trinity Place (roof level)	3/7/06	0.57	Mercury	EPA 324/1631	BRL	3/9/06	< 26.0	No	No	
TotalHg-ST12-3/7/06	06BR0342-06	110 Greenwich Street (roof level)	3/7/06	0.57	Mercury	EPA 324/1631	BRL	3/9/06	< 26.0	No	No	
TotalHg-ST13-3/7/06	06BR0342-07	Marriott Hotel, 38th Floor (roof level)	3/7/06	0.57	Mercury	EPA 324/1631	BRL	3/9/06	< 26.0	No	No	
TotalHg-ST14-3/7/06	06BR0342-08	West Face - South end at corner (scaffolding level)	3/7/06	0.57	Mercury	EPA 324/1631	BRL	3/9/06	< 26.0	No	No	
TotalHg-ST15-3/7/06	06BR0342-09	South Face - East end at corner (scaffolding level)	3/7/06	0.57	Mercury	EPA 324/1631	BRL	3/9/06	< 26.0	No	No	
TotalHg-ST16-3/7/06	06BR0342-10	East Face - North end at corner (scaffolding level)	3/7/06	0.57	Mercury	EPA 324/1631	BRL	3/9/06	< 26.0	No	No	
TotalHg-ST17-3/7/06	06BR0342-11	North Face - West end at corner (scaffolding level)	3/7/06	0.57	Mercury	EPA 324/1631	BRL	3/9/06	< 26.0	No	No	

Note:

- Mercury sample was not available for analysis at Station 10 (North Side [sidewalk bridge level]) on March 7, 2006, on account of pump failure.