

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Mercury (Total) Concentration (ng/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
									300			
									3,000			
TotalHg-ST1-3/10/06	06BR0362-01	Southwest Area (sidewalk bridge level)	3/10/06	0.58	Mercury	EPA 324/1631	BRL	3/14/06	< 26.0	No	No	
TotalHg-ST2-3/10/06	06BR0362-02	Southeast Area (sidewalk bridge level)	3/10/06	0.58	Mercury	EPA 324/1631	BRL	3/14/06	< 26.0	No	No	
TotalHg-ST4-3/10/06	06BR0362-03	Northwest Area (street-level)	3/10/06	0.59	Mercury	EPA 324/1631	BRL	3/14/06	< 25.0	No	No	
TotalHg-ST5-3/10/06	06BR0362-04	Firehouse #10 (roof level)	3/10/06	0.57	Mercury	EPA 324/1631	BRL	3/14/06	< 26.0	No	No	
TotalHg-ST10-3/10/06	06BR0362-05	North Side Sidewalk Bridge	3/10/06	0.59	Mercury	EPA 324/1631	BRL	3/14/06	< 25.0	No	No	
TotalHg-ST11-3/10/06	06BR0362-06	90 Trinity Place (roof level)	3/10/06	0.59	Mercury	EPA 324/1631	BRL	3/14/06	< 25.0	No	No	
TotalHg-ST12-3/10/06	06BR0362-07	110 Greenwich Street (roof level)	3/10/06	0.59	Mercury	EPA 324/1631	BRL	3/14/06	< 25.0	No	No	
TotalHg-ST13-3/10/06	06BR0362-08	Marriott Hotel, 38th Floor (roof level)	3/10/06	0.59	Mercury	EPA 324/1631	BRL	3/14/06	< 25.0	No	No	
TotalHg-ST14-3/10/06	06BR0362-09	West Face - South end at corner (scaffolding level)	3/10/06	0.55	Mercury	EPA 324/1631	BRL	3/14/06	< 27.0	No	No	
TotalHg-ST15-3/10/06	06BR0362-10	South Face - East end at corner (scaffolding level)	3/10/06	0.53	Mercury	EPA 324/1631	BRL	3/14/06	< 28.0	No	No	
TotalHg-ST16-3/10/06	06BR0362-11	East Face - North end at corner (scaffolding level)	3/10/06	0.54	Mercury	EPA 324/1631	BRL	3/14/06	< 28.0	No	No	
TotalHg-ST17-3/10/06	06BR0362-12	North Face - West end at corner (scaffolding level)	3/10/06	0.55	Mercury	EPA 324/1631	BRL	3/14/06	< 27.0	No	No	
TotalHg-ST1-3/11/06	06BR0363-01	Southwest Area (sidewalk bridge level)	3/11/06	0.57	Mercury	EPA 324/1631	BRL	3/14/06	< 26.0	No	No	
TotalHg-ST2-3/11/06	06BR0363-02	Southeast Area (sidewalk bridge level)	3/11/06	0.57	Mercury	EPA 324/1631	BRL	3/14/06	< 26.0	No	No	
TotalHg-ST4-3/11/06	06BR0363-03	Northwest Area (street-level)	3/11/06	0.57	Mercury	EPA 324/1631	BRL	3/14/06	< 26.0	No	No	
TotalHg-ST5-3/11/06	06BR0363-04	Firehouse #10 (roof level)	3/11/06	0.57	Mercury	EPA 324/1631	BRL	3/14/06	< 26.0	No	No	
TotalHg-ST10-3/11/06	06BR0363-05	North Side Sidewalk Bridge	3/11/06	0.57	Mercury	EPA 324/1631	BRL	3/14/06	< 26.0	No	No	
TotalHg-ST11-3/11/06	06BR0363-06	90 Trinity Place (roof level)	3/11/06	0.57	Mercury	EPA 324/1631	BRL	3/14/06	< 26.0	No	No	
TotalHg-ST12-3/11/06	06BR0363-07	110 Greenwich Street (roof level)	3/11/06	0.55	Mercury	EPA 324/1631	BRL	3/14/06	< 27.0	No	No	
TotalHg-ST13-3/11/06	06BR0363-08	Marriott Hotel, 38th Floor (roof level)	3/11/06	0.53	Mercury	EPA 324/1631	BRL	3/14/06	< 28.0	No	No	
TotalHg-ST14-3/11/06	06BR0363-09	West Face - South end at corner (scaffolding level)	3/11/06	0.57	Mercury	EPA 324/1631	BRL	3/14/06	< 26.0	No	No	
TotalHg-ST15-3/11/06	06BR0363-10	South Face - East end at corner (scaffolding level)	3/11/06	0.58	Mercury	EPA 324/1631	BRL	3/14/06	< 26.0	No	No	
TotalHg-ST16-3/11/06	06BR0363-11	East Face - North end at corner (scaffolding level)	3/11/06	0.58	Mercury	EPA 324/1631	BRL	3/14/06	< 26.0	No	No	
TotalHg-ST17-3/11/06	06BR0363-12	North Face - West end at corner (scaffolding level)	3/11/06	0.57	Mercury	EPA 324/1631	BRL	3/14/06	< 26.0	No	No	
TotalHg-ST1-3/12/06	06BR0364-01	Southwest Area (sidewalk bridge level)	3/12/06	0.57	Mercury	EPA 324/1631	BRL	3/14/06	< 26.0	No	No	
TotalHg-ST2-3/12/06	06BR0364-02	Southeast Area (sidewalk bridge level)	3/12/06	0.57	Mercury	EPA 324/1631	BRL	3/14/06	< 26.0	No	No	
TotalHg-ST4-3/12/06	06BR0364-03	Northwest Area (street-level)	3/12/06	0.55	Mercury	EPA 324/1631	BRL	3/14/06	< 27.0	No	No	
TotalHg-ST5-3/12/06	06BR0364-04	Firehouse #10 (roof level)	3/12/06	0.57	Mercury	EPA 324/1631	BRL	3/14/06	< 26.0	No	No	
TotalHg-ST10-3/12/06	06BR0364-05	North Side Sidewalk Bridge	3/12/06	0.55	Mercury	EPA 324/1631	BRL	3/14/06	< 27.0	No	No	
TotalHg-ST11-3/12/06	06BR0364-06	90 Trinity Place (roof level)	3/12/06	0.56	Mercury	EPA 324/1631	BRL	3/14/06	< 27.0	No	No	
TotalHg-ST12-3/12/06	06BR0364-07	110 Greenwich Street (roof level)	3/12/06	0.58	Mercury	EPA 324/1631	BRL	3/14/06	< 26.0	No	No	
TotalHg-ST13-3/12/06	06BR0364-08	Marriott Hotel, 38th Floor (roof level)	3/12/06	0.59	Mercury	EPA 324/1631	BRL	3/14/06	< 25.0	No	No	
TotalHg-ST14-3/12/06	06BR0364-09	West Face - South end at corner (scaffolding level)	3/12/06	0.60	Mercury	EPA 324/1631	BRL	3/14/06	< 25.0	No	No	
TotalHg-ST15-3/12/06	06BR0364-10	South Face - East end at corner (scaffolding level)	3/12/06	0.60	Mercury	EPA 324/1631	BRL	3/14/06	< 25.0	No	No	
TotalHg-ST16-3/12/06	06BR0364-11	East Face - North end at corner (scaffolding level)	3/12/06	0.59	Mercury	EPA 324/1631	BRL	3/14/06	< 25.0	No	No	
TotalHg-ST17-3/12/06	06BR0364-12	North Face - West end at corner (scaffolding level)	3/12/06	0.60	Mercury	EPA 324/1631	BRL	3/14/06	< 25.0	No	No	