

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Mercury (Total) Concentration (ng/m3)		Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
									300	3,000			
									Target Air Quality Levels				
EPA Site Specific Trigger Levels													
TotalHg-ST1-3/12/08	0811040-01	Southwest Area (sidewalk bridge level)	3/12/08	0.55	Mercury	EPA 324/1631	BRL	3/14/08	< 27.0		No	No	
TotalHg-ST2-3/12/08	0811040-02	Southeast Area (sidewalk bridge level)	3/12/08	0.58	Mercury	EPA 324/1631	BRL	3/14/08	< 26.0		No	No	
TotalHg-ST4-3/12/08	0811040-03	Northwest Area (street-level)	3/12/08	0.55	Mercury	EPA 324/1631	BRL	3/14/08	< 27.0		No	No	
TotalHg-ST5-3/12/08	0811040-04	Firehouse #10 (roof level)	3/12/08	0.55	Mercury	EPA 324/1631	BRL	3/14/08	< 27.0		No	No	
TotalHg-ST10-3/12/08	0811040-05	North Side Sidewalk Bridge	3/12/08	0.63	Mercury	EPA 324/1631	BRL	3/14/08	< 24.0		No	No	
TotalHg-ST11-3/12/08	0811040-06	90 Trinity Place (roof level)	3/12/08	0.52	Mercury	EPA 324/1631	BRL	3/14/08	< 29.0		No	No	
TotalHg-ST12-3/12/08	0811040-07	110 Greenwich Street (roof level)	3/12/08	0.57	Mercury	EPA 324/1631	BRL	3/14/08	< 26.0		No	No	
TotalHg-ST13-3/12/08	0811040-08	Marriott Hotel, 38th Floor (roof level)	3/12/08	0.52	Mercury	EPA 324/1631	BRL	3/14/08	< 29.0		No	No	
TotalHg-ST14-3/12/08	0811040-09	West Face - South end at corner (scaffolding level)	3/12/08	0.56	Mercury	EPA 324/1631	BRL	3/14/08	< 27.0		No	No	
TotalHg-ST15-3/12/08	0811040-10	South Face - East end at corner (scaffolding level)	3/12/08	0.58	Mercury	EPA 324/1631	BRL	3/14/08	< 26.0		No	No	
TotalHg-ST16-3/12/08	0811040-11	East Face - North end at corner (scaffolding level)	3/12/08	0.59	Mercury	EPA 324/1631	BRL	3/14/08	< 25.0		No	No	
TotalHg-ST17-3/12/08	0811040-12	North Face - West end at corner (scaffolding level)	3/12/08	0.55	Mercury	EPA 324/1631	BRL	3/14/08	< 27.0		No	No	
TotalHg-ST1-3/13/08	0811050-01	Southwest Area (sidewalk bridge level)	3/13/08	0.63	Mercury	EPA 324/1631	BRL	3/15/08	< 24.0		No	No	
TotalHg-ST2-3/13/08	0811050-02	Southeast Area (sidewalk bridge level)	3/13/08	0.57	Mercury	EPA 324/1631	BRL	3/15/08	< 26.0		No	No	
TotalHg-ST4-3/13/08	0811050-03	Northwest Area (street-level)	3/13/08	0.58	Mercury	EPA 324/1631	BRL	3/15/08	< 26.0		No	No	
TotalHg-ST5-3/13/08	0811050-04	Firehouse #10 (roof level)	3/13/08	0.57	Mercury	EPA 324/1631	BRL	3/15/08	< 26.0		No	No	
TotalHg-ST10-3/13/08	0811050-05	North Side Sidewalk Bridge	3/13/08	0.56	Mercury	EPA 324/1631	BRL	3/15/08	< 27.0		No	No	
TotalHg-ST11-3/13/08	0811050-06	90 Trinity Place (roof level)	3/13/08	0.56	Mercury	EPA 324/1631	BRL	3/15/08	< 27.0		No	No	
TotalHg-ST12-3/13/08	0811050-07	110 Greenwich Street (roof level)	3/13/08	0.60	Mercury	EPA 324/1631	BRL	3/15/08	< 25.0		No	No	
TotalHg-ST13-3/13/08	0811050-08	Marriott Hotel, 38th Floor (roof level)	3/13/08	0.56	Mercury	EPA 324/1631	BRL	3/15/08	< 27.0		No	No	
TotalHg-ST14-3/13/08	0811050-09	West Face - South end at corner (scaffolding level)	3/13/08	0.56	Mercury	EPA 324/1631	BRL	3/15/08	< 27.0		No	No	
TotalHg-ST15-3/13/08	0811050-10	South Face - East end at corner (scaffolding level)	3/13/08	0.60	Mercury	EPA 324/1631	BRL	3/15/08	< 25.0		No	No	
TotalHg-ST16-3/13/08	0811050-11	East Face - North end at corner (scaffolding level)	3/13/08	0.61	Mercury	EPA 324/1631	BRL	3/15/08	< 25.0		No	No	
TotalHg-ST17-3/13/08	0811050-12	North Face - West end at corner (scaffolding level)	3/13/08	0.54	Mercury	EPA 324/1631	BRL	3/15/08	< 28.0		No	No	
TotalHg-ST1-3/14/08	0812002-01	Southwest Area (sidewalk bridge level)	3/14/08	0.55	Mercury	EPA 324/1631	BRL	3/17/08	< 27.0		No	No	
TotalHg-ST2-3/14/08	0812002-02	Southeast Area (sidewalk bridge level)	3/14/08	0.54	Mercury	EPA 324/1631	BRL	3/17/08	< 28.0		No	No	
TotalHg-ST4-3/14/08	0812002-03	Northwest Area (street-level)	3/14/08	0.59	Mercury	EPA 324/1631	BRL	3/17/08	< 25.0		No	No	
TotalHg-ST5-3/14/08	0812002-04	Firehouse #10 (roof level)	3/14/08	0.55	Mercury	EPA 324/1631	BRL	3/17/08	< 27.0		No	No	
TotalHg-ST10-3/14/08	0812002-05	North Side Sidewalk Bridge	3/14/08	0.56	Mercury	EPA 324/1631	BRL	3/17/08	< 27.0		No	No	
TotalHg-ST11-3/14/08	0812002-06	90 Trinity Place (roof level)	3/14/08	0.57	Mercury	EPA 324/1631	BRL	3/17/08	< 26.0		No	No	
TotalHg-ST12-3/14/08	0812002-07	110 Greenwich Street (roof level)	3/14/08	0.58	Mercury	EPA 324/1631	BRL	3/17/08	< 26.0		No	No	
TotalHg-ST13-3/14/08	0812002-08	Marriott Hotel, 38th Floor (roof level)	3/14/08	0.55	Mercury	EPA 324/1631	BRL	3/17/08	< 27.0		No	No	
TotalHg-ST14-3/14/08	0812002-09	West Face - South end at corner (scaffolding level)	3/14/08	0.56	Mercury	EPA 324/1631	BRL	3/17/08	< 27.0		No	No	
TotalHg-ST15-3/14/08	0812002-10	South Face - East end at corner (scaffolding level)	3/14/08	0.55	Mercury	EPA 324/1631	BRL	3/17/08	< 27.0		No	No	
TotalHg-ST16-3/14/08	0812002-11	East Face - North end at corner (scaffolding level)	3/14/08	0.52	Mercury	EPA 324/1631	BRL	3/17/08	< 29.0		No	No	
TotalHg-ST17-3/14/08	0812002-12	North Face - West end at corner (scaffolding level)	3/14/08	0.54	Mercury	EPA 324/1631	BRL	3/17/08	< 28.0		No	No	