

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Mercury (Total) Concentration (ng/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
									300			
									3,000			
EPA Site Specific Trigger Levels												
TotalHg-ST1-3/22/08	0813023-01	Southwest Area (sidewalk bridge level)	3/22/08	0.56	Mercury	EPA 324/1631	BRL	3/27/08	< 27.0	No	No	
TotalHg-ST2-3/22/08	0813023-02	Southeast Area (sidewalk bridge level)	3/22/08	0.55	Mercury	EPA 324/1631	BRL	3/27/08	< 27.0	No	No	
TotalHg-ST4-3/22/08	0813023-03	Northwest Area (street-level)	3/22/08	0.57	Mercury	EPA 324/1631	BRL	3/27/08	< 26.0	No	No	
TotalHg-ST5-3/22/08	0813023-04	Firehouse #10 (roof level)	3/22/08	0.56	Mercury	EPA 324/1631	BRL	3/27/08	< 27.0	No	No	
TotalHg-ST10-3/22/08	0813023-05	North Side Sidewalk Bridge	3/22/08	0.57	Mercury	EPA 324/1631	BRL	3/27/08	< 26.0	No	No	
TotalHg-ST11-3/22/08	0813023-06	90 Trinity Place (roof level)	3/22/08	0.56	Mercury	EPA 324/1631	BRL	3/27/08	< 27.0	No	No	
TotalHg-ST12-3/22/08	0813023-07	110 Greenwich Street (roof level)	3/22/08	0.56	Mercury	EPA 324/1631	BRL	3/27/08	< 27.0	No	No	
TotalHg-ST13-3/22/08	0813023-08	Marriott Hotel, 38th Floor (roof level)	3/22/08	0.56	Mercury	EPA 324/1631	BRL	3/27/08	< 27.0	No	No	
TotalHg-ST14-3/22/08	0813023-09	West Face - South end at corner (scaffolding level)	3/22/08	0.54	Mercury	EPA 324/1631	BRL	3/27/08	< 28.0	No	No	
TotalHg-ST15-3/22/08	0813023-10	South Face - East end at corner (scaffolding level)	3/22/08	0.54	Mercury	EPA 324/1631	BRL	3/27/08	< 28.0	No	No	
TotalHg-ST16-3/22/08	0813023-11	East Face - North end at corner (scaffolding level)	3/22/08	0.58	Mercury	EPA 324/1631	BRL	3/27/08	< 26.0	No	No	
TotalHg-ST17-3/22/08	0813023-12	North Face - West end at corner (scaffolding level)	3/22/08	0.60	Mercury	EPA 324/1631	BRL	3/27/08	< 25.0	No	No	
TotalHg-ST1-3/23/08	0813024-01	Southwest Area (sidewalk bridge level)	3/23/08	0.57	Mercury	EPA 324/1631	BRL	3/27/08	< 26.0	No	No	
TotalHg-ST2-3/23/08	0813024-02	Southeast Area (sidewalk bridge level)	3/23/08	0.56	Mercury	EPA 324/1631	BRL	3/27/08	< 27.0	No	No	
TotalHg-ST4-3/23/08	0813024-03	Northwest Area (street-level)	3/23/08	0.58	Mercury	EPA 324/1631	BRL	3/27/08	< 26.0	No	No	
TotalHg-ST5-3/23/08	0813024-04	Firehouse #10 (roof level)	3/23/08	0.61	Mercury	EPA 324/1631	BRL	3/27/08	< 25.0	No	No	
TotalHg-ST10-3/23/08	0813024-05	North Side Sidewalk Bridge	3/23/08	0.56	Mercury	EPA 324/1631	BRL	3/27/08	< 27.0	No	No	
TotalHg-ST11-3/23/08	0813024-06	90 Trinity Place (roof level)	3/23/08	0.57	Mercury	EPA 324/1631	BRL	3/27/08	< 26.0	No	No	
TotalHg-ST12-3/23/08	0813024-07	110 Greenwich Street (roof level)	3/23/08	0.61	Mercury	EPA 324/1631	BRL	3/27/08	< 25.0	No	No	
TotalHg-ST13-3/23/08	0813024-08	Marriott Hotel, 38th Floor (roof level)	3/23/08	0.55	Mercury	EPA 324/1631	BRL	3/27/08	< 27.0	No	No	
TotalHg-ST14-3/23/08	0813024-09	West Face - South end at corner (scaffolding level)	3/23/08	0.61	Mercury	EPA 324/1631	BRL	3/27/08	< 25.0	No	No	
TotalHg-ST15-3/23/08	0813024-10	South Face - East end at corner (scaffolding level)	3/23/08	0.58	Mercury	EPA 324/1631	BRL	3/27/08	< 26.0	No	No	
TotalHg-ST16-3/23/08	0813024-11	East Face - North end at corner (scaffolding level)	3/23/08	0.59	Mercury	EPA 324/1631	BRL	3/27/08	< 25.0	No	No	
TotalHg-ST17-3/23/08	0813024-12	North Face - West end at corner (scaffolding level)	3/23/08	0.61	Mercury	EPA 324/1631	BRL	3/27/08	< 25.0	No	No	
TotalHg-ST1-3/24/08	0813025-01	Southwest Area (sidewalk bridge level)	3/24/08	0.56	Mercury	EPA 324/1631	BRL	3/27/08	< 27.0	No	No	
TotalHg-ST2-3/24/08	0813025-02	Southeast Area (sidewalk bridge level)	3/24/08	0.58	Mercury	EPA 324/1631	BRL	3/27/08	< 26.0	No	No	
TotalHg-ST4-3/24/08	0813025-03	Northwest Area (street-level)	3/24/08	0.58	Mercury	EPA 324/1631	BRL	3/27/08	< 26.0	No	No	
TotalHg-ST5-3/24/08	0813025-04	Firehouse #10 (roof level)	3/24/08	0.55	Mercury	EPA 324/1631	BRL	3/27/08	< 27.0	No	No	
TotalHg-ST10-3/24/08	0813025-05	North Side Sidewalk Bridge	3/24/08	0.58	Mercury	EPA 324/1631	BRL	3/27/08	< 26.0	No	No	
TotalHg-ST11-3/24/08	0813025-06	90 Trinity Place (roof level)	3/24/08	0.55	Mercury	EPA 324/1631	BRL	3/27/08	< 27.0	No	No	
TotalHg-ST12-3/24/08	0813025-07	110 Greenwich Street (roof level)	3/24/08	0.55	Mercury	EPA 324/1631	BRL	3/27/08	< 27.0	No	No	
TotalHg-ST13-3/24/08	0813025-08	Marriott Hotel, 38th Floor (roof level)	3/24/08	0.57	Mercury	EPA 324/1631	BRL	3/27/08	< 26.0	No	No	
TotalHg-ST14-3/24/08	0813025-09	West Face - South end at corner (scaffolding level)	3/24/08	0.59	Mercury	EPA 324/1631	BRL	3/27/08	< 25.0	No	No	
TotalHg-ST15-3/24/08	0813025-10	South Face - East end at corner (scaffolding level)	3/24/08	0.60	Mercury	EPA 324/1631	BRL	3/27/08	< 25.0	No	No	
TotalHg-ST16-3/24/08	0813025-11	East Face - North end at corner (scaffolding level)	3/24/08	0.61	Mercury	EPA 324/1631	BRL	3/27/08	< 25.0	No	No	
TotalHg-ST17-3/24/08	0813025-12	North Face - West end at corner (scaffolding level)	3/24/08	0.55	Mercury	EPA 324/1631	BRL	3/27/08	< 27.0	No	No	
TotalHg-ST1-3/25/08	0813028-01	Southwest Area (sidewalk bridge level)	3/25/08	0.55	Mercury	EPA 324/1631	BRL	3/27/08	< 27.0	No	No	
TotalHg-ST2-3/25/08	0813028-02	Southeast Area (sidewalk bridge level)	3/25/08	0.59	Mercury	EPA 324/1631	BRL	3/27/08	< 25.0	No	No	
TotalHg-ST4-3/25/08	0813028-03	Northwest Area (street-level)	3/25/08	0.56	Mercury	EPA 324/1631	BRL	3/27/08	< 27.0	No	No	
TotalHg-ST5-3/25/08	0813028-04	Firehouse #10 (roof level)	3/25/08	0.58	Mercury	EPA 324/1631	BRL	3/27/08	< 26.0	No	No	
TotalHg-ST10-3/25/08	0813028-05	North Side Sidewalk Bridge	3/25/08	0.58	Mercury	EPA 324/1631	BRL	3/27/08	< 26.0	No	No	
TotalHg-ST11-3/25/08	0813028-06	90 Trinity Place (roof level)	3/25/08	0.57	Mercury	EPA 324/1631	BRL	3/27/08	< 26.0	No	No	
TotalHg-ST12-3/25/08	0813028-07	110 Greenwich Street (roof level)	3/25/08	0.55	Mercury	EPA 324/1631	BRL	3/27/08	< 27.0	No	No	
TotalHg-ST13-3/25/08	0813028-08	Marriott Hotel, 38th Floor (roof level)	3/25/08	0.56	Mercury	EPA 324/1631	BRL	3/27/08	< 27.0	No	No	
TotalHg-ST14-3/25/08	0813028-09	West Face - South end at corner (scaffolding level)	3/25/08	0.56	Mercury	EPA 324/1631	BRL	3/27/08	< 27.0	No	No	
TotalHg-ST15-3/25/08	0813028-10	South Face - East end at corner (scaffolding level)	3/25/08	0.57	Mercury	EPA 324/1631	BRL	3/27/08	< 26.0	No	No	
TotalHg-ST16-3/25/08	0813028-11	East Face - North end at corner (scaffolding level)	3/25/08	0.56	Mercury	EPA 324/1631	BRL	3/27/08	< 27.0	No	No	
TotalHg-ST17-3/25/08	0813028-12	North Face - West end at corner (scaffolding level)	3/25/08	0.58	Mercury	EPA 324/1631	BRL	3/27/08	< 26.0	No	No	
TotalHg-ST1-3/26/08	0813036-01	Southwest Area (sidewalk bridge level)	3/26/08	0.55	Mercury	EPA 324/1631	BRL	3/28/08	< 27.0	No	No	
TotalHg-ST2-3/26/08	0813036-02	Southeast Area (sidewalk bridge level)	3/26/08	0.54	Mercury	EPA 324/1631	BRL	3/28/08	< 28.0	No	No	
TotalHg-ST4-3/26/08	0813036-03	Northwest Area (street-level)	3/26/08	0.55	Mercury	EPA 324/1631	BRL	3/28/08	< 27.0	No	No	
TotalHg-ST5-3/26/08	0813036-04	Firehouse #10 (roof level)	3/26/08	0.57	Mercury	EPA 324/1631	BRL	3/28/08	< 26.0	No	No	
TotalHg-ST10-3/26/08	0813036-05	North Side Sidewalk Bridge	3/26/08	0.54	Mercury	EPA 324/1631	BRL	3/28/08	< 28.0	No	No	
TotalHg-ST11-3/26/08	0813036-06	90 Trinity Place (roof level)	3/26/08	0.61	Mercury	EPA 324/1631	BRL	3/28/08	< 25.0	No	No	
TotalHg-ST12-3/26/08	0813036-07	110 Greenwich Street (roof level)	3/26/08	0.54	Mercury	EPA 324/1631	BRL	3/28/08	< 28.0	No	No	
TotalHg-ST13-3/26/08	0813036-08	Marriott Hotel, 38th Floor (roof level)	3/26/08	0.54	Mercury	EPA 324/1631	BRL	3/28/08	< 28.0	No	No	
TotalHg-ST14-3/26/08	0813036-09	West Face - South end at corner (scaffolding level)	3/26/08	0.54	Mercury	EPA 324/1631	BRL	3/28/08	< 28.0	No	No	
TotalHg-ST15-3/26/08	0813036-10	South Face - East end at corner (scaffolding level)	3/26/08	0.58	Mercury	EPA 324/1631	BRL	3/28/08	< 26.0	No	No	
TotalHg-ST16-3/26/08	0813036-11	East Face - North end at corner (scaffolding level)	3/26/08	0.52	Mercury	EPA 324/1631	BRL	3/28/08	< 29.0	No	No	
TotalHg-ST17-3/26/08	0813036-12	North Face - West end at corner (scaffolding level)	3/26/08	0.53	Mercury	EPA 324/1631	BRL	3/28/08	< 28.0	No	No	