

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Mercury (Total) Concentration (ng/m3)		Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
									300	3,000			
									Target Air Quality Levels EPA Site Specific Trigger Levels				
TotalHg-ST4-3/30/06	06BR0483-01	Northwest Area (street-level)	3/30/06	0.60	Mercury	EPA 324/1631	BRL	4/1/06	< 25.0		No	No	
TotalHg-ST5-3/30/06	06BR0483-02	Firehouse #10 (roof level)	3/30/06	0.57	Mercury	EPA 324/1631	BRL	4/1/06	< 26.0		No	No	
TotalHg-ST10-3/30/06	06BR0483-03	North Side Sidewalk Bridge	3/30/06	0.59	Mercury	EPA 324/1631	BRL	4/1/06	< 25.0		No	No	
TotalHg-ST11-3/30/06	06BR0483-04	90 Trinity Place (roof level)	3/30/06	0.57	Mercury	EPA 324/1631	BRL	4/1/06	< 26.0		No	No	
TotalHg-ST12-3/30/06	06BR0483-05	110 Greenwich Street (roof level)	3/30/06	0.55	Mercury	EPA 324/1631	BRL	4/1/06	< 27.0		No	No	
TotalHg-ST13-3/30/06	06BR0483-06	Marriott Hotel, 38th Floor (roof level)	3/30/06	0.58	Mercury	EPA 324/1631	BRL	4/1/06	< 26.0		No	No	
TotalHg-ST14-3/30/06	06BR0483-07	West Face - South end at corner (scaffolding level)	3/30/06	0.57	Mercury	EPA 324/1631	BRL	4/1/06	< 26.0		No	No	
TotalHg-ST15-3/30/06	06BR0483-08	South Face - East end at corner (scaffolding level)	3/30/06	0.57	Mercury	EPA 324/1631	BRL	4/1/06	< 26.0		No	No	
TotalHg-ST16-3/30/06	06BR0483-09	East Face - North end at corner (scaffolding level)	3/30/06	0.57	Mercury	EPA 324/1631	BRL	4/1/06	< 26.0		No	No	
TotalHg-ST17-3/30/06	06BR0483-10	North Face - West end at corner (scaffolding level)	3/30/06	0.57	Mercury	EPA 324/1631	BRL	4/1/06	< 26.0		No	No	
TotalHg-ST1-3/31/06	06BR0488-01	Southwest Area (sidewalk bridge level)	3/31/06	0.55	Mercury	EPA 324/1631	BRL	4/4/06	< 27.0		No	No	
TotalHg-ST2-3/31/06	06BR0488-02	Southeast Area (sidewalk bridge level)	3/31/06	0.56	Mercury	EPA 324/1631	BRL	4/4/06	< 27.0		No	No	
TotalHg-ST4-3/31/06	06BR0488-03	Northwest Area (street-level)	3/31/06	0.55	Mercury	EPA 324/1631	BRL	4/4/06	< 27.0		No	No	
TotalHg-ST5-3/31/06	06BR0488-04	Firehouse #10 (roof level)	3/31/06	0.58	Mercury	EPA 324/1631	BRL	4/4/06	< 26.0		No	No	
TotalHg-ST10-3/31/06	06BR0488-05	North Side Sidewalk Bridge	3/31/06	0.51	Mercury	EPA 324/1631	BRL	4/4/06	< 29.0		No	No	
TotalHg-ST11-3/31/06	06BR0488-06	90 Trinity Place (roof level)	3/31/06	0.59	Mercury	EPA 324/1631	BRL	4/4/06	< 25.0		No	No	
TotalHg-ST12-3/31/06	06BR0488-07	110 Greenwich Street (roof level)	3/31/06	0.59	Mercury	EPA 324/1631	BRL	4/4/06	< 25.0		No	No	
TotalHg-ST13-3/31/06	06BR0488-08	Marriott Hotel, 38th Floor (roof level)	3/31/06	0.54	Mercury	EPA 324/1631	BRL	4/4/06	< 28.0		No	No	
TotalHg-ST14-3/31/06	06BR0488-09	West Face - South end at corner (scaffolding level)	3/31/06	0.55	Mercury	EPA 324/1631	BRL	4/4/06	< 27.0		No	No	
TotalHg-ST15-3/31/06	06BR0488-10	South Face - East end at corner (scaffolding level)	3/31/06	0.55	Mercury	EPA 324/1631	BRL	4/4/06	< 27.0		No	No	
TotalHg-ST16-3/31/06	06BR0488-11	East Face - North end at corner (scaffolding level)	3/31/06	0.55	Mercury	EPA 324/1631	BRL	4/4/06	< 27.0		No	No	
TotalHg-ST17-3/31/06	06BR0488-12	North Face - West end at corner (scaffolding level)	3/31/06	0.55	Mercury	EPA 324/1631	BRL	4/4/06	< 27.0		No	No	
TotalHg-ST1-4/1/06	06BR0489-01	Southwest Area (sidewalk bridge level)	4/1/06	0.56	Mercury	EPA 324/1631	BRL	4/4/06	< 27.0		No	No	
TotalHg-ST2-4/1/06	06BR0489-02	Southeast Area (sidewalk bridge level)	4/1/06	0.56	Mercury	EPA 324/1631	BRL	4/4/06	< 27.0		No	No	
TotalHg-ST4-4/1/06	06BR0489-03	Northwest Area (street-level)	4/1/06	0.56	Mercury	EPA 324/1631	BRL	4/4/06	< 27.0		No	No	
TotalHg-ST5-4/1/06	06BR0489-04	Firehouse #10 (roof level)	4/1/06	0.56	Mercury	EPA 324/1631	BRL	4/4/06	< 27.0		No	No	
TotalHg-ST10-4/1/06	06BR0489-05	North Side Sidewalk Bridge	4/1/06	0.55	Mercury	EPA 324/1631	BRL	4/4/06	< 27.0		No	No	
TotalHg-ST11-4/1/06	06BR0489-06	90 Trinity Place (roof level)	4/1/06	0.55	Mercury	EPA 324/1631	BRL	4/4/06	< 27.0		No	No	
TotalHg-ST12-4/1/06	06BR0489-07	110 Greenwich Street (roof level)	4/1/06	0.55	Mercury	EPA 324/1631	BRL	4/4/06	< 27.0		No	No	
TotalHg-ST13-4/1/06	06BR0489-08	Marriott Hotel, 38th Floor (roof level)	4/1/06	0.56	Mercury	EPA 324/1631	BRL	4/4/06	< 27.0		No	No	
TotalHg-ST14-4/1/06	06BR0489-09	West Face - South end at corner (scaffolding level)	4/1/06	0.56	Mercury	EPA 324/1631	BRL	4/4/06	< 27.0		No	No	
TotalHg-ST15-4/1/06	06BR0489-10	South Face - East end at corner (scaffolding level)	4/1/06	0.55	Mercury	EPA 324/1631	BRL	4/4/06	< 27.0		No	No	
TotalHg-ST16-4/1/06	06BR0489-11	East Face - North end at corner (scaffolding level)	4/1/06	0.57	Mercury	EPA 324/1631	BRL	4/4/06	< 26.0		No	No	
TotalHg-ST17-4/1/06	06BR0489-12	North Face - West end at corner (scaffolding level)	4/1/06	0.56	Mercury	EPA 324/1631	BRL	4/4/06	< 27.0		No	No	
TotalHg-ST1-4/2/06	06BR0495-01	Southwest Area (sidewalk bridge level)	4/2/06	0.57	Mercury	EPA 324/1631	BRL	4/4/06	< 26.0		No	No	
TotalHg-ST2-4/2/06	06BR0495-02	Southeast Area (sidewalk bridge level)	4/2/06	0.56	Mercury	EPA 324/1631	BRL	4/4/06	< 27.0		No	No	
TotalHg-ST4-4/2/06	06BR0495-03	Northwest Area (street-level)	4/2/06	0.57	Mercury	EPA 324/1631	BRL	4/4/06	< 26.0		No	No	
TotalHg-ST5-4/2/06	06BR0495-04	Firehouse #10 (roof level)	4/2/06	0.56	Mercury	EPA 324/1631	BRL	4/4/06	< 27.0		No	No	
TotalHg-ST10-4/2/06	06BR0495-05	North Side Sidewalk Bridge	4/2/06	0.57	Mercury	EPA 324/1631	BRL	4/4/06	< 26.0		No	No	
TotalHg-ST11-4/2/06	06BR0495-06	90 Trinity Place (roof level)	4/2/06	0.55	Mercury	EPA 324/1631	BRL	4/4/06	< 27.0		No	No	
TotalHg-ST12-4/2/06	06BR0495-07	110 Greenwich Street (roof level)	4/2/06	0.55	Mercury	EPA 324/1631	BRL	4/4/06	< 27.0		No	No	
TotalHg-ST13-4/2/06	06BR0495-08	Marriott Hotel, 38th Floor (roof level)	4/2/06	0.58	Mercury	EPA 324/1631	BRL	4/4/06	< 26.0		No	No	
TotalHg-ST14-4/2/06	06BR0495-09	West Face - South end at corner (scaffolding level)	4/2/06	0.59	Mercury	EPA 324/1631	BRL	4/4/06	< 25.0		No	No	
TotalHg-ST15-4/2/06	06BR0495-10	South Face - East end at corner (scaffolding level)	4/2/06	0.59	Mercury	EPA 324/1631	BRL	4/4/06	< 25.0		No	No	
TotalHg-ST16-4/2/06	06BR0495-11	East Face - North end at corner (scaffolding level)	4/2/06	0.58	Mercury	EPA 324/1631	BRL	4/4/06	< 26.0		No	No	
TotalHg-ST17-4/2/06	06BR0495-12	North Face - West end at corner (scaffolding level)	4/2/06	0.58	Mercury	EPA 324/1631	BRL	4/4/06	< 26.0		No	No	

Notes:

- Mercury sample at Station 1 (Southwest Area [sidewalk bridge level]) was not available for analysis on March 30, 2006 on account of clogging of the low flow adapter.
- Mercury sample at Station 2 (Southeast Area [sidewalk bridge level]) was not available for analysis on March 30, 2006 on account of pump failure.