

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Mercury (Total) Concentration (ng/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
									300			
									3,000			
Target Air Quality Levels												
EPA Site Specific Trigger Levels												
TotalHg-ST1-4/7/06	06BR0516-01	Southwest Area (sidewalk bridge level)	4/7/06	0.58	Mercury	EPA 324/1631	BRL	4/11/06	< 26.0	No	No	
TotalHg-ST2-4/7/06	06BR0516-02	Southeast Area (sidewalk bridge level)	4/7/06	0.58	Mercury	EPA 324/1631	BRL	4/11/06	< 26.0	No	No	
TotalHg-ST4-4/7/06	06BR0516-03	Northwest Area (street-level)	4/7/06	0.57	Mercury	EPA 324/1631	BRL	4/11/06	< 26.0	No	No	
TotalHg-ST5-4/7/06	06BR0516-04	Firehouse #10 (roof level)	4/7/06	0.58	Mercury	EPA 324/1631	BRL	4/11/06	< 26.0	No	No	
TotalHg-ST10-4/7/06	06BR0516-05	North Side Sidewalk Bridge	4/7/06	0.57	Mercury	EPA 324/1631	BRL	4/11/06	< 26.0	No	No	
TotalHg-ST11-4/7/06	06BR0516-06	90 Trinity Place (roof level)	4/7/06	0.59	Mercury	EPA 324/1631	BRL	4/11/06	< 25.0	No	No	
TotalHg-ST12-4/7/06	06BR0516-07	110 Greenwich Street (roof level)	4/7/06	0.57	Mercury	EPA 324/1631	BRL	4/11/06	< 26.0	No	No	
TotalHg-ST13-4/7/06	06BR0516-08	Marriott Hotel, 38th Floor (roof level)	4/7/06	0.59	Mercury	EPA 324/1631	BRL	4/11/06	< 25.0	No	No	
TotalHg-ST14-4/7/06	06BR0516-09	West Face - South end at corner (scaffolding level)	4/7/06	0.54	Mercury	EPA 324/1631	BRL	4/11/06	< 28.0	No	No	
TotalHg-ST15-4/7/06	06BR0516-10	South Face - East end at corner (scaffolding level)	4/7/06	0.54	Mercury	EPA 324/1631	BRL	4/11/06	< 28.0	No	No	
TotalHg-ST16-4/7/06	06BR0516-11	East Face - North end at corner (scaffolding level)	4/7/06	0.54	Mercury	EPA 324/1631	BRL	4/11/06	< 28.0	No	No	
TotalHg-ST17-4/7/06	06BR0516-12	North Face - West end at corner (scaffolding level)	4/7/06	0.54	Mercury	EPA 324/1631	BRL	4/11/06	< 28.0	No	No	
TotalHg-ST2-4/8/06	06BR0517-01	Southeast Area (sidewalk bridge level)	4/8/06	0.58	Mercury	EPA 324/1631	BRL	4/11/06	< 26.0	No	No	
TotalHg-ST4-4/8/06	06BR0517-02	Northwest Area (street-level)	4/8/06	0.58	Mercury	EPA 324/1631	BRL	4/11/06	< 26.0	No	No	
TotalHg-ST5-4/8/06	06BR0517-03	Firehouse #10 (roof level)	4/8/06	0.58	Mercury	EPA 324/1631	BRL	4/11/06	< 26.0	No	No	
TotalHg-ST10-4/8/06	06BR0517-04	North Side Sidewalk Bridge	4/8/06	0.58	Mercury	EPA 324/1631	BRL	4/11/06	< 26.0	No	No	
TotalHg-ST11-4/8/06	06BR0517-05	90 Trinity Place (roof level)	4/8/06	0.57	Mercury	EPA 324/1631	BRL	4/11/06	< 26.0	No	No	
TotalHg-ST12-4/8/06	06BR0517-06	110 Greenwich Street (roof level)	4/8/06	0.58	Mercury	EPA 324/1631	BRL	4/11/06	< 26.0	No	No	
TotalHg-ST13-4/8/06	06BR0517-07	Marriott Hotel, 38th Floor (roof level)	4/8/06	0.57	Mercury	EPA 324/1631	BRL	4/11/06	< 26.0	No	No	
TotalHg-ST14-4/8/06	06BR0517-08	West Face - South end at corner (scaffolding level)	4/8/06	0.57	Mercury	EPA 324/1631	BRL	4/11/06	< 26.0	No	No	
TotalHg-ST15-4/8/06	06BR0517-09	South Face - East end at corner (scaffolding level)	4/8/06	0.57	Mercury	EPA 324/1631	BRL	4/11/06	< 26.0	No	No	
TotalHg-ST16-4/8/06	06BR0517-10	East Face - North end at corner (scaffolding level)	4/8/06	0.57	Mercury	EPA 324/1631	BRL	4/11/06	< 26.0	No	No	
TotalHg-ST17-4/8/06	06BR0517-11	North Face - West end at corner (scaffolding level)	4/8/06	0.57	Mercury	EPA 324/1631	BRL	4/11/06	< 26.0	No	No	
TotalHg-ST1-4/9/06	06BR0518-01	Southwest Area (sidewalk bridge level)	4/9/06	0.57	Mercury	EPA 324/1631	BRL	4/11/06	< 26.0	No	No	
TotalHg-ST2-4/9/06	06BR0518-02	Southeast Area (sidewalk bridge level)	4/9/06	0.57	Mercury	EPA 324/1631	BRL	4/11/06	< 26.0	No	No	
TotalHg-ST4-4/9/06	06BR0518-03	Northwest Area (street-level)	4/9/06	0.57	Mercury	EPA 324/1631	BRL	4/11/06	< 26.0	No	No	
TotalHg-ST5-4/9/06	06BR0518-04	Firehouse #10 (roof level)	4/9/06	0.57	Mercury	EPA 324/1631	BRL	4/11/06	< 26.0	No	No	
TotalHg-ST10-4/9/06	06BR0518-05	North Side Sidewalk Bridge	4/9/06	0.57	Mercury	EPA 324/1631	BRL	4/11/06	< 26.0	No	No	
TotalHg-ST11-4/9/06	06BR0518-06	90 Trinity Place (roof level)	4/9/06	0.56	Mercury	EPA 324/1631	BRL	4/11/06	< 27.0	No	No	
TotalHg-ST12-4/9/06	06BR0518-07	110 Greenwich Street (roof level)	4/9/06	0.55	Mercury	EPA 324/1631	BRL	4/11/06	< 27.0	No	No	
TotalHg-ST13-4/9/06	06BR0518-08	Marriott Hotel, 38th Floor (roof level)	4/9/06	0.55	Mercury	EPA 324/1631	BRL	4/11/06	< 27.0	No	No	
TotalHg-ST14-4/9/06	06BR0518-09	West Face - South end at corner (scaffolding level)	4/9/06	0.60	Mercury	EPA 324/1631	BRL	4/11/06	< 25.0	No	No	
TotalHg-ST15-4/9/06	06BR0518-10	South Face - East end at corner (scaffolding level)	4/9/06	0.60	Mercury	EPA 324/1631	BRL	4/11/06	< 25.0	No	No	
TotalHg-ST16-4/9/06	06BR0518-11	East Face - North end at corner (scaffolding level)	4/9/06	0.59	Mercury	EPA 324/1631	BRL	4/11/06	< 25.0	No	No	
TotalHg-ST17-4/9/06	06BR0518-12	North Face - West end at corner (scaffolding level)	4/9/06	0.59	Mercury	EPA 324/1631	BRL	4/11/06	< 25.0	No	No	

Note:

- Mercury sample at Station 1 (Southwest Area [sidewalk bridge level]) was not available for analysis on April 8, 2006 on account of pump failure.