

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m <sup>3</sup> )	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Mercury (Total) Concentration (ng/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
									300			
									3,000			
TotalHg-ST1-4/9/07	07BR0465-01	Southwest Area (sidewalk bridge level)	4/9/07	0.55	Mercury	EPA 324/1631	BRL	4/11/07	< 27.0	No	No	
TotalHg-ST2-4/9/07	07BR0465-02	Southeast Area (sidewalk bridge level)	4/9/07	0.54	Mercury	EPA 324/1631	BRL	4/11/07	< 28.0	No	No	
TotalHg-ST4-4/9/07	07BR0465-03	Northwest Area (street-level)	4/9/07	0.59	Mercury	EPA 324/1631	BRL	4/11/07	< 25.0	No	No	
TotalHg-ST5-4/9/07	07BR0465-04	Firehouse #10 (roof level)	4/9/07	0.59	Mercury	EPA 324/1631	BRL	4/11/07	< 25.0	No	No	
TotalHg-ST10-4/9/07	07BR0465-05	North Side Sidewalk Bridge	4/9/07	0.59	Mercury	EPA 324/1631	BRL	4/11/07	< 25.0	No	No	
TotalHg-ST11-4/9/07	07BR0465-06	90 Trinity Place (roof level)	4/9/07	0.52	Mercury	EPA 324/1631	BRL	4/11/07	< 29.0	No	No	
TotalHg-ST12-4/9/07	07BR0465-07	110 Greenwich Street (roof level)	4/9/07	0.56	Mercury	EPA 324/1631	BRL	4/11/07	< 27.0	No	No	
TotalHg-ST13-4/9/07	07BR0465-08	Marriott Hotel, 38th Floor (roof level)	4/9/07	0.56	Mercury	EPA 324/1631	BRL	4/11/07	< 27.0	No	No	
TotalHg-ST14-4/9/07	07BR0465-09	West Face - South end at corner (scaffolding level)	4/9/07	0.55	Mercury	EPA 324/1631	BRL	4/11/07	< 27.0	No	No	
TotalHg-ST15-4/9/07	07BR0465-10	South Face - East end at corner (scaffolding level)	4/9/07	0.58	Mercury	EPA 324/1631	BRL	4/11/07	< 26.0	No	No	
TotalHg-ST16-4/9/07	07BR0465-11	East Face - North end at corner (scaffolding level)	4/9/07	0.59	Mercury	EPA 324/1631	BRL	4/11/07	< 25.0	No	No	
TotalHg-ST17-4/9/07	07BR0465-12	North Face - West end at corner (scaffolding level)	4/9/07	0.55	Mercury	EPA 324/1631	BRL	4/11/07	< 27.0	No	No	
TotalHg-ST1-4/10/07	07BR0472-01	Southwest Area (sidewalk bridge level)	4/10/07	0.56	Mercury	EPA 324/1631	BRL	4/12/07	< 27.0	No	No	
TotalHg-ST2-4/10/07	07BR0472-02	Southeast Area (sidewalk bridge level)	4/10/07	0.57	Mercury	EPA 324/1631	BRL	4/12/07	< 26.0	No	No	
TotalHg-ST4-4/10/07	07BR0472-03	Northwest Area (street-level)	4/10/07	0.54	Mercury	EPA 324/1631	BRL	4/12/07	< 28.0	No	No	
TotalHg-ST5-4/10/07	07BR0472-04	Firehouse #10 (roof level)	4/10/07	0.59	Mercury	EPA 324/1631	BRL	4/12/07	< 25.0	No	No	
TotalHg-ST10-4/10/07	07BR0472-05	North Side Sidewalk Bridge	4/10/07	0.57	Mercury	EPA 324/1631	BRL	4/12/07	< 26.0	No	No	
TotalHg-ST11-4/10/07	07BR0472-06	90 Trinity Place (roof level)	4/10/07	0.59	Mercury	EPA 324/1631	BRL	4/12/07	< 25.0	No	No	
TotalHg-ST12-4/10/07	07BR0472-07	110 Greenwich Street (roof level)	4/10/07	0.57	Mercury	EPA 324/1631	BRL	4/12/07	< 26.0	No	No	
TotalHg-ST13-4/10/07	07BR0472-08	Marriott Hotel, 38th Floor (roof level)	4/10/07	0.59	Mercury	EPA 324/1631	BRL	4/12/07	< 25.0	No	No	
TotalHg-ST14-4/10/07	07BR0472-09	West Face - South end at corner (scaffolding level)	4/10/07	0.56	Mercury	EPA 324/1631	BRL	4/12/07	< 27.0	No	No	
TotalHg-ST15-4/10/07	07BR0472-10	South Face - East end at corner (scaffolding level)	4/10/07	0.54	Mercury	EPA 324/1631	BRL	4/12/07	< 28.0	No	No	
TotalHg-ST16-4/10/07	07BR0472-11	East Face - North end at corner (scaffolding level)	4/10/07	0.55	Mercury	EPA 324/1631	BRL	4/12/07	< 27.0	No	No	
TotalHg-ST17-4/10/07	07BR0472-12	North Face - West end at corner (scaffolding level)	4/10/07	0.55	Mercury	EPA 324/1631	BRL	4/12/07	< 27.0	No	No	