

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m <sup>3</sup> )	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Mercury (Total) Concentration (ng/m3)	Exceeds Target	Exceeds EPA	Comments
									<b>300</b>	Air Quality Levels	Site Specific Trigger Levels	
<b>Target Air Quality Levels</b>									<b>3,000</b>			
<b>EPA Site Specific Trigger Levels</b>												
TotalHg-ST1-4/14/06	06BR0544-01	Southwest Area (sidewalk bridge level)	4/14/06	0.58	Mercury	EPA 324/1631	BRL	4/18/06	< 26.0	No	No	
TotalHg-ST2-4/14/06	06BR0544-02	Southeast Area (sidewalk bridge level)	4/14/06	0.58	Mercury	EPA 324/1631	BRL	4/18/06	< 26.0	No	No	
TotalHg-ST4-4/14/06	06BR0544-03	Northwest Area (street-level)	4/14/06	0.58	Mercury	EPA 324/1631	BRL	4/18/06	< 26.0	No	No	
TotalHg-ST5-4/14/06	06BR0544-04	Firehouse #10 (roof level)	4/14/06	0.59	Mercury	EPA 324/1631	BRL	4/18/06	< 25.0	No	No	
TotalHg-ST10-4/14/06	06BR0544-05	North Side Sidewalk Bridge	4/14/06	0.57	Mercury	EPA 324/1631	BRL	4/18/06	< 26.0	No	No	
TotalHg-ST11-4/14/06	06BR0544-06	90 Trinity Place (roof level)	4/14/06	0.58	Mercury	EPA 324/1631	BRL	4/18/06	< 26.0	No	No	
TotalHg-ST12-4/14/06	06BR0544-07	110 Greenwich Street (roof level)	4/14/06	0.56	Mercury	EPA 324/1631	BRL	4/18/06	< 27.0	No	No	
TotalHg-ST13-4/14/06	06BR0544-08	Marriott Hotel, 38th Floor (roof level)	4/14/06	0.62	Mercury	EPA 324/1631	BRL	4/18/06	< 24.0	No	No	
TotalHg-ST14-4/14/06	06BR0544-09	West Face - South end at corner (scaffolding level)	4/14/06	0.54	Mercury	EPA 324/1631	BRL	4/18/06	< 28.0	No	No	
TotalHg-ST15-4/14/06	06BR0544-10	South Face - East end at corner (scaffolding level)	4/14/06	0.55	Mercury	EPA 324/1631	BRL	4/18/06	< 27.0	No	No	
TotalHg-ST16-4/14/06	06BR0544-11	East Face - North end at corner (scaffolding level)	4/14/06	0.55	Mercury	EPA 324/1631	BRL	4/18/06	< 27.0	No	No	
TotalHg-ST17-4/14/06	06BR0544-12	North Face - West end at corner (scaffolding level)	4/14/06	0.55	Mercury	EPA 324/1631	BRL	4/18/06	< 27.0	No	No	
TotalHg-ST1-4/15/06	06BR0546-01	Southwest Area (sidewalk bridge level)	4/15/06	0.57	Mercury	EPA 324/1631	BRL	4/18/06	< 26.0	No	No	
TotalHg-ST2-4/15/06	06BR0546-02	Southeast Area (sidewalk bridge level)	4/15/06	0.57	Mercury	EPA 324/1631	BRL	4/18/06	< 26.0	No	No	
TotalHg-ST4-4/15/06	06BR0546-03	Northwest Area (street-level)	4/15/06	0.57	Mercury	EPA 324/1631	BRL	4/18/06	< 26.0	No	No	
TotalHg-ST5-4/15/06	06BR0546-04	Firehouse #10 (roof level)	4/15/06	0.56	Mercury	EPA 324/1631	BRL	4/18/06	< 27.0	No	No	
TotalHg-ST10-4/15/06	06BR0546-05	North Side Sidewalk Bridge	4/15/06	0.57	Mercury	EPA 324/1631	BRL	4/18/06	< 26.0	No	No	
TotalHg-ST11-4/15/06	06BR0546-06	90 Trinity Place (roof level)	4/15/06	0.57	Mercury	EPA 324/1631	BRL	4/18/06	< 26.0	No	No	
TotalHg-ST12-4/15/06	06BR0546-07	110 Greenwich Street (roof level)	4/15/06	0.57	Mercury	EPA 324/1631	BRL	4/18/06	< 26.0	No	No	
TotalHg-ST13-4/15/06	06BR0546-08	Marriott Hotel, 38th Floor (roof level)	4/15/06	0.56	Mercury	EPA 324/1631	BRL	4/18/06	< 27.0	No	No	
TotalHg-ST14-4/15/06	06BR0546-09	West Face - South end at corner (scaffolding level)	4/15/06	0.59	Mercury	EPA 324/1631	BRL	4/18/06	< 25.0	No	No	
TotalHg-ST15-4/15/06	06BR0546-10	South Face - East end at corner (scaffolding level)	4/15/06	0.59	Mercury	EPA 324/1631	BRL	4/18/06	< 25.0	No	No	
TotalHg-ST16-4/15/06	06BR0546-11	East Face - North end at corner (scaffolding level)	4/15/06	0.60	Mercury	EPA 324/1631	BRL	4/18/06	< 25.0	No	No	
TotalHg-ST17-4/15/06	06BR0546-12	North Face - West end at corner (scaffolding level)	4/15/06	0.59	Mercury	EPA 324/1631	BRL	4/18/06	< 25.0	No	No	
TotalHg-ST1-4/16/06	06BR0547-01	Southwest Area (sidewalk bridge level)	4/16/06	0.58	Mercury	EPA 324/1631	BRL	4/18/06	< 26.0	No	No	
TotalHg-ST2-4/16/06	06BR0547-02	Southeast Area (sidewalk bridge level)	4/16/06	0.58	Mercury	EPA 324/1631	BRL	4/18/06	< 26.0	No	No	
TotalHg-ST4-4/16/06	06BR0547-03	Northwest Area (street-level)	4/16/06	0.59	Mercury	EPA 324/1631	BRL	4/18/06	< 25.0	No	No	
TotalHg-ST5-4/16/06	06BR0547-04	Firehouse #10 (roof level)	4/16/06	0.58	Mercury	EPA 324/1631	BRL	4/18/06	< 26.0	No	No	
TotalHg-ST10-4/16/06	06BR0547-05	North Side Sidewalk Bridge	4/16/06	0.59	Mercury	EPA 324/1631	BRL	4/18/06	< 25.0	No	No	
TotalHg-ST11-4/16/06	06BR0547-06	90 Trinity Place (roof level)	4/16/06	0.58	Mercury	EPA 324/1631	BRL	4/18/06	< 26.0	No	No	
TotalHg-ST12-4/16/06	06BR0547-07	110 Greenwich Street (roof level)	4/16/06	0.58	Mercury	EPA 324/1631	BRL	4/18/06	< 26.0	No	No	
TotalHg-ST13-4/16/06	06BR0547-08	Marriott Hotel, 38th Floor (roof level)	4/16/06	0.53	Mercury	EPA 324/1631	BRL	4/18/06	< 28.0	No	No	
TotalHg-ST14-4/16/06	06BR0547-09	West Face - South end at corner (scaffolding level)	4/16/06	0.57	Mercury	EPA 324/1631	BRL	4/18/06	< 26.0	No	No	
TotalHg-ST15-4/16/06	06BR0547-10	South Face - East end at corner (scaffolding level)	4/16/06	0.58	Mercury	EPA 324/1631	BRL	4/18/06	< 26.0	No	No	
TotalHg-ST16-4/16/06	06BR0547-11	East Face - North end at corner (scaffolding level)	4/16/06	0.57	Mercury	EPA 324/1631	BRL	4/18/06	< 26.0	No	No	
TotalHg-ST17-4/16/06	06BR0547-12	North Face - West end at corner (scaffolding level)	4/16/06	0.58	Mercury	EPA 324/1631	BRL	4/18/06	< 26.0	No	No	