

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Mercury (Total) Concentration (ng/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
									300			
									3,000			
TotalHg-ST1-4/21/06	06BR0578-01	Southwest Area (sidewalk bridge level)	4/21/06	0.57	Mercury	EPA 324/1631	BRL	4/25/06	< 26.0	No	No	
TotalHg-ST2-4/21/06	06BR0578-02	Southeast Area (sidewalk bridge level)	4/21/06	0.57	Mercury	EPA 324/1631	BRL	4/25/06	< 26.0	No	No	
TotalHg-ST4-4/21/06	06BR0578-03	Northwest Area (street-level)	4/21/06	0.57	Mercury	EPA 324/1631	BRL	4/25/06	< 26.0	No	No	
TotalHg-ST10-4/21/06	06BR0578-04	North Side Sidewalk Bridge	4/21/06	0.57	Mercury	EPA 324/1631	BRL	4/25/06	< 26.0	No	No	
TotalHg-ST11-4/21/06	06BR0578-05	90 Trinity Place (roof level)	4/21/06	0.57	Mercury	EPA 324/1631	BRL	4/25/06	< 26.0	No	No	
TotalHg-ST12-4/21/06	06BR0578-06	110 Greenwich Street (roof level)	4/21/06	0.56	Mercury	EPA 324/1631	BRL	4/25/06	< 27.0	No	No	
TotalHg-ST13-4/21/06	06BR0578-07	Marriott Hotel, 38th Floor (roof level)	4/21/06	0.53	Mercury	EPA 324/1631	BRL	4/25/06	< 28.0	No	No	
TotalHg-ST14-4/21/06	06BR0578-08	West Face - South end at corner (scaffolding level)	4/21/06	0.56	Mercury	EPA 324/1631	BRL	4/25/06	< 27.0	No	No	
TotalHg-ST15-4/21/06	06BR0578-09	South Face - East end at corner (scaffolding level)	4/21/06	0.57	Mercury	EPA 324/1631	BRL	4/25/06	< 26.0	No	No	
TotalHg-ST16-4/21/06	06BR0578-10	East Face - North end at corner (scaffolding level)	4/21/06	0.57	Mercury	EPA 324/1631	BRL	4/25/06	< 26.0	No	No	
TotalHg-ST17-4/21/06	06BR0578-11	North Face - West end at corner (scaffolding level)	4/21/06	0.56	Mercury	EPA 324/1631	BRL	4/25/06	< 27.0	No	No	
TotalHg-ST1-4/22/06	06BR0579-01	Southwest Area (sidewalk bridge level)	4/22/06	0.58	Mercury	EPA 324/1631	BRL	4/25/06	< 26.0	No	No	
TotalHg-ST2-4/22/06	06BR0579-02	Southeast Area (sidewalk bridge level)	4/22/06	0.58	Mercury	EPA 324/1631	BRL	4/25/06	< 26.0	No	No	
TotalHg-ST4-4/22/06	06BR0579-03	Northwest Area (street-level)	4/22/06	0.58	Mercury	EPA 324/1631	BRL	4/25/06	< 26.0	No	No	
TotalHg-ST5-4/22/06	06BR0579-04	Firehouse #10 (roof level)	4/22/06	0.60	Mercury	EPA 324/1631	BRL	4/25/06	< 25.0	No	No	
TotalHg-ST10-4/22/06	06BR0579-05	North Side Sidewalk Bridge	4/22/06	0.58	Mercury	EPA 324/1631	BRL	4/25/06	< 26.0	No	No	
TotalHg-ST11-4/22/06	06BR0579-06	90 Trinity Place (roof level)	4/22/06	0.57	Mercury	EPA 324/1631	BRL	4/25/06	< 26.0	No	No	
TotalHg-ST12-4/22/06	06BR0579-07	110 Greenwich Street (roof level)	4/22/06	0.54	Mercury	EPA 324/1631	BRL	4/25/06	< 28.0	No	No	
TotalHg-ST13-4/22/06	06BR0579-08	Marriott Hotel, 38th Floor (roof level)	4/22/06	0.59	Mercury	EPA 324/1631	BRL	4/25/06	< 25.0	No	No	
TotalHg-ST14-4/22/06	06BR0579-09	West Face - South end at corner (scaffolding level)	4/22/06	0.56	Mercury	EPA 324/1631	BRL	4/25/06	< 27.0	No	No	
TotalHg-ST15-4/22/06	06BR0579-10	South Face - East end at corner (scaffolding level)	4/22/06	0.55	Mercury	EPA 324/1631	BRL	4/25/06	< 27.0	No	No	
TotalHg-ST17-4/22/06	06BR0579-11	North Face - West end at corner (scaffolding level)	4/22/06	0.56	Mercury	EPA 324/1631	BRL	4/25/06	< 27.0	No	No	
TotalHg-ST1-4/23/06	06BR0580-01	Southwest Area (sidewalk bridge level)	4/23/06	0.56	Mercury	EPA 324/1631	BRL	4/25/06	< 27.0	No	No	
TotalHg-ST2-4/23/06	06BR0580-02	Southeast Area (sidewalk bridge level)	4/23/06	0.57	Mercury	EPA 324/1631	BRL	4/25/06	< 26.0	No	No	
TotalHg-ST5-4/23/06	06BR0580-03	Firehouse #10 (roof level)	4/23/06	0.55	Mercury	EPA 324/1631	BRL	4/25/06	< 27.0	No	No	
TotalHg-ST10-4/23/06	06BR0580-04	North Side Sidewalk Bridge	4/23/06	0.56	Mercury	EPA 324/1631	BRL	4/25/06	< 27.0	No	No	
TotalHg-ST11-4/23/06	06BR0580-05	90 Trinity Place (roof level)	4/23/06	0.55	Mercury	EPA 324/1631	BRL	4/25/06	< 27.0	No	No	
TotalHg-ST12-4/23/06	06BR0580-06	110 Greenwich Street (roof level)	4/23/06	0.58	Mercury	EPA 324/1631	BRL	4/25/06	< 26.0	No	No	
TotalHg-ST13-4/23/06	06BR0580-07	Marriott Hotel, 38th Floor (roof level)	4/23/06	0.59	Mercury	EPA 324/1631	BRL	4/25/06	< 25.0	No	No	
TotalHg-ST14-4/23/06	06BR0580-08	West Face - South end at corner (scaffolding level)	4/23/06	0.60	Mercury	EPA 324/1631	BRL	4/25/06	< 25.0	No	No	
TotalHg-ST15-4/23/06	06BR0580-09	South Face - East end at corner (scaffolding level)	4/23/06	0.60	Mercury	EPA 324/1631	BRL	4/25/06	< 25.0	No	No	
TotalHg-ST16-4/23/06	06BR0580-10	East Face - North end at corner (scaffolding level)	4/23/06	0.59	Mercury	EPA 324/1631	BRL	4/25/06	< 25.0	No	No	
TotalHg-ST17-4/23/06	06BR0580-11	North Face - West end at corner (scaffolding level)	4/23/06	0.60	Mercury	EPA 324/1631	BRL	4/25/06	< 25.0	No	No	

Note:

1. Mercury samples at Station 5 (Firehouse #10 [roof level]) on April 21, 2006 and Station 16 (East Face - North end at corner [scaffolding level]) on April 22, 2006 were not available for analysis on account of a power failure.
2. Mercury sample at Station 4 (Northwest Area [street-level]) on April 23, 2006 was not available for analysis on account of pump failures.