

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m <sup>3</sup> )	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Mercury (Total) Concentration (ng/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
									300			
									3,000			
TotalHg-ST1-4/24/06	06BR0592-01	Southwest Area (sidewalk bridge level)	4/24/06	0.56	Mercury	EPA 324/1631	BRL	4/26/06	< 27.0	No	No	
TotalHg-ST2-4/24/06	06BR0592-02	Southeast Area (sidewalk bridge level)	4/24/06	0.56	Mercury	EPA 324/1631	BRL	4/26/06	< 27.0	No	No	
TotalHg-ST4-4/24/06	06BR0592-03	Northwest Area (street-level)	4/24/06	0.53	Mercury	EPA 324/1631	BRL	4/26/06	< 28.0	No	No	
TotalHg-ST5-4/24/06	06BR0592-04	Firehouse #10 (roof level)	4/24/06	0.58	Mercury	EPA 324/1631	BRL	4/26/06	< 26.0	No	No	
TotalHg-ST10-4/24/06	06BR0592-05	North Side Sidewalk Bridge	4/24/06	0.57	Mercury	EPA 324/1631	BRL	4/26/06	< 26.0	No	No	
TotalHg-ST11-4/24/06	06BR0592-06	90 Trinity Place (roof level)	4/24/06	0.57	Mercury	EPA 324/1631	BRL	4/26/06	< 26.0	No	No	
TotalHg-ST12-4/24/06	06BR0592-07	110 Greenwich Street (roof level)	4/24/06	0.58	Mercury	EPA 324/1631	BRL	4/26/06	< 26.0	No	No	
TotalHg-ST13-4/24/06	06BR0592-08	Marriott Hotel, 38th Floor (roof level)	4/24/06	0.55	Mercury	EPA 324/1631	BRL	4/26/06	< 27.0	No	No	
TotalHg-ST14-4/24/06	06BR0592-09	West Face - South end at corner (scaffolding level)	4/24/06	0.56	Mercury	EPA 324/1631	BRL	4/26/06	< 27.0	No	No	
TotalHg-ST15-4/24/06	06BR0592-10	South Face - East end at corner (scaffolding level)	4/24/06	0.56	Mercury	EPA 324/1631	BRL	4/26/06	< 27.0	No	No	
TotalHg-ST16-4/24/06	06BR0592-11	East Face - North end at corner (scaffolding level)	4/24/06	0.56	Mercury	EPA 324/1631	BRL	4/26/06	< 27.0	No	No	
TotalHg-ST17-4/24/06	06BR0592-12	North Face - West end at corner (scaffolding level)	4/24/06	0.56	Mercury	EPA 324/1631	BRL	4/26/06	< 27.0	No	No	
TotalHg-ST1-4/25/06	06BR0599-01	Southwest Area (sidewalk bridge level)	4/25/06	0.58	Mercury	EPA 324/1631	BRL	4/27/06	< 26.0	No	No	
TotalHg-ST2-4/25/06	06BR0599-02	Southeast Area (sidewalk bridge level)	4/25/06	0.58	Mercury	EPA 324/1631	BRL	4/27/06	< 26.0	No	No	
TotalHg-ST4-4/25/06	06BR0599-03	Northwest Area (street-level)	4/25/06	0.57	Mercury	EPA 324/1631	BRL	4/27/06	< 26.0	No	No	
TotalHg-ST5-4/25/06	06BR0599-04	Firehouse #10 (roof level)	4/25/06	0.57	Mercury	EPA 324/1631	BRL	4/27/06	< 26.0	No	No	
TotalHg-ST10-4/25/06	06BR0599-05	North Side Sidewalk Bridge	4/25/06	0.57	Mercury	EPA 324/1631	BRL	4/27/06	< 26.0	No	No	
TotalHg-ST11-4/25/06	06BR0599-06	90 Trinity Place (roof level)	4/25/06	0.57	Mercury	EPA 324/1631	BRL	4/27/06	< 26.0	No	No	
TotalHg-ST12-4/25/06	06BR0599-07	110 Greenwich Street (roof level)	4/25/06	0.57	Mercury	EPA 324/1631	BRL	4/27/06	< 26.0	No	No	
TotalHg-ST13-4/25/06	06BR0599-08	Marriott Hotel, 38th Floor (roof level)	4/25/06	0.57	Mercury	EPA 324/1631	BRL	4/27/06	< 26.0	No	No	
TotalHg-ST14-4/25/06	06BR0599-09	West Face - South end at corner (scaffolding level)	4/25/06	0.57	Mercury	EPA 324/1631	BRL	4/27/06	< 26.0	No	No	
TotalHg-ST15-4/25/06	06BR0599-10	South Face - East end at corner (scaffolding level)	4/25/06	0.58	Mercury	EPA 324/1631	BRL	4/27/06	< 26.0	No	No	
TotalHg-ST16-4/25/06	06BR0599-11	East Face - North end at corner (scaffolding level)	4/25/06	0.57	Mercury	EPA 324/1631	BRL	4/27/06	< 26.0	No	No	

Note:

- Mercury sample at Station 17 (North Face - West end at corner [scaffolding level]) on April 25, 2006 was not available for analysis on account of pump failure.