

| TRC Field Sample No.                    | Sample No. | Sampling Location                                   | Collection Start Date | Sample Volume (m <sup>3</sup> ) | Analyte | Analytical Method | Lab | Lab Sample Receipt Date | Mercury (Total) Concentration (ng/m3) | Exceeds Target                                   | Exceeds EPA   | Comments |
|---|------------|---|-----------------------|---------------------------------|---------|-------------------|-----|-------------------------|---------------------------------------|--|---|----------|
|   |            |   |                       |                                 |         |                   |     |                         | <b>300</b>                            | <b>Exceeds Target<br/>Air Quality<br/>Levels</b> | <b>Exceeds EPA<br/>Site Specific<br/>Trigger Levels</b> |          |
| <b>Target Air Quality Levels</b>        |            |   |                       |                                 |         |                   |     |                         | <b>3,000</b>                          |  |   |          |
| <b>EPA Site Specific Trigger Levels</b> |            |   |                       |                                 |         |                   |     |                         |                                       |  |   |          |
| TotalHg-ST1-4/30/08                     | 0818042-01 | Southwest Area (sidewalk bridge level)              | 4/30/08               | 0.59                            | Mercury | EPA 324/1631      | BRL | 5/2/08                  | < 25.0                                | No   | No  |          |
| TotalHg-ST2-4/30/08                     | 0818042-02 | Southeast Area (sidewalk bridge level)              | 4/30/08               | 0.58                            | Mercury | EPA 324/1631      | BRL | 5/2/08                  | < 26.0                                | No   | No  |          |
| TotalHg-ST4-4/30/08                     | 0818042-03 | Northwest Area (street-level)                       | 4/30/08               | 0.56                            | Mercury | EPA 324/1631      | BRL | 5/2/08                  | < 27.0                                | No   | No  |          |
| TotalHg-ST5-4/30/08                     | 0818042-04 | Firehouse #10 (roof level)                          | 4/30/08               | 0.58                            | Mercury | EPA 324/1631      | BRL | 5/2/08                  | < 26.0                                | No   | No  |          |
| TotalHg-ST10-4/30/08                    | 0818042-05 | North Side Sidewalk Bridge                          | 4/30/08               | 0.64                            | Mercury | EPA 324/1631      | BRL | 5/2/08                  | < 23.0                                | No   | No  |          |
| TotalHg-ST11-4/30/08                    | 0818042-06 | 90 Trinity Place (roof level)                       | 4/30/08               | 0.56                            | Mercury | EPA 324/1631      | BRL | 5/2/08                  | < 27.0                                | No   | No  |          |
| TotalHg-ST12-4/30/08                    | 0818042-07 | 110 Greenwich Street (roof level)                   | 4/30/08               | 0.59                            | Mercury | EPA 324/1631      | BRL | 5/2/08                  | < 25.0                                | No   | No  |          |
| TotalHg-ST13-4/30/08                    | 0818042-08 | Marriott Hotel, 38th Floor (roof level)             | 4/30/08               | 0.56                            | Mercury | EPA 324/1631      | BRL | 5/2/08                  | < 27.0                                | No   | No  |          |
| TotalHg-ST14-4/30/08                    | 0818042-09 | West Face - South end at corner (scaffolding level) | 4/30/08               | 0.58                            | Mercury | EPA 324/1631      | BRL | 5/2/08                  | < 26.0                                | No   | No  |          |
| TotalHg-ST15-4/30/08                    | 0818042-10 | South Face - East end at corner (scaffolding level) | 4/30/08               | 0.56                            | Mercury | EPA 324/1631      | BRL | 5/2/08                  | < 27.0                                | No   | No  |          |
| TotalHg-ST16-4/30/08                    | 0818042-11 | East Face - North end at corner (scaffolding level) | 4/30/08               | 0.55                            | Mercury | EPA 324/1631      | BRL | 5/2/08                  | < 27.0                                | No   | No  |          |
| TotalHg-ST17-4/30/08                    | 0818042-12 | North Face - West end at corner (scaffolding level) | 4/30/08               | 0.57                            | Mercury | EPA 324/1631      | BRL | 5/2/08                  | < 26.0                                | No   | No  |          |
| TotalHg-ST1-5/1/08                      | 0818048-01 | Southwest Area (sidewalk bridge level)              | 5/1/08                | 0.56                            | Mercury | EPA 324/1631      | BRL | 5/3/08                  | < 27.0                                | No   | No  |          |
| TotalHg-ST2-5/1/08                      | 0818048-02 | Southeast Area (sidewalk bridge level)              | 5/1/08                | 0.55                            | Mercury | EPA 324/1631      | BRL | 5/3/08                  | < 27.0                                | No   | No  |          |
| TotalHg-ST4-5/1/08                      | 0818048-03 | Northwest Area (street-level)                       | 5/1/08                | 0.54                            | Mercury | EPA 324/1631      | BRL | 5/3/08                  | < 28.0                                | No   | No  |          |
| TotalHg-ST5-5/1/08                      | 0818048-04 | Firehouse #10 (roof level)                          | 5/1/08                | 0.57                            | Mercury | EPA 324/1631      | BRL | 5/3/08                  | < 26.0                                | No   | No  |          |
| TotalHg-ST10-5/1/08                     | 0818048-05 | North Side Sidewalk Bridge                          | 5/1/08                | 0.61                            | Mercury | EPA 324/1631      | BRL | 5/3/08                  | < 25.0                                | No   | No  |          |
| TotalHg-ST11-5/1/08                     | 0818048-06 | 90 Trinity Place (roof level)                       | 5/1/08                | 0.55                            | Mercury | EPA 324/1631      | BRL | 5/3/08                  | < 27.0                                | No   | No  |          |
| TotalHg-ST12-5/1/08                     | 0818048-07 | 110 Greenwich Street (roof level)                   | 5/1/08                | 0.61                            | Mercury | EPA 324/1631      | BRL | 5/3/08                  | < 25.0                                | No   | No  |          |
| TotalHg-ST13-5/1/08                     | 0818048-08 | Marriott Hotel, 38th Floor (roof level)             | 5/1/08                | 0.60                            | Mercury | EPA 324/1631      | BRL | 5/3/08                  | < 25.0                                | No   | No  |          |
| TotalHg-ST14-5/1/08                     | 0818048-09 | West Face - South end at corner (scaffolding level) | 5/1/08                | 0.56                            | Mercury | EPA 324/1631      | BRL | 5/3/08                  | < 27.0                                | No   | No  |          |
| TotalHg-ST15-5/1/08                     | 0818048-10 | South Face - East end at corner (scaffolding level) | 5/1/08                | 0.54                            | Mercury | EPA 324/1631      | BRL | 5/3/08                  | < 28.0                                | No   | No  |          |
| TotalHg-ST16-5/1/08                     | 0818048-11 | East Face - North end at corner (scaffolding level) | 5/1/08                | 0.57                            | Mercury | EPA 324/1631      | BRL | 5/3/08                  | < 26.0                                | No   | No  |          |
| TotalHg-ST17-5/1/08                     | 0818048-12 | North Face - West end at corner (scaffolding level) | 5/1/08                | 0.60                            | Mercury | EPA 324/1631      | BRL | 5/3/08                  | < 25.0                                | No   | No  |          |
| TotalHg-ST1-5/02/08                     | 0819001-01 | Southwest Area (sidewalk bridge level)              | 5/2/08                | 0.59                            | Mercury | EPA 324/1631      | BRL | 5/5/08                  | < 25.0                                | No   | No  |          |
| TotalHg-ST2-5/02/08                     | 0819001-02 | Southeast Area (sidewalk bridge level)              | 5/2/08                | 0.55                            | Mercury | EPA 324/1631      | BRL | 5/5/08                  | < 27.0                                | No   | No  |          |
| TotalHg-ST4-5/02/08                     | 0819001-03 | Northwest Area (street-level)                       | 5/2/08                | 0.55                            | Mercury | EPA 324/1631      | BRL | 5/5/08                  | < 27.0                                | No   | No  |          |
| TotalHg-ST5-5/02/08                     | 0819001-04 | Firehouse #10 (roof level)                          | 5/2/08                | 0.59                            | Mercury | EPA 324/1631      | BRL | 5/5/08                  | < 25.0                                | No   | No  |          |
| TotalHg-ST10-5/02/08                    | 0819001-05 | North Side Sidewalk Bridge                          | 5/2/08                | 0.55                            | Mercury | EPA 324/1631      | BRL | 5/5/08                  | < 27.0                                | No   | No  |          |
| TotalHg-ST11-5/02/08                    | 0819001-06 | 90 Trinity Place (roof level)                       | 5/2/08                | 0.61                            | Mercury | EPA 324/1631      | BRL | 5/5/08                  | < 25.0                                | No   | No  |          |
| TotalHg-ST12-5/02/08                    | 0819001-07 | 110 Greenwich Street (roof level)                   | 5/2/08                | 0.55                            | Mercury | EPA 324/1631      | BRL | 5/5/08                  | < 27.0                                | No   | No  |          |
| TotalHg-ST13-5/02/08                    | 0819001-08 | Marriott Hotel, 38th Floor (roof level)             | 5/2/08                | 0.58                            | Mercury | EPA 324/1631      | BRL | 5/5/08                  | < 26.0                                | No   | No  |          |
| TotalHg-ST14-5/02/08                    | 0819001-09 | West Face - South end at corner (scaffolding level) | 5/2/08                | 0.54                            | Mercury | EPA 324/1631      | BRL | 5/5/08                  | < 28.0                                | No   | No  |          |
| TotalHg-ST15-5/02/08                    | 0819001-10 | South Face - East end at corner (scaffolding level) | 5/2/08                | 0.57                            | Mercury | EPA 324/1631      | BRL | 5/5/08                  | < 26.0                                | No   | No  |          |
| TotalHg-ST16-5/02/08                    | 0819001-11 | East Face - North end at corner (scaffolding level) | 5/2/08                | 0.57                            | Mercury | EPA 324/1631      | BRL | 5/5/08                  | < 26.0                                | No   | No  |          |
| TotalHg-ST17-5/02/08                    | 0819001-12 | North Face - West end at corner (scaffolding level) | 5/2/08                | 0.59                            | Mercury | EPA 324/1631      | BRL | 5/5/08                  | < 25.0                                | No   | No  |          |