

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Mercury (Total) Concentration (ng/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
									300			
Target Air Quality Levels												
EPA Site Specific Trigger Levels									3,000			
TotalHg-ST1-5/6/09	0919023-01	Southwest Area (sidewalk bridge level)	5/6/09	0.57	Mercury	EPA 324/1631	BRL	5/8/09	< 26.0	No	No	
TotalHg-ST2-5/6/09	0919023-02	Southeast Area (sidewalk bridge level)	5/6/09	0.59	Mercury	EPA 324/1631	BRL	5/8/09	< 25.0	No	No	
TotalHg-ST4-5/6/09	0919023-03	Northwest Area (street-level)	5/6/09	0.56	Mercury	EPA 324/1631	BRL	5/8/09	< 25.0	No	No	
TotalHg-ST5-5/6/09	0919023-04	Firehouse #10 (roof level)	5/6/09	0.60	Mercury	EPA 324/1631	BRL	5/8/09	< 25.0	No	No	
TotalHg-ST10-5/6/09	0919023-05	North Side Sidewalk Bridge	5/6/09	0.55	Mercury	EPA 324/1631	BRL	5/8/09	< 27.0	No	No	
TotalHg-ST11-5/6/09	0919023-06	90 Trinity Place (roof level)	5/6/09	0.55	Mercury	EPA 324/1631	BRL	5/8/09	< 27.0	No	No	
TotalHg-ST12-5/6/09	0919023-07	110 Greenwich Street (roof level)	5/6/09	0.56	Mercury	EPA 324/1631	BRL	5/8/09	< 27.0	No	No	
TotalHg-ST13-5/6/09	0919023-08	Marriott Hotel, 38th Floor (roof level)	5/6/09	0.60	Mercury	EPA 324/1631	BRL	5/8/09	< 26.0	No	No	
TotalHg-ST14-5/6/09	0919023-09	West Face - South end at corner (scaffolding level)	5/6/09	0.54	Mercury	EPA 324/1631	BRL	5/8/09	< 28.0	No	No	
TotalHg-ST15-5/6/09	0919023-10	South Face - East end at corner (scaffolding level)	5/6/09	0.52	Mercury	EPA 324/1631	BRL	5/8/09	< 29.0	No	No	
TotalHg-ST16-5/6/09	0919023-11	East Face - North end at corner (scaffolding level)	5/6/09	0.56	Mercury	EPA 324/1631	BRL	5/8/09	< 27.0	No	No	
TotalHg-ST17-5/6/09	0919023-12	North Face - West end at corner (scaffolding level)	5/6/09	0.55	Mercury	EPA 324/1631	BRL	5/8/09	< 27.0	No	No	
TotalHg-ST1-5/7/09	0919029-01	Southwest Area (sidewalk bridge level)	5/7/09	0.54	Mercury	EPA 324/1631	BRL	5/9/09	< 28.0	No	No	
TotalHg-ST2-5/7/09	0919029-02	Southeast Area (sidewalk bridge level)	5/7/09	0.57	Mercury	EPA 324/1631	BRL	5/9/09	< 26.0	No	No	
TotalHg-ST4-5/7/09	0919029-03	Northwest Area (street-level)	5/7/09	0.56	Mercury	EPA 324/1631	BRL	5/9/09	< 27.0	No	No	
TotalHg-ST5-5/7/09	0919029-04	Firehouse #10 (roof level)	5/7/09	0.61	Mercury	EPA 324/1631	BRL	5/9/09	< 25.0	No	No	
TotalHg-ST10-5/7/09	0919029-05	North Side Sidewalk Bridge	5/7/09	0.54	Mercury	EPA 324/1631	BRL	5/9/09	< 28.0	No	No	
TotalHg-ST11-5/7/09	0919029-06	90 Trinity Place (roof level)	5/7/09	0.60	Mercury	EPA 324/1631	BRL	5/9/09	< 25.0	No	No	
TotalHg-ST12-5/7/09	0919029-07	110 Greenwich Street (roof level)	5/7/09	0.61	Mercury	EPA 324/1631	BRL	5/9/09	< 25.0	No	No	
TotalHg-ST13-5/7/09	0919029-08	Marriott Hotel, 38th Floor (roof level)	5/7/09	0.56	Mercury	EPA 324/1631	BRL	5/9/09	< 27.0	No	No	
TotalHg-ST14-5/7/09	0919029-09	West Face - South end at corner (scaffolding level)	5/7/09	0.53	Mercury	EPA 324/1631	BRL	5/9/09	< 28.0	No	No	
TotalHg-ST15-5/7/09	0919029-10	South Face - East end at corner (scaffolding level)	5/7/09	0.57	Mercury	EPA 324/1631	BRL	5/9/09	< 26.0	No	No	
TotalHg-ST16-5/7/09	0919029-11	East Face - North end at corner (scaffolding level)	5/7/09	0.55	Mercury	EPA 324/1631	BRL	5/9/09	< 27.0	No	No	
TotalHg-ST17-5/7/09	0919029-12	North Face - West end at corner (scaffolding level)	5/7/09	0.60	Mercury	EPA 324/1631	BRL	5/9/09	< 25.0	No	No	
TotalHg-ST1-5/8/09	0920001-01	Southwest Area (sidewalk bridge level)	5/8/09	0.60	Mercury	EPA 324/1631	BRL	5/11/09	< 25.0	No	No	
TotalHg-ST2-5/8/09	0920001-02	Southeast Area (sidewalk bridge level)	5/8/09	0.61	Mercury	EPA 324/1631	BRL	5/11/09	< 25.0	No	No	
TotalHg-ST4-5/8/09	0920001-03	Northwest Area (street-level)	5/8/09	0.58	Mercury	EPA 324/1631	BRL	5/11/09	< 26.0	No	No	
TotalHg-ST5-5/8/09	0920001-04	Firehouse #10 (roof level)	5/8/09	0.55	Mercury	EPA 324/1631	BRL	5/11/09	< 27.0	No	No	
TotalHg-ST10-5/8/09	0920001-05	North Side Sidewalk Bridge	5/8/09	0.54	Mercury	EPA 324/1631	BRL	5/11/09	< 28.0	No	No	
TotalHg-ST11-5/8/09	0920001-06	90 Trinity Place (roof level)	5/8/09	0.59	Mercury	EPA 324/1631	BRL	5/11/09	< 25.0	No	No	
TotalHg-ST12-5/8/09	0920001-07	110 Greenwich Street (roof level)	5/8/09	0.56	Mercury	EPA 324/1631	BRL	5/11/09	< 27.0	No	No	
TotalHg-ST13-5/8/09	0920001-08	Marriott Hotel, 38th Floor (roof level)	5/8/09	0.56	Mercury	EPA 324/1631	BRL	5/11/09	< 27.0	No	No	
TotalHg-ST14-5/8/09	0920001-09	West Face - South end at corner (scaffolding level)	5/8/09	0.56	Mercury	EPA 324/1631	BRL	5/11/09	< 27.0	No	No	
TotalHg-ST15-5/8/09	0920001-10	South Face - East end at corner (scaffolding level)	5/8/09	0.53	Mercury	EPA 324/1631	BRL	5/11/09	< 28.0	No	No	
TotalHg-ST16-5/8/09	0920001-11	East Face - North end at corner (scaffolding level)	5/8/09	0.55	Mercury	EPA 324/1631	BRL	5/11/09	< 27.0	No	No	
TotalHg-ST17-5/8/09	0920001-12	North Face - West end at corner (scaffolding level)	5/8/09	0.55	Mercury	EPA 324/1631	BRL	5/11/09	< 27.0	No	No	