

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Mercury (Total) Concentration (ng/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
									300			
									3,000			
TotalHg-ST1-5/15/06	06BR0728-01	Southwest Area (sidewalk bridge level)	5/15/06	0.60	Mercury	EPA 324/1631	BRL	5/17/06	< 25.0	No	No	
TotalHg-ST2-5/15/06	06BR0728-02	Southeast Area (sidewalk bridge level)	5/15/06	0.57	Mercury	EPA 324/1631	BRL	5/17/06	< 26.0	No	No	
TotalHg-ST4-5/15/06	06BR0728-03	Northwest Area (street-level)	5/15/06	0.58	Mercury	EPA 324/1631	BRL	5/17/06	< 26.0	No	No	
TotalHg-ST5-5/15/06	06BR0728-04	Firehouse #10 (roof level)	5/15/06	0.59	Mercury	EPA 324/1631	BRL	5/17/06	< 25.0	No	No	
TotalHg-ST10-5/15/06	06BR0728-05	North Side Sidewalk Bridge	5/15/06	0.59	Mercury	EPA 324/1631	BRL	5/17/06	< 25.0	No	No	
TotalHg-ST11-5/15/06	06BR0728-06	90 Trinity Place (roof level)	5/15/06	0.57	Mercury	EPA 324/1631	BRL	5/17/06	< 26.0	No	No	
TotalHg-ST12-5/15/06	06BR0728-07	110 Greenwich Street (roof level)	5/15/06	0.58	Mercury	EPA 324/1631	BRL	5/17/06	< 26.0	No	No	
TotalHg-ST13-5/15/06	06BR0728-08	Marriott Hotel, 38th Floor (roof level)	5/15/06	0.58	Mercury	EPA 324/1631	BRL	5/17/06	< 26.0	No	No	
TotalHg-ST14-5/15/06	06BR0728-09	West Face - South end at corner (scaffolding level)	5/15/06	0.59	Mercury	EPA 324/1631	BRL	5/17/06	< 25.0	No	No	
TotalHg-ST15-5/15/06	06BR0728-10	South Face - East end at corner (scaffolding level)	5/15/06	0.60	Mercury	EPA 324/1631	BRL	5/17/06	< 25.0	No	No	
TotalHg-ST16-5/15/06	06BR0728-11	East Face - North end at corner (scaffolding level)	5/15/06	0.59	Mercury	EPA 324/1631	BRL	5/17/06	< 25.0	No	No	
TotalHg-ST17-5/15/06	06BR0728-12	North Face - West end at corner (scaffolding level)	5/15/06	0.59	Mercury	EPA 324/1631	BRL	5/17/06	< 25.0	No	No	
TotalHg-ST1-5/16/06	06BR0733-01	Southwest Area (sidewalk bridge level)	5/16/06	0.55	Mercury	EPA 324/1631	BRL	5/18/06	< 27.0	No	No	
TotalHg-ST2-5/16/06	06BR0733-02	Southeast Area (sidewalk bridge level)	5/16/06	0.57	Mercury	EPA 324/1631	BRL	5/18/06	< 26.0	No	No	
TotalHg-ST4-5/16/06	06BR0733-03	Northwest Area (street-level)	5/16/06	0.57	Mercury	EPA 324/1631	BRL	5/18/06	< 26.0	No	No	
TotalHg-ST5-5/16/06	06BR0733-04	Firehouse #10 (roof level)	5/16/06	0.57	Mercury	EPA 324/1631	BRL	5/18/06	< 26.0	No	No	
TotalHg-ST10-5/16/06	06BR0733-05	North Side Sidewalk Bridge	5/16/06	0.56	Mercury	EPA 324/1631	BRL	5/18/06	< 27.0	No	No	
TotalHg-ST100-5/16/06 FD	06BR0733-13	Station 10 Field Duplicate	5/16/06	0.56	Mercury	EPA 324/1631	BRL	5/18/06	< 27.0	No	No	
TotalHg-ST11-5/16/06	06BR0733-06	90 Trinity Place (roof level)	5/16/06	0.57	Mercury	EPA 324/1631	BRL	5/18/06	< 26.0	No	No	
TotalHg-ST12-5/16/06	06BR0733-07	110 Greenwich Street (roof level)	5/16/06	0.57	Mercury	EPA 324/1631	BRL	5/18/06	< 26.0	No	No	
TotalHg-ST13-5/16/06	06BR0733-08	Marriott Hotel, 38th Floor (roof level)	5/16/06	0.57	Mercury	EPA 324/1631	BRL	5/18/06	< 26.0	No	No	
TotalHg-ST14-5/16/06	06BR0733-09	West Face - South end at corner (scaffolding level)	5/16/06	0.56	Mercury	EPA 324/1631	BRL	5/18/06	< 27.0	No	No	
TotalHg-ST15-5/16/06	06BR0733-10	South Face - East end at corner (scaffolding level)	5/16/06	0.56	Mercury	EPA 324/1631	BRL	5/18/06	< 27.0	No	No	
TotalHg-ST16-5/16/06	06BR0733-11	East Face - North end at corner (scaffolding level)	5/16/06	0.56	Mercury	EPA 324/1631	BRL	5/18/06	< 27.0	No	No	
TotalHg-ST17-5/16/06	06BR0733-12	North Face - West end at corner (scaffolding level)	5/16/06	0.56	Mercury	EPA 324/1631	BRL	5/18/06	< 27.0	No	No	