

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Mercury (Total) Concentration (ng/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
									300			
									3,000			
TotalHg-ST1-5/30/06	06BR0823-01	Southwest Area (sidewalk bridge level)	5/30/06	0.58	Mercury	EPA 324/1631	BRL	6/1/06	< 26.0	No	No	
TotalHg-ST2-5/30/06	06BR0823-02	Southeast Area (sidewalk bridge level)	5/30/06	0.58	Mercury	EPA 324/1631	BRL	6/1/06	< 26.0	No	No	
TotalHg-ST4-5/30/06	06BR0823-03	Northwest Area (street-level)	5/30/06	0.58	Mercury	EPA 324/1631	BRL	6/1/06	< 29.0	No	No	
TotalHg-ST5-5/30/06	06BR0823-04	Firehouse #10 (roof level)	5/30/06	0.58	Mercury	EPA 324/1631	BRL	6/1/06	< 26.0	No	No	
TotalHg-ST10-5/30/06	06BR0823-05	North Side Sidewalk Bridge	5/30/06	0.58	Mercury	EPA 324/1631	BRL	6/1/06	< 28.0	No	No	
TotalHg-ST11-5/30/06	06BR0823-06	90 Trinity Place (roof level)	5/30/06	0.58	Mercury	EPA 324/1631	BRL	6/1/06	< 26.0	No	No	
TotalHg-ST12-5/30/06	06BR0823-07	110 Greenwich Street (roof level)	5/30/06	0.58	Mercury	EPA 324/1631	BRL	6/1/06	< 26.0	No	No	
TotalHg-ST13-5/30/06	06BR0823-08	Marriott Hotel, 38th Floor (roof level)	5/30/06	0.58	Mercury	EPA 324/1631	BRL	6/1/06	< 26.0	No	No	
TotalHg-ST14-5/30/06	06BR0823-09	West Face - South end at corner (scaffolding level)	5/30/06	0.58	Mercury	EPA 324/1631	BRL	6/1/06	< 26.0	No	No	
TotalHg-ST15-5/30/06	06BR0823-10	South Face - East end at corner (scaffolding level)	5/30/06	0.58	Mercury	EPA 324/1631	BRL	6/1/06	< 26.0	No	No	
TotalHg-ST17-5/30/06	06BR0823-11	North Face - West end at corner (scaffolding level)	5/30/06	0.58	Mercury	EPA 324/1631	BRL	6/1/06	< 26.0	No	No	
TotalHg-ST1-5/31/06	06BR0847-01	Southwest Area (sidewalk bridge level)	5/31/06	0.58	Mercury	EPA 324/1631	BRL	6/5/06	< 26.0	No	No	
TotalHg-ST2-5/31/06	06BR0847-02	Southeast Area (sidewalk bridge level)	5/31/06	0.57	Mercury	EPA 324/1631	BRL	6/5/06	< 26.0	No	No	
TotalHg-ST4-5/31/06	06BR0847-03	Northwest Area (street-level)	5/31/06	0.53	Mercury	EPA 324/1631	BRL	6/5/06	< 28.0	No	No	
TotalHg-ST5-5/31/06	06BR0847-04	Firehouse #10 (roof level)	5/31/06	0.58	Mercury	EPA 324/1631	BRL	6/5/06	< 26.0	No	No	
TotalHg-ST10-5/31/06	06BR0847-05	North Side Sidewalk Bridge	5/31/06	0.53	Mercury	EPA 324/1631	BRL	6/5/06	< 28.0	No	No	
TotalHg-ST11-5/31/06	06BR0847-06	90 Trinity Place (roof level)	5/31/06	0.57	Mercury	EPA 324/1631	BRL	6/5/06	< 26.0	No	No	
TotalHg-ST12-5/31/06	06BR0847-07	110 Greenwich Street (roof level)	5/31/06	0.57	Mercury	EPA 324/1631	BRL	6/5/06	< 26.0	No	No	
TotalHg-ST13-5/31/06	06BR0847-08	Marriott Hotel, 38th Floor (roof level)	5/31/06	0.58	Mercury	EPA 324/1631	BRL	6/5/06	< 26.0	No	No	
TotalHg-ST14-5/31/06	06BR0847-09	West Face - South end at corner (scaffolding level)	5/31/06	0.58	Mercury	EPA 324/1631	BRL	6/5/06	< 26.0	No	No	
TotalHg-ST15-5/31/06	06BR0847-10	South Face - East end at corner (scaffolding level)	5/31/06	0.57	Mercury	EPA 324/1631	BRL	6/5/06	< 26.0	No	No	
TotalHg-ST16-5/31/06	06BR0847-11	East Face - North end at corner (scaffolding level)	5/31/06	0.57	Mercury	EPA 324/1631	BRL	6/5/06	< 26.0	No	No	
TotalHg-ST17-5/31/06	06BR0847-12	North Face - West end at corner (scaffolding level)	5/31/06	0.57	Mercury	EPA 324/1631	BRL	6/5/06	< 26.0	No	No	
TotalHg-ST1-6/1/06	06BR0848-01	Southwest Area (sidewalk bridge level)	6/1/06	0.57	Mercury	EPA 324/1631	BRL	6/3/06	< 26.0	No	No	
TotalHg-ST2-6/1/06	06BR0848-02	Southeast Area (sidewalk bridge level)	6/1/06	0.57	Mercury	EPA 324/1631	BRL	6/3/06	< 26.0	No	No	
TotalHg-ST4-6/1/06	06BR0848-03	Northwest Area (street-level)	6/1/06	0.57	Mercury	EPA 324/1631	BRL	6/3/06	< 26.0	No	No	
TotalHg-ST5-6/1/06	06BR0848-04	Firehouse #10 (roof level)	6/1/06	0.57	Mercury	EPA 324/1631	BRL	6/3/06	< 26.0	No	No	
TotalHg-ST10-6/1/06	06BR0848-05	North Side Sidewalk Bridge	6/1/06	0.57	Mercury	EPA 324/1631	BRL	6/3/06	< 26.0	No	No	
TotalHg-ST11-6/1/06	06BR0848-06	90 Trinity Place (roof level)	6/1/06	0.57	Mercury	EPA 324/1631	BRL	6/3/06	< 26.0	No	No	
TotalHg-ST12-6/1/06	06BR0848-07	110 Greenwich Street (roof level)	6/1/06	0.57	Mercury	EPA 324/1631	BRL	6/3/06	< 26.0	No	No	
TotalHg-ST13-6/1/06	06BR0848-08	Marriott Hotel, 38th Floor (roof level)	6/1/06	0.57	Mercury	EPA 324/1631	BRL	6/3/06	< 26.0	No	No	
TotalHg-ST14-6/1/06	06BR0848-09	West Face - South end at corner (scaffolding level)	6/1/06	0.57	Mercury	EPA 324/1631	BRL	6/3/06	< 26.0	No	No	
TotalHg-ST15-6/1/06	06BR0848-10	South Face - East end at corner (scaffolding level)	6/1/06	0.56	Mercury	EPA 324/1631	BRL	6/3/06	< 27.0	No	No	
TotalHg-ST16-6/1/06	06BR0848-11	East Face - North end at corner (scaffolding level)	6/1/06	0.57	Mercury	EPA 324/1631	BRL	6/3/06	< 26.0	No	No	
TotalHg-ST17-6/1/06	06BR0848-12	North Face - West end at corner (scaffolding level)	6/1/06	0.57	Mercury	EPA 324/1631	BRL	6/3/06	< 26.0	No	No	

Note:

1. Mercury sample at Station 16 (East Face - North end at corner [scaffolding level]) on May 30, 2006 was not available for analysis on account of pump failure.