

| TRC Field Sample No. | Sample No. | Sampling Location | Collection Start Date | Sample Volume (m ³) | Analyte | Analytical Method | Lab | Lab Sample Receipt Date | Mercury (Total) Concentration (ng/m3) | Exceeds Target Air Quality Levels | Exceeds EPA Site Specific Trigger Levels | Comments |
|-------------------------|-------------|---|-----------------------|---------------------------------|---------|-------------------|-----|-------------------------|---------------------------------------|-----------------------------------|--|----------|
| | | | | | | | | | 300 | | | |
| | | | | | | | | | 3,000 | | | |
| TotalHg-ST1-6/27/06 | 06BR0996-01 | Southwest Area (sidewalk bridge level) | 6/27/06 | 0.57 | Mercury | EPA 324/1631 | BRL | 6/29/06 | < 26.0 | No | No | |
| TotalHg-ST2-6/27/06 | 06BR0996-02 | Southeast Area (sidewalk bridge level) | 6/27/06 | 0.58 | Mercury | EPA 324/1631 | BRL | 6/29/06 | < 26.0 | No | No | |
| TotalHg-ST4-6/27/06 | 06BR0996-03 | Northwest Area (street-level) | 6/27/06 | 0.57 | Mercury | EPA 324/1631 | BRL | 6/29/06 | < 26.0 | No | No | |
| TotalHg-ST5-6/27/06 | 06BR0996-04 | Firehouse #10 (roof level) | 6/27/06 | 0.57 | Mercury | EPA 324/1631 | BRL | 6/29/06 | < 26.0 | No | No | |
| TotalHg-ST10-6/27/06 | 06BR0996-05 | North Side Sidewalk Bridge | 6/27/06 | 0.56 | Mercury | EPA 324/1631 | BRL | 6/29/06 | < 27.0 | No | No | |
| TotalHg-ST100-6/27/06FD | 06BR0996-13 | Station 10 Field Duplicate | 6/27/06 | 0.57 | Mercury | EPA 324/1631 | BRL | 6/29/06 | < 26.0 | No | No | |
| TotalHg-ST11-6/27/06 | 06BR0996-06 | 90 Trinity Place (roof level) | 6/27/06 | 0.57 | Mercury | EPA 324/1631 | BRL | 6/29/06 | < 26.0 | No | No | |
| TotalHg-ST12-6/27/06 | 06BR0996-07 | 110 Greenwich Street (roof level) | 6/27/06 | 0.57 | Mercury | EPA 324/1631 | BRL | 6/29/06 | < 26.0 | No | No | |
| TotalHg-ST13-6/27/06 | 06BR0996-08 | Marriott Hotel, 38th Floor (roof level) | 6/27/06 | 0.57 | Mercury | EPA 324/1631 | BRL | 6/29/06 | < 26.0 | No | No | |
| TotalHg-ST14-6/27/06 | 06BR0996-09 | West Face - South end at corner (scaffolding level) | 6/27/06 | 0.57 | Mercury | EPA 324/1631 | BRL | 6/29/06 | < 26.0 | No | No | |
| TotalHg-ST15-6/27/06 | 06BR0996-10 | South Face - East end at corner (scaffolding level) | 6/27/06 | 0.57 | Mercury | EPA 324/1631 | BRL | 6/29/06 | < 26.0 | No | No | |
| TotalHg-ST16-6/27/06 | 06BR0996-11 | East Face - North end at corner (scaffolding level) | 6/27/06 | 0.57 | Mercury | EPA 324/1631 | BRL | 6/29/06 | < 26.0 | No | No | |
| TotalHg-ST17-6/27/06 | 06BR0996-12 | North Face - West end at corner (scaffolding level) | 6/27/06 | 0.56 | Mercury | EPA 324/1631 | BRL | 6/29/06 | < 27.0 | No | No | |
| TotalHg-ST1-6/28/06 | 06BR1004-01 | Southwest Area (sidewalk bridge level) | 6/28/06 | 0.58 | Mercury | EPA 324/1631 | BRL | 6/30/06 | < 26.0 | No | No | |
| TotalHg-ST2-6/28/06 | 06BR1004-02 | Southeast Area (sidewalk bridge level) | 6/28/06 | 0.58 | Mercury | EPA 324/1631 | BRL | 6/30/06 | < 26.0 | No | No | |
| TotalHg-ST4-6/28/06 | 06BR1004-03 | Northwest Area (street-level) | 6/28/06 | 0.58 | Mercury | EPA 324/1631 | BRL | 6/30/06 | < 26.0 | No | No | |
| TotalHg-ST5-6/28/06 | 06BR1004-04 | Firehouse #10 (roof level) | 6/28/06 | 0.58 | Mercury | EPA 324/1631 | BRL | 6/30/06 | < 26.0 | No | No | |
| TotalHg-ST10-6/28/06 | 06BR1004-05 | North Side Sidewalk Bridge | 6/28/06 | 0.58 | Mercury | EPA 324/1631 | BRL | 6/30/06 | < 26.0 | No | No | |
| TotalHg-ST11-6/28/06 | 06BR1004-06 | 90 Trinity Place (roof level) | 6/28/06 | 0.57 | Mercury | EPA 324/1631 | BRL | 6/30/06 | < 26.0 | No | No | |
| TotalHg-ST12-6/28/06 | 06BR1004-07 | 110 Greenwich Street (roof level) | 6/28/06 | 0.57 | Mercury | EPA 324/1631 | BRL | 6/30/06 | < 26.0 | No | No | |
| TotalHg-ST13-6/28/06 | 06BR1004-08 | Marriott Hotel, 38th Floor (roof level) | 6/28/06 | 0.56 | Mercury | EPA 324/1631 | BRL | 6/30/06 | < 27.0 | No | No | |
| TotalHg-ST14-6/28/06 | 06BR1004-09 | West Face - South end at corner (scaffolding level) | 6/28/06 | 0.58 | Mercury | EPA 324/1631 | BRL | 6/30/06 | < 26.0 | No | No | |
| TotalHg-ST15-6/28/06 | 06BR1004-10 | South Face - East end at corner (scaffolding level) | 6/28/06 | 0.57 | Mercury | EPA 324/1631 | BRL | 6/30/06 | < 26.0 | No | No | |
| TotalHg-ST16-6/28/06 | 06BR1004-11 | East Face - North end at corner (scaffolding level) | 6/28/06 | 0.56 | Mercury | EPA 324/1631 | BRL | 6/30/06 | < 27.0 | No | No | |
| TotalHg-ST17-6/28/06 | 06BR1004-12 | North Face - West end at corner (scaffolding level) | 6/28/06 | 0.57 | Mercury | EPA 324/1631 | BRL | 6/30/06 | < 26.0 | No | No | |