

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Mercury (Total) Concentration (ng/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
									300			
Target Air Quality Levels												
EPA Site Specific Trigger Levels									3,000			
TotalHg-ST1-8/13/08	0833046-01	Southwest Area (sidewalk bridge level)	8/13/08	0.55	Mercury	EPA 324/1631	BRL	8/15/08	< 27.0	No	No	
TotalHg-ST2-8/13/08	0833046-02	Southeast Area (sidewalk bridge level)	8/13/08	0.53	Mercury	EPA 324/1631	BRL	8/15/08	< 28.0	No	No	
TotalHg-ST4-8/13/08	0833046-03	Northwest Area (street-level)	8/13/08	0.54	Mercury	EPA 324/1631	BRL	8/15/08	< 28.0	No	No	
TotalHg-ST5-8/13/08	0833046-04	Firehouse #10 (roof level)	8/13/08	0.58	Mercury	EPA 324/1631	BRL	8/15/08	< 26.0	No	No	
TotalHg-ST10-8/13/08	0833046-05	North Side Sidewalk Bridge	8/13/08	0.55	Mercury	EPA 324/1631	BRL	8/15/08	< 27.0	No	No	
TotalHg-ST11-8/13/08	0833046-06	90 Trinity Place (roof level)	8/13/08	0.54	Mercury	EPA 324/1631	BRL	8/15/08	< 28.0	No	No	
TotalHg-ST12-8/13/08	0833046-07	110 Greenwich Street (roof level)	8/13/08	0.55	Mercury	EPA 324/1631	BRL	8/15/08	< 27.0	No	No	
TotalHg-ST13-8/13/08	0833046-08	Marriott Hotel, 38th Floor (roof level)	8/13/08	0.54	Mercury	EPA 324/1631	BRL	8/15/08	< 28.0	No	No	
TotalHg-ST14-8/13/08	0833046-09	West Face - South end at corner (scaffolding level)	8/13/08	0.55	Mercury	EPA 324/1631	BRL	8/15/08	< 27.0	No	No	
TotalHg-ST15-8/13/08	0833046-10	South Face - East end at corner (scaffolding level)	8/13/08	0.55	Mercury	EPA 324/1631	BRL	8/15/08	< 27.0	No	No	
TotalHg-ST16-8/13/08	0833046-11	East Face - North end at corner (scaffolding level)	8/13/08	0.54	Mercury	EPA 324/1631	BRL	8/15/08	< 28.0	No	No	
TotalHg-ST17-8/13/08	0833046-12	North Face - West end at corner (scaffolding level)	8/13/08	0.56	Mercury	EPA 324/1631	BRL	8/15/08	< 27.0	No	No	
TotalHg-ST1-8/14/08	0833060-01	Southwest Area (sidewalk bridge level)	8/14/08	0.61	Mercury	EPA 324/1631	BRL	8/16/08	< 25.0	No	No	
TotalHg-ST2-8/14/08	0833060-02	Southeast Area (sidewalk bridge level)	8/14/08	0.53	Mercury	EPA 324/1631	BRL	8/16/08	< 28.0	No	No	
TotalHg-ST4-8/14/08	0833060-03	Northwest Area (street-level)	8/14/08	0.54	Mercury	EPA 324/1631	BRL	8/16/08	< 28.0	No	No	
TotalHg-ST5-8/14/08	0833060-04	Firehouse #10 (roof level)	8/14/08	0.57	Mercury	EPA 324/1631	BRL	8/16/08	< 26.0	No	No	
TotalHg-ST10-8/14/08	0833060-05	North Side Sidewalk Bridge	8/14/08	0.60	Mercury	EPA 324/1631	BRL	8/16/08	< 25.0	No	No	
TotalHg-ST11-8/14/08	0833060-06	90 Trinity Place (roof level)	8/14/08	0.56	Mercury	EPA 324/1631	BRL	8/16/08	< 27.0	No	No	
TotalHg-ST12-8/14/08	0833060-07	110 Greenwich Street (roof level)	8/14/08	0.61	Mercury	EPA 324/1631	BRL	8/16/08	< 25.0	No	No	
TotalHg-ST13-8/14/08	0833060-08	Marriott Hotel, 38th Floor (roof level)	8/14/08	0.54	Mercury	EPA 324/1631	BRL	8/16/08	< 28.0	No	No	
TotalHg-ST14-8/14/08	0833060-09	West Face - South end at corner (scaffolding level)	8/14/08	0.60	Mercury	EPA 324/1631	BRL	8/16/08	< 25.0	No	No	
TotalHg-ST15-8/14/08	0833060-10	South Face - East end at corner (scaffolding level)	8/14/08	0.54	Mercury	EPA 324/1631	BRL	8/16/08	< 28.0	No	No	
TotalHg-ST16-8/14/08	0833060-11	East Face - North end at corner (scaffolding level)	8/14/08	0.58	Mercury	EPA 324/1631	BRL	8/16/08	< 26.0	No	No	
TotalHg-ST17-8/14/08	0833060-12	North Face - West end at corner (scaffolding level)	8/14/08	0.53	Mercury	EPA 324/1631	BRL	8/16/08	< 28.0	No	No	
TotalHg-ST1-8/15/08	0834001-01	Southwest Area (sidewalk bridge level)	8/15/08	0.57	Mercury	EPA 324/1631	BRL	8/18/08	< 26.0	No	No	
TotalHg-ST2-8/15/08	0834001-02	Southeast Area (sidewalk bridge level)	8/15/08	0.61	Mercury	EPA 324/1631	BRL	8/18/08	< 25.0	No	No	
TotalHg-ST4-8/15/08	0834001-03	Northwest Area (street-level)	8/15/08	0.58	Mercury	EPA 324/1631	BRL	8/18/08	< 26.0	No	No	
TotalHg-ST5-8/15/08	0834001-04	Firehouse #10 (roof level)	8/15/08	0.56	Mercury	EPA 324/1631	BRL	8/18/08	< 27.0	No	No	
TotalHg-ST10-8/15/08	0834001-05	North Side Sidewalk Bridge	8/15/08	0.54	Mercury	EPA 324/1631	BRL	8/18/08	< 28.0	No	No	
TotalHg-ST11-8/15/08	0834001-06	90 Trinity Place (roof level)	8/15/08	0.57	Mercury	EPA 324/1631	BRL	8/18/08	< 26.0	No	No	
TotalHg-ST12-8/15/08	0834001-07	110 Greenwich Street (roof level)	8/15/08	0.55	Mercury	EPA 324/1631	BRL	8/18/08	< 27.0	No	No	
TotalHg-ST13-8/15/08	0834001-08	Marriott Hotel, 38th Floor (roof level)	8/15/08	0.58	Mercury	EPA 324/1631	BRL	8/18/08	< 26.0	No	No	
TotalHg-ST14-8/15/08	0834001-09	West Face - South end at corner (scaffolding level)	8/15/08	0.58	Mercury	EPA 324/1631	BRL	8/18/08	< 26.0	No	No	
TotalHg-ST15-8/15/08	0834001-10	South Face - East end at corner (scaffolding level)	8/15/08	0.53	Mercury	EPA 324/1631	BRL	8/18/08	< 28.0	No	No	
TotalHg-ST16-8/15/08	0834001-11	East Face - North end at corner (scaffolding level)	8/15/08	0.53	Mercury	EPA 324/1631	BRL	8/18/08	< 28.0	No	No	
TotalHg-ST17-8/15/08	0834001-12	North Face - West end at corner (scaffolding level)	8/15/08	0.52	Mercury	EPA 324/1631	BRL	8/18/08	< 29.0	No	No	
TotalHg-ST1-8/16/08	0834005-01	Southwest Area (sidewalk bridge level)	8/16/08	0.56	Mercury	EPA 324/1631	BRL	8/19/08	< 27.0	No	No	
TotalHg-ST2-8/16/08	0834005-02	Southeast Area (sidewalk bridge level)	8/16/08	0.60	Mercury	EPA 324/1631	BRL	8/19/08	< 25.0	No	No	
TotalHg-ST4-8/16/08	0834005-03	Northwest Area (street-level)	8/16/08	0.58	Mercury	EPA 324/1631	BRL	8/19/08	< 26.0	No	No	
TotalHg-ST5-8/16/08	0834005-04	Firehouse #10 (roof level)	8/16/08	0.54	Mercury	EPA 324/1631	BRL	8/19/08	< 28.0	No	No	
TotalHg-ST10-8/16/08	0834005-05	North Side Sidewalk Bridge	8/16/08	0.59	Mercury	EPA 324/1631	BRL	8/19/08	< 25.0	No	No	
TotalHg-ST11-8/16/08	0834005-06	90 Trinity Place (roof level)	8/16/08	0.57	Mercury	EPA 324/1631	BRL	8/19/08	< 26.0	No	No	
TotalHg-ST12-8/16/08	0834005-07	110 Greenwich Street (roof level)	8/16/08	0.55	Mercury	EPA 324/1631	BRL	8/19/08	< 27.0	No	No	
TotalHg-ST13-8/16/08	0834005-08	Marriott Hotel, 38th Floor (roof level)	8/16/08	0.57	Mercury	EPA 324/1631	BRL	8/19/08	< 26.0	No	No	
TotalHg-ST14-8/16/08	0834005-09	West Face - South end at corner (scaffolding level)	8/16/08	0.54	Mercury	EPA 324/1631	BRL	8/19/08	< 28.0	No	No	
TotalHg-ST15-8/16/08	0834005-10	South Face - East end at corner (scaffolding level)	8/16/08	0.60	Mercury	EPA 324/1631	BRL	8/19/08	< 25.0	No	No	
TotalHg-ST16-8/16/08	0834005-11	East Face - North end at corner (scaffolding level)	8/16/08	0.57	Mercury	EPA 324/1631	BRL	8/19/08	< 26.0	No	No	
TotalHg-ST17-8/16/08	0834005-12	North Face - West end at corner (scaffolding level)	8/16/08	0.56	Mercury	EPA 324/1631	BRL	8/19/08	< 27.0	No	No	
TotalHg-ST1-8/17/08	0834008-01	Southwest Area (sidewalk bridge level)	8/17/08	0.56	Mercury	EPA 324/1631	BRL	8/19/08	< 27.0	No	No	
TotalHg-ST2-8/17/08	0834008-02	Southeast Area (sidewalk bridge level)	8/17/08	0.58	Mercury	EPA 324/1631	BRL	8/19/08	< 26.0	No	No	
TotalHg-ST4-8/17/08	0834008-03	Northwest Area (street-level)	8/17/08	0.55	Mercury	EPA 324/1631	BRL	8/19/08	< 27.0	No	No	
TotalHg-ST5-8/17/08	0834008-04	Firehouse #10 (roof level)	8/17/08	0.59	Mercury	EPA 324/1631	BRL	8/19/08	< 25.0	No	No	
TotalHg-ST10-8/17/08	0834008-05	North Side Sidewalk Bridge	8/17/08	0.56	Mercury	EPA 324/1631	BRL	8/19/08	< 27.0	No	No	
TotalHg-ST11-8/17/08	0834008-06	90 Trinity Place (roof level)	8/17/08	0.56	Mercury	EPA 324/1631	BRL	8/19/08	< 27.0	No	No	
TotalHg-ST12-8/17/08	0834008-07	110 Greenwich Street (roof level)	8/17/08	0.59	Mercury	EPA 324/1631	BRL	8/19/08	< 25.0	No	No	
TotalHg-ST13-8/17/08	0834008-08	Marriott Hotel, 38th Floor (roof level)	8/17/08	0.57	Mercury	EPA 324/1631	BRL	8/19/08	< 26.0	No	No	
TotalHg-ST14-8/17/08	0834008-09	West Face - South end at corner (scaffolding level)	8/17/08	0.53	Mercury	EPA 324/1631	BRL	8/19/08	< 28.0	No	No	
TotalHg-ST15-8/17/08	0834008-10	South Face - East end at corner (scaffolding level)	8/17/08	0.55	Mercury	EPA 324/1631	BRL	8/19/08	< 27.0	No	No	
TotalHg-ST16-8/17/08	0834008-11	East Face - North end at corner (scaffolding level)	8/17/08	0.56	Mercury	EPA 324/1631	BRL	8/19/08	< 27.0	No	No	
TotalHg-ST17-8/17/08	0834008-12	North Face - West end at corner (scaffolding level)	8/17/08	0.58	Mercury	EPA 324/1631	BRL	8/19/08	< 26.0	No	No	