

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Mercury (Total) Concentration (ng/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
									300			
									3,000			
TotalHg-ST1-8/31/07	0736005-01	Southwest Area (sidewalk bridge level)	8/31/07	0.55	Mercury	EPA 324/1631	BRL	9/5/07	< 27.0	No	No	
TotalHg-ST2-8/31/07	0736005-02	Southeast Area (sidewalk bridge level)	8/31/07	0.55	Mercury	EPA 324/1631	BRL	9/5/07	< 27.0	No	No	
TotalHg-ST4-8/31/07	0736005-03	Northwest Area (street-level)	8/31/07	0.56	Mercury	EPA 324/1631	BRL	9/5/07	< 27.0	No	No	
TotalHg-ST5-8/31/07	0736005-04	Firehouse #10 (roof level)	8/31/07	0.55	Mercury	EPA 324/1631	BRL	9/5/07	< 27.0	No	No	
TotalHg-ST10-8/31/07	0736005-05	North Side Sidewalk Bridge	8/31/07	0.58	Mercury	EPA 324/1631	BRL	9/5/07	< 26.0	No	No	
TotalHg-ST11-8/31/07	0736005-06	90 Trinity Place (roof level)	8/31/07	0.56	Mercury	EPA 324/1631	BRL	9/5/07	< 27.0	No	No	
TotalHg-ST12-8/31/07	0736005-07	110 Greenwich Street (roof level)	8/31/07	0.55	Mercury	EPA 324/1631	BRL	9/5/07	< 27.0	No	No	
TotalHg-ST13-8/31/07	0736005-08	Marriott Hotel, 38th Floor (roof level)	8/31/07	0.59	Mercury	EPA 324/1631	BRL	9/5/07	< 25.0	No	No	
TotalHg-ST14-8/31/07	0736005-09	West Face - South end at corner (scaffolding level)	8/31/07	0.51	Mercury	EPA 324/1631	BRL	9/5/07	< 29.0	No	No	
TotalHg-ST15-8/31/07	0736005-10	South Face - East end at corner (scaffolding level)	8/31/07	0.51	Mercury	EPA 324/1631	BRL	9/5/07	< 29.0	No	No	
TotalHg-ST16-8/31/07	0736005-11	East Face - North end at corner (scaffolding level)	8/31/07	0.52	Mercury	EPA 324/1631	BRL	9/5/07	< 29.0	No	No	
TotalHg-ST17-8/31/07	0736005-12	North Face - West end at corner (scaffolding level)	8/31/07	0.57	Mercury	EPA 324/1631	BRL	9/5/07	< 26.0	No	No	
TotalHg-ST1-9/1/07	0736006-01	Southwest Area (sidewalk bridge level)	9/1/07	0.54	Mercury	EPA 324/1631	BRL	9/5/07	< 28.0	No	No	
TotalHg-ST2-9/1/07	0736006-02	Southeast Area (sidewalk bridge level)	9/1/07	0.54	Mercury	EPA 324/1631	BRL	9/5/07	< 28.0	No	No	
TotalHg-ST4-9/1/07	0736006-03	Northwest Area (street-level)	9/1/07	0.56	Mercury	EPA 324/1631	BRL	9/5/07	< 27.0	No	No	
TotalHg-ST5-9/1/07	0736006-04	Firehouse #10 (roof level)	9/1/07	0.56	Mercury	EPA 324/1631	BRL	9/5/07	< 27.0	No	No	
TotalHg-ST10-9/1/07	0736006-05	North Side Sidewalk Bridge	9/1/07	0.55	Mercury	EPA 324/1631	BRL	9/5/07	< 27.0	No	No	
TotalHg-ST11-9/1/07	0736006-06	90 Trinity Place (roof level)	9/1/07	0.56	Mercury	EPA 324/1631	BRL	9/5/07	< 27.0	No	No	
TotalHg-ST12-9/1/07	0736006-07	110 Greenwich Street (roof level)	9/1/07	0.54	Mercury	EPA 324/1631	BRL	9/5/07	< 28.0	No	No	
TotalHg-ST13-9/1/07	0736006-08	Marriott Hotel, 38th Floor (roof level)	9/1/07	0.55	Mercury	EPA 324/1631	BRL	9/5/07	< 27.0	No	No	
TotalHg-ST14-9/1/07	0736006-09	West Face - South end at corner (scaffolding level)	9/1/07	0.54	Mercury	EPA 324/1631	BRL	9/5/07	< 28.0	No	No	
TotalHg-ST15-9/1/07	0736006-10	South Face - East end at corner (scaffolding level)	9/1/07	0.51	Mercury	EPA 324/1631	BRL	9/5/07	< 29.0	No	No	
TotalHg-ST16-9/1/07	0736006-11	East Face - North end at corner (scaffolding level)	9/1/07	0.52	Mercury	EPA 324/1631	BRL	9/5/07	< 29.0	No	No	
TotalHg-ST17-9/1/07	0736006-12	North Face - West end at corner (scaffolding level)	9/1/07	0.54	Mercury	EPA 324/1631	BRL	9/5/07	< 28.0	No	No	
TotalHg-ST1-9/2/07	0736007-01	Southwest Area (sidewalk bridge level)	9/2/07	0.57	Mercury	EPA 324/1631	BRL	9/5/07	< 26.0	No	No	
TotalHg-ST2-9/2/07	0736007-02	Southeast Area (sidewalk bridge level)	9/2/07	0.57	Mercury	EPA 324/1631	BRL	9/5/07	< 26.0	No	No	
TotalHg-ST4-9/2/07	0736007-03	Northwest Area (street-level)	9/2/07	0.58	Mercury	EPA 324/1631	BRL	9/5/07	< 26.0	No	No	
TotalHg-ST5-9/2/07	0736007-04	Firehouse #10 (roof level)	9/2/07	0.57	Mercury	EPA 324/1631	BRL	9/5/07	< 26.0	No	No	
TotalHg-ST10-9/2/07	0736007-05	North Side Sidewalk Bridge	9/2/07	0.57	Mercury	EPA 324/1631	BRL	9/5/07	< 26.0	No	No	
TotalHg-ST11-9/2/07	0736007-06	90 Trinity Place (roof level)	9/2/07	0.55	Mercury	EPA 324/1631	BRL	9/5/07	< 27.0	No	No	
TotalHg-ST12-9/2/07	0736007-07	110 Greenwich Street (roof level)	9/2/07	0.57	Mercury	EPA 324/1631	BRL	9/5/07	< 26.0	No	No	
TotalHg-ST13-9/2/07	0736007-08	Marriott Hotel, 38th Floor (roof level)	9/2/07	0.56	Mercury	EPA 324/1631	BRL	9/5/07	< 27.0	No	No	
TotalHg-ST14-9/2/07	0736007-09	West Face - South end at corner (scaffolding level)	9/2/07	0.58	Mercury	EPA 324/1631	BRL	9/5/07	< 26.0	No	No	
TotalHg-ST15-9/2/07	0736007-10	South Face - East end at corner (scaffolding level)	9/2/07	0.57	Mercury	EPA 324/1631	BRL	9/5/07	< 26.0	No	No	
TotalHg-ST16-9/2/07	0736007-11	East Face - North end at corner (scaffolding level)	9/2/07	0.62	Mercury	EPA 324/1631	BRL	9/5/07	< 24.0	No	No	
TotalHg-ST17-9/2/07	0736007-12	North Face - West end at corner (scaffolding level)	9/2/07	0.57	Mercury	EPA 324/1631	BRL	9/5/07	< 26.0	No	No	
TotalHg-ST1-9/3/07	0736008-01	Southwest Area (sidewalk bridge level)	9/3/07	0.55	Mercury	EPA 324/1631	BRL	9/5/07	< 27.0	No	No	
TotalHg-ST2-9/3/07	0736008-02	Southeast Area (sidewalk bridge level)	9/3/07	0.57	Mercury	EPA 324/1631	BRL	9/5/07	< 26.0	No	No	
TotalHg-ST4-9/3/07	0736008-03	Northwest Area (street-level)	9/3/07	0.58	Mercury	EPA 324/1631	BRL	9/5/07	< 26.0	No	No	
TotalHg-ST5-9/3/07	0736008-04	Firehouse #10 (roof level)	9/3/07	0.59	Mercury	EPA 324/1631	BRL	9/5/07	< 25.0	No	No	
TotalHg-ST10-9/3/07	0736008-05	North Side Sidewalk Bridge	9/3/07	0.58	Mercury	EPA 324/1631	BRL	9/5/07	< 26.0	No	No	
TotalHg-ST11-9/3/07	0736008-06	90 Trinity Place (roof level)	9/3/07	0.59	Mercury	EPA 324/1631	BRL	9/5/07	< 25.0	No	No	
TotalHg-ST12-9/3/07	0736008-07	110 Greenwich Street (roof level)	9/3/07	0.55	Mercury	EPA 324/1631	BRL	9/5/07	< 27.0	No	No	
TotalHg-ST13-9/3/07	0736008-08	Marriott Hotel, 38th Floor (roof level)	9/3/07	0.59	Mercury	EPA 324/1631	BRL	9/5/07	< 25.0	No	No	
TotalHg-ST14-9/3/07	0736008-09	West Face - South end at corner (scaffolding level)	9/3/07	0.60	Mercury	EPA 324/1631	BRL	9/5/07	< 25.0	No	No	
TotalHg-ST15-9/3/07	0736008-10	South Face - East end at corner (scaffolding level)	9/3/07	0.60	Mercury	EPA 324/1631	BRL	9/5/07	< 25.0	No	No	
TotalHg-ST16-9/3/07	0736008-11	East Face - North end at corner (scaffolding level)	9/3/07	0.63	Mercury	EPA 324/1631	BRL	9/5/07	< 24.0	No	No	
TotalHg-ST17-9/3/07	0736008-12	North Face - West end at corner (scaffolding level)	9/3/07	0.61	Mercury	EPA 324/1631	BRL	9/5/07	< 25.0	No	No	
TotalHg-ST1-9/4/07	0736016-01	Southwest Area (sidewalk bridge level)	9/4/07	0.55	Mercury	EPA 324/1631	BRL	9/6/07	< 27.0	No	No	
TotalHg-ST2-9/4/07	0736016-02	Southeast Area (sidewalk bridge level)	9/4/07	0.59	Mercury	EPA 324/1631	BRL	9/6/07	< 25.0	No	No	
TotalHg-ST4-9/4/07	0736016-03	Northwest Area (street-level)	9/4/07	0.55	Mercury	EPA 324/1631	BRL	9/6/07	< 27.0	No	No	
TotalHg-ST5-9/4/07	0736016-04	Firehouse #10 (roof level)	9/4/07	0.57	Mercury	EPA 324/1631	BRL	9/6/07	< 26.0	No	No	
TotalHg-ST10-9/4/07	0736016-05	North Side Sidewalk Bridge	9/4/07	0.56	Mercury	EPA 324/1631	BRL	9/6/07	< 27.0	No	No	
TotalHg-ST11-9/4/07	0736016-06	90 Trinity Place (roof level)	9/4/07	0.58	Mercury	EPA 324/1631	BRL	9/6/07	< 26.0	No	No	
TotalHg-ST12-9/4/07	0736016-07	110 Greenwich Street (roof level)	9/4/07	0.58	Mercury	EPA 324/1631	BRL	9/6/07	< 26.0	No	No	
TotalHg-ST13-9/4/07	0736016-08	Marriott Hotel, 38th Floor (roof level)	9/4/07	0.58	Mercury	EPA 324/1631	BRL	9/6/07	< 26.0	No	No	
TotalHg-ST14-9/4/07	0736016-09	West Face - South end at corner (scaffolding level)	9/4/07	0.57	Mercury	EPA 324/1631	BRL	9/6/07	< 26.0	No	No	
TotalHg-ST15-9/4/07	0736016-10	South Face - East end at corner (scaffolding level)	9/4/07	0.54	Mercury	EPA 324/1631	BRL	9/6/07	< 28.0	No	No	
TotalHg-ST16-9/4/07	0736016-11	East Face - North end at corner (scaffolding level)	9/4/07	0.57	Mercury	EPA 324/1631	BRL	9/6/07	< 26.0	No	No	
TotalHg-ST17-9/4/07	0736016-12	North Face - West end at corner (scaffolding level)	9/4/07	0.54	Mercury	EPA 324/1631	BRL	9/6/07	< 28.0	No	No	