

| TRC Field Sample No.                    | Sample No. | Sampling Location                       | Collection Start Date | Sample Volume (m <sup>3</sup> ) | Analyte | Analytical Method | Lab | Lab Sample Receipt Date | Mercury (Total) Concentration (ng/m3) | Exceeds Target Air Quality Levels | Exceeds EPA Site Specific Trigger Levels | Comments |
|-----------------------------------------|------------|-----------------------------------------|-----------------------|---------------------------------|---------|-------------------|-----|-------------------------|---------------------------------------|-----------------------------------|------------------------------------------|----------|
| <b>Target Air Quality Levels</b>        |            |                                         |                       |                                 |         |                   |     |                         | <b>300</b>                            |                                   |                                          |          |
| <b>EPA Site Specific Trigger Levels</b> |            |                                         |                       |                                 |         |                   |     |                         | <b>3,000</b>                          |                                   |                                          |          |
| TotalHg-ST1-9/14/09                     | 0938015-01 | Southwest Area (sidewalk bridge level)  | 9/14/09               | 0.58                            | Mercury | EPA 324/1631 Auto | BRL | 9/16/09                 | < 25.9                                | No                                | No                                       |          |
| TotalHg-ST4-9/14/09                     | 0938015-02 | Northwest Area (street-level)           | 9/14/09               | 0.56                            | Mercury | EPA 324/1631 Auto | BRL | 9/16/09                 | < 26.8                                | No                                | No                                       |          |
| TotalHg-ST5-9/14/09                     | 0938015-03 | Firehouse #10 (roof level)              | 9/14/09               | 0.56                            | Mercury | EPA 324/1631 Auto | BRL | 9/16/09                 | < 26.8                                | No                                | No                                       |          |
| TotalHg-ST10-9/14/09                    | 0938015-04 | North Side Sidewalk Bridge              | 9/14/09               | 0.52                            | Mercury | EPA 324/1631 Auto | BRL | 9/16/09                 | < 28.9                                | No                                | No                                       |          |
| TotalHg-ST11-9/14/09                    | 0938015-05 | 90 Trinity Place (roof level)           | 9/14/09               | 0.56                            | Mercury | EPA 324/1631 Auto | BRL | 9/16/09                 | < 26.8                                | No                                | No                                       |          |
| TotalHg-ST12-9/14/09                    | 0938015-06 | 110 Greenwich Street (roof level)       | 9/14/09               | 0.59                            | Mercury | EPA 324/1631 Auto | BRL | 9/16/09                 | < 25.4                                | No                                | No                                       |          |
| TotalHg-ST13-9/14/09                    | 0938015-07 | Marriott Hotel, 38th Floor (roof level) | 9/14/09               | 0.58                            | Mercury | EPA 324/1631 Auto | BRL | 9/16/09                 | < 25.9                                | No                                | No                                       |          |
| TotalHg-ST1-9/15/09                     | 0938022-01 | Southwest Area (sidewalk bridge level)  | 9/15/09               | 0.56                            | Mercury | EPA 324/1631 Auto | BRL | 9/17/09                 | < 26.8                                | No                                | No                                       |          |
| TotalHg-ST2-9/15/09                     | 0938022-02 | Southeast Area (sidewalk bridge level)  | 9/15/09               | 0.60                            | Mercury | EPA 324/1631 Auto | BRL | 9/17/09                 | < 25.0                                | No                                | No                                       |          |
| TotalHg-ST4-9/15/09                     | 0938022-03 | Northwest Area (street-level)           | 9/15/09               | 0.58                            | Mercury | EPA 324/1631 Auto | BRL | 9/17/09                 | < 25.9                                | No                                | No                                       |          |
| TotalHg-ST5-9/15/09                     | 0938022-04 | Firehouse #10 (roof level)              | 9/15/09               | 0.59                            | Mercury | EPA 324/1631 Auto | BRL | 9/17/09                 | < 25.4                                | No                                | No                                       |          |
| TotalHg-ST10-9/15/09                    | 0938022-05 | North Side Sidewalk Bridge              | 9/15/09               | 0.55                            | Mercury | EPA 324/1631 Auto | BRL | 9/17/09                 | < 27.3                                | No                                | No                                       |          |
| TotalHg-ST11-9/15/09                    | 0938022-06 | 90 Trinity Place (roof level)           | 9/15/09               | 0.55                            | Mercury | EPA 324/1631 Auto | BRL | 9/17/09                 | < 27.3                                | No                                | No                                       |          |
| TotalHg-ST12-9/15/09                    | 0938022-07 | 110 Greenwich Street (roof level)       | 9/15/09               | 0.58                            | Mercury | EPA 324/1631 Auto | BRL | 9/17/09                 | < 25.9                                | No                                | No                                       |          |
| TotalHg-ST13-9/15/09                    | 0938022-08 | Marriott Hotel, 38th Floor (roof level) | 9/15/09               | 0.56                            | Mercury | EPA 324/1631 Auto | BRL | 9/17/09                 | < 26.8                                | No                                | No                                       |          |
| TotalHg-ST1-9/16/09                     | 0938029-01 | Southwest Area (sidewalk bridge level)  | 9/16/09               | 0.55                            | Mercury | EPA 324/1631 Auto | BRL | 9/18/09                 | < 27.3                                | No                                | No                                       |          |
| TotalHg-ST2-9/16/09                     | 0938029-02 | Southeast Area (sidewalk bridge level)  | 9/16/09               | 0.56                            | Mercury | EPA 324/1631 Auto | BRL | 9/18/09                 | < 26.8                                | No                                | No                                       |          |
| TotalHg-ST4-9/16/09                     | 0938029-03 | Northwest Area (street-level)           | 9/16/09               | 0.57                            | Mercury | EPA 324/1631 Auto | BRL | 9/18/09                 | < 26.3                                | No                                | No                                       |          |
| TotalHg-ST5-9/16/09                     | 0938029-04 | Firehouse #10 (roof level)              | 9/16/09               | 0.52                            | Mercury | EPA 324/1631 Auto | BRL | 9/18/09                 | < 28.9                                | No                                | No                                       |          |
| TotalHg-ST10-9/16/09                    | 0938029-05 | North Side Sidewalk Bridge              | 9/16/09               | 0.54                            | Mercury | EPA 324/1631 Auto | BRL | 9/18/09                 | < 27.8                                | No                                | No                                       |          |
| TotalHg-ST11-9/16/09                    | 0938029-06 | 90 Trinity Place (roof level)           | 9/16/09               | 0.59                            | Mercury | EPA 324/1631 Auto | BRL | 9/18/09                 | < 25.4                                | No                                | No                                       |          |
| TotalHg-ST12-9/16/09                    | 0938029-07 | 110 Greenwich Street (roof level)       | 9/16/09               | 0.55                            | Mercury | EPA 324/1631 Auto | BRL | 9/18/09                 | < 27.3                                | No                                | No                                       |          |
| TotalHg-ST13-9/16/09                    | 0938029-08 | Marriott Hotel, 38th Floor (roof level) | 9/16/09               | 0.56                            | Mercury | EPA 324/1631 Auto | BRL | 9/18/09                 | < 26.8                                | No                                | No                                       |          |

Note:

1. The mercury sample from Station 2 (Southeast area [sidewalk bridge level]) on September 14, 2009 was not available for analysis on account of damage to the collection media.