

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m <sup>3</sup> )	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Mercury (Total) Concentration (ng/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
<b>Target Air Quality Levels</b>									<b>300</b>			
<b>EPA Site Specific Trigger Levels</b>									<b>3,000</b>			
TotalHg-ST1-9/23/05	05BR1421-1	Southwest Area (street-level)	9/23/2005	0.57	Mercury	EPA 324/1631	BRL	9/27/2005	< 26.3	No	No	
TotalHg-ST2-9/23/05	05BR1421-2	Southeast Area (street-level)	9/23/2005	0.57	Mercury	EPA 324/1631	BRL	9/27/2005	< 26.3	No	No	
TotalHg-ST4-9/23/05	05BR1421-3	Northwest Area (street-level)	9/23/2005	0.58	Mercury	EPA 324/1631	BRL	9/27/2005	< 25.9	No	No	
TotalHg-ST5-9/23/05	05BR1421-4	Firehouse #10 (roof level)	9/23/2005	0.58	Mercury	EPA 324/1631	BRL	9/27/2005	< 25.9	No	No	
TotalHg-ST6-9/23/05	05BR1421-5	Southwest Area (roof level)	9/23/2005	0.57	Mercury	EPA 324/1631	BRL	9/27/2005	< 26.3	No	No	
TotalHg-ST7-9/23/05	05BR1421-6	Southeast Area (roof level)	9/23/2005	0.57	Mercury	EPA 324/1631	BRL	9/27/2005	< 26.3	No	No	
TotalHg-ST8-9/23/05	05BR1421-7	Northeast Area (roof level)	9/23/2005	0.57	Mercury	EPA 324/1631	BRL	9/27/2005	< 26.3	No	No	
TotalHg-ST9-9/23/05	05BR1421-8	Northwest Area (roof level)	9/23/2005	0.57	Mercury	EPA 324/1631	BRL	9/27/2005	< 26.3	No	No	
TotalHg-ST10-9/23/05	05BR1421-9	North Side Sidewalk Bridge	9/23/2005	0.57	Mercury	EPA 324/1631	BRL	9/27/2005	< 26.3	No	No	
TotalHg-ST1-9/24/05	05BR1422-1	Southwest Area (street-level)	9/24/2005	0.58	Mercury	EPA 324/1631	BRL	9/27/2005	< 25.9	No	No	
TotalHg-ST2-9/24/05	05BR1422-2	Southeast Area (street-level)	9/24/2005	0.58	Mercury	EPA 324/1631	BRL	9/27/2005	< 25.9	No	No	
TotalHg-ST4-9/24/05	05BR1422-3	Northwest Area (street-level)	9/24/2005	0.56	Mercury	EPA 324/1631	BRL	9/27/2005	< 26.8	No	No	
TotalHg-ST5-9/24/05	05BR1422-4	Firehouse #10 (roof level)	9/24/2005	0.57	Mercury	EPA 324/1631	BRL	9/27/2005	< 26.3	No	No	
TotalHg-ST6-9/24/05	05BR1422-5	Southwest Area (roof level)	9/24/2005	0.57	Mercury	EPA 324/1631	BRL	9/27/2005	< 26.3	No	No	
TotalHg-ST7-9/24/05	05BR1422-6	Southeast Area (roof level)	9/24/2005	0.57	Mercury	EPA 324/1631	BRL	9/27/2005	< 26.3	No	No	
TotalHg-ST8-9/24/05	05BR1422-7	Northeast Area (roof level)	9/24/2005	0.56	Mercury	EPA 324/1631	BRL	9/27/2005	< 26.8	No	No	
TotalHg-ST9-9/24/05	05BR1422-8	Northwest Area (roof level)	9/24/2005	0.57	Mercury	EPA 324/1631	BRL	9/27/2005	< 26.3	No	No	
TotalHg-ST10-9/24/05	05BR1422-9	North Side Sidewalk Bridge	9/24/2005	0.58	Mercury	EPA 324/1631	BRL	9/27/2005	< 25.9	No	No	
TotalHg-ST1-9/25/05	05BR1423-1	Southwest Area (street-level)	9/25/2005	0.57	Mercury	EPA 324/1631	BRL	9/27/2005	< 26.3	No	No	
TotalHg-ST2-9/25/05	05BR1423-2	Southeast Area (street-level)	9/25/2005	0.57	Mercury	EPA 324/1631	BRL	9/27/2005	< 26.3	No	No	
TotalHg-ST4-9/25/05	05BR1423-3	Northwest Area (street-level)	9/25/2005	0.58	Mercury	EPA 324/1631	BRL	9/27/2005	< 25.9	No	No	
TotalHg-ST5-9/25/05	05BR1423-4	Firehouse #10 (roof level)	9/25/2005	0.57	Mercury	EPA 324/1631	BRL	9/27/2005	< 26.3	No	No	
TotalHg-ST6-9/25/05	05BR1423-5	Southwest Area (roof level)	9/25/2005	0.58	Mercury	EPA 324/1631	BRL	9/27/2005	< 25.9	No	No	
TotalHg-ST7-9/25/05	05BR1423-6	Southeast Area (roof level)	9/25/2005	0.58	Mercury	EPA 324/1631	BRL	9/27/2005	< 25.9	No	No	
TotalHg-ST8-9/25/05	05BR1423-7	Northeast Area (roof level)	9/25/2005	0.58	Mercury	EPA 324/1631	BRL	9/27/2005	< 25.9	No	No	
TotalHg-ST9-9/25/05	05BR1423-8	Northwest Area (roof level)	9/25/2005	0.58	Mercury	EPA 324/1631	BRL	9/27/2005	< 25.9	No	No	
TotalHg-ST10-9/25/05	05BR1423-9	North Side Sidewalk Bridge	9/25/2005	0.56	Mercury	EPA 324/1631	BRL	9/27/2005	< 26.8	No	No	