

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Mercury (Total) Concentration (ng/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
Target Air Quality Levels									300			
EPA Site Specific Trigger Levels									3,000			
TotalHg-ST1-9/24/09	0939031-01	Southwest Area (sidewalk bridge level)	9/24/09	0.57	Mercury	EPA 324/1631 Auto	BRL	9/26/09	< 26.3	No	No	
TotalHg-ST2-9/24/09	0939031-02	Southeast Area (sidewalk bridge level)	9/24/09	0.54	Mercury	EPA 324/1631 Auto	BRL	9/26/09	< 27.8	No	No	
TotalHg-ST4-9/24/09	0939031-03	Northwest Area (street-level)	9/24/09	0.57	Mercury	EPA 324/1631 Auto	BRL	9/26/09	< 26.3	No	No	
TotalHg-ST5-9/24/09	0939031-04	Firehouse #10 (roof level)	9/24/09	0.58	Mercury	EPA 324/1631 Auto	BRL	9/26/09	< 25.9	No	No	
TotalHg-ST10-9/24/09	0939031-05	North Side Sidewalk Bridge	9/24/09	0.53	Mercury	EPA 324/1631 Auto	BRL	9/26/09	< 28.3	No	No	
TotalHg-ST100-9/24/09	0939031-09	Station 10 Field Duplicate	9/24/09	0.59	Mercury	EPA 324/1631 Auto	BRL	9/26/09	< 25.4	No	No	
TotalHg-ST11-9/24/09	0939031-06	90 Trinity Place (roof level)	9/24/09	0.59	Mercury	EPA 324/1631 Auto	BRL	9/26/09	< 25.4	No	No	
TotalHg-ST12-9/24/09	0939031-07	110 Greenwich Street (roof level)	9/24/09	0.55	Mercury	EPA 324/1631 Auto	BRL	9/26/09	< 27.3	No	No	
TotalHg-ST13-9/24/09	0939031-08	Marriott Hotel, 38th Floor (roof level)	9/24/09	0.53	Mercury	EPA 324/1631 Auto	BRL	9/26/09	< 28.3	No	No	
TotalHg-ST1-9/25/09	0940001-01	Southwest Area (sidewalk bridge level)	9/25/09	0.54	Mercury	EPA 324/1631 Auto	BRL	9/28/09	< 27.8	No	No	
TotalHg-ST2-9/25/09	0940001-02	Southeast Area (sidewalk bridge level)	9/25/09	0.55	Mercury	EPA 324/1631 Auto	BRL	9/28/09	< 27.3	No	No	
TotalHg-ST4-9/25/09	0940001-03	Northwest Area (street-level)	9/25/09	0.56	Mercury	EPA 324/1631 Auto	BRL	9/28/09	< 26.8	No	No	
TotalHg-ST5-9/25/09	0940001-04	Firehouse #10 (roof level)	9/25/09	0.57	Mercury	EPA 324/1631 Auto	BRL	9/28/09	< 26.3	No	No	
TotalHg-ST10-9/25/09	0940001-05	North Side Sidewalk Bridge	9/25/09	0.56	Mercury	EPA 324/1631 Auto	BRL	9/28/09	< 26.8	No	No	
TotalHg-ST11-9/25/09	0940001-06	90 Trinity Place (roof level)	9/25/09	0.56	Mercury	EPA 324/1631 Auto	BRL	9/28/09	< 26.8	No	No	
TotalHg-ST12-9/25/09	0940001-07	110 Greenwich Street (roof level)	9/25/09	0.57	Mercury	EPA 324/1631 Auto	BRL	9/28/09	< 26.3	No	No	
TotalHg-ST13-9/25/09	0940001-08	Marriott Hotel, 38th Floor (roof level)	9/25/09	0.56	Mercury	EPA 324/1631 Auto	BRL	9/28/09	< 26.8	No	No	
TotalHg-ST1-9/26/09	0940005-01	Southwest Area (sidewalk bridge level)	9/26/09	0.56	Mercury	EPA 324/1631 Auto	BRL	9/29/09	< 26.8	No	No	
TotalHg-ST2-9/26/09	0940005-02	Southeast Area (sidewalk bridge level)	9/26/09	0.54	Mercury	EPA 324/1631 Auto	BRL	9/29/09	< 27.8	No	No	
TotalHg-ST4-9/26/09	0940005-03	Northwest Area (street-level)	9/26/09	0.54	Mercury	EPA 324/1631 Auto	BRL	9/29/09	< 27.8	No	No	
TotalHg-ST5-9/26/09	0940005-04	Firehouse #10 (roof level)	9/26/09	0.58	Mercury	EPA 324/1631 Auto	BRL	9/29/09	< 25.9	No	No	
TotalHg-ST10-9/26/09	0940005-05	North Side Sidewalk Bridge	9/26/09	0.53	Mercury	EPA 324/1631 Auto	BRL	9/29/09	< 28.3	No	No	
TotalHg-ST11-9/26/09	0940005-06	90 Trinity Place (roof level)	9/26/09	0.55	Mercury	EPA 324/1631 Auto	BRL	9/29/09	< 27.3	No	No	
TotalHg-ST12-9/26/09	0940005-07	110 Greenwich Street (roof level)	9/26/09	0.57	Mercury	EPA 324/1631 Auto	BRL	9/29/09	< 26.3	No	No	
TotalHg-ST13-9/26/09	0940005-08	Marriott Hotel, 38th Floor (roof level)	9/26/09	0.59	Mercury	EPA 324/1631 Auto	BRL	9/29/09	< 25.4	No	No	
TotalHg-ST1-9/27/09	0940006-01	Southwest Area (sidewalk bridge level)	9/27/09	0.54	Mercury	EPA 324/1631 Auto	BRL	9/29/09	< 27.8	No	No	
TotalHg-ST2-9/27/09	0940006-02	Southeast Area (sidewalk bridge level)	9/27/09	0.56	Mercury	EPA 324/1631 Auto	BRL	9/29/09	< 26.8	No	No	
TotalHg-ST4-9/27/09	0940006-03	Northwest Area (street-level)	9/27/09	0.57	Mercury	EPA 324/1631 Auto	BRL	9/29/09	< 26.3	No	No	
TotalHg-ST5-9/27/09	0940006-04	Firehouse #10 (roof level)	9/27/09	0.53	Mercury	EPA 324/1631 Auto	BRL	9/29/09	< 28.3	No	No	
TotalHg-ST10-9/27/09	0940006-05	North Side Sidewalk Bridge	9/27/09	0.54	Mercury	EPA 324/1631 Auto	BRL	9/29/09	< 27.8	No	No	
TotalHg-ST11-9/27/09	0940006-06	90 Trinity Place (roof level)	9/27/09	0.54	Mercury	EPA 324/1631 Auto	BRL	9/29/09	< 27.8	No	No	
TotalHg-ST12-9/27/09	0940006-07	110 Greenwich Street (roof level)	9/27/09	0.54	Mercury	EPA 324/1631 Auto	BRL	9/29/09	< 27.8	No	No	
TotalHg-ST13-9/27/09	0940006-08	Marriott Hotel, 38th Floor (roof level)	9/27/09	0.54	Mercury	EPA 324/1631 Auto	BRL	9/29/09	< 27.8	No	No	
TotalHg-ST1-9/28/09	0940021-01	Southwest Area (sidewalk bridge level)	9/28/09	0.60	Mercury	EPA 324/1631 Auto	BRL	9/30/09	< 25.0	No	No	
TotalHg-ST2-9/28/09	0940021-02	Southeast Area (sidewalk bridge level)	9/28/09	0.58	Mercury	EPA 324/1631 Auto	BRL	9/30/09	< 25.9	No	No	
TotalHg-ST4-9/28/09	0940021-03	Northwest Area (street-level)	9/28/09	0.56	Mercury	EPA 324/1631 Auto	BRL	9/30/09	< 26.8	No	No	
TotalHg-ST5-9/28/09	0940021-04	Firehouse #10 (roof level)	9/28/09	0.60	Mercury	EPA 324/1631 Auto	BRL	9/30/09	< 25.0	No	No	
TotalHg-ST10-9/28/09	0940021-05	North Side Sidewalk Bridge	9/28/09	0.56	Mercury	EPA 324/1631 Auto	BRL	9/30/09	< 26.8	No	No	
TotalHg-ST11-9/28/09	0940021-06	90 Trinity Place (roof level)	9/28/09	0.59	Mercury	EPA 324/1631 Auto	BRL	9/30/09	< 25.4	No	No	
TotalHg-ST12-9/28/09	0940021-07	110 Greenwich Street (roof level)	9/28/09	0.57	Mercury	EPA 324/1631 Auto	BRL	9/30/09	< 26.3	No	No	
TotalHg-ST13-9/28/09	0940021-08	Marriott Hotel, 38th Floor (roof level)	9/28/09	0.57	Mercury	EPA 324/1631 Auto	BRL	9/30/09	< 26.3	No	No	