

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m <sup>3</sup> )	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Mercury (Total) Concentration (ng/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
									<b>300</b>			
<b>Target Air Quality Levels</b>												
<b>EPA Site Specific Trigger Levels</b>									<b>3,000</b>			
TotalHg-ST1-9/26/08	0840002-01	Southwest Area (sidewalk bridge level)	9/26/08	0.61	Mercury	EPA 324/1631	BRL	9/29/08	< 25.0	No	No	
TotalHg-ST2-9/26/08	0840002-02	Southeast Area (sidewalk bridge level)	9/26/08	0.55	Mercury	EPA 324/1631	BRL	9/29/08	< 27.0	No	No	
TotalHg-ST4-9/26/08	0840002-03	Northwest Area (street-level)	9/26/08	0.60	Mercury	EPA 324/1631	BRL	9/29/08	< 25.0	No	No	
TotalHg-ST5-9/26/08	0840002-04	Firehouse #10 (roof level)	9/26/08	0.54	Mercury	EPA 324/1631	BRL	9/29/08	< 28.0	No	No	
TotalHg-ST10-9/26/08	0840002-05	North Side Sidewalk Bridge	9/26/08	0.59	Mercury	EPA 324/1631	BRL	9/29/08	< 25.0	No	No	
TotalHg-ST11-9/26/08	0840002-06	90 Trinity Place (roof level)	9/26/08	0.54	Mercury	EPA 324/1631	BRL	9/29/08	< 28.0	No	No	
TotalHg-ST12-9/26/08	0840002-07	110 Greenwich Street (roof level)	9/26/08	0.56	Mercury	EPA 324/1631	BRL	9/29/08	< 27.0	No	No	
TotalHg-ST13-9/26/08	0840002-08	Marriott Hotel, 38th Floor (roof level)	9/26/08	0.55	Mercury	EPA 324/1631	BRL	9/29/08	< 27.0	No	No	
TotalHg-ST14-9/26/08	0840002-09	West Face - South end at corner (scaffolding level)	9/26/08	0.56	Mercury	EPA 324/1631	BRL	9/29/08	< 27.0	No	No	
TotalHg-ST15-9/26/08	0840002-10	South Face - East end at corner (scaffolding level)	9/26/08	0.52	Mercury	EPA 324/1631	BRL	9/29/08	< 29.0	No	No	
TotalHg-ST16-9/26/08	0840002-11	East Face - North end at corner (scaffolding level)	9/26/08	0.54	Mercury	EPA 324/1631	BRL	9/29/08	< 28.0	No	No	
TotalHg-ST17-9/26/08	0840002-12	North Face - West end at corner (scaffolding level)	9/26/08	0.54	Mercury	EPA 324/1631	BRL	9/29/08	< 28.0	No	No	
TotalHg-ST1-9/27/08	0840012-01	Southwest Area (sidewalk bridge level)	9/27/08	0.59	Mercury	EPA 324/1631	BRL	9/30/08	< 25.0	No	No	
TotalHg-ST2-9/27/08	0840012-02	Southeast Area (sidewalk bridge level)	9/27/08	0.57	Mercury	EPA 324/1631	BRL	9/30/08	< 26.0	No	No	
TotalHg-ST4-9/27/08	0840012-03	Northwest Area (street-level)	9/27/08	0.57	Mercury	EPA 324/1631	BRL	9/30/08	< 26.0	No	No	
TotalHg-ST5-9/27/08	0840012-04	Firehouse #10 (roof level)	9/27/08	0.56	Mercury	EPA 324/1631	BRL	9/30/08	< 27.0	No	No	
TotalHg-ST10-9/27/08	0840012-05	North Side Sidewalk Bridge	9/27/08	0.59	Mercury	EPA 324/1631	BRL	9/30/08	< 25.0	No	No	
TotalHg-ST11-9/27/08	0840012-06	90 Trinity Place (roof level)	9/27/08	0.59	Mercury	EPA 324/1631	BRL	9/30/08	< 25.0	No	No	
TotalHg-ST12-9/27/08	0840012-07	110 Greenwich Street (roof level)	9/27/08	0.54	Mercury	EPA 324/1631	BRL	9/30/08	< 28.0	No	No	
TotalHg-ST13-9/27/08	0840012-08	Marriott Hotel, 38th Floor (roof level)	9/27/08	0.54	Mercury	EPA 324/1631	BRL	9/30/08	< 28.0	No	No	
TotalHg-ST14-9/27/08	0840012-09	West Face - South end at corner (scaffolding level)	9/27/08	0.53	Mercury	EPA 324/1631	BRL	9/30/08	< 28.0	No	No	
TotalHg-ST15-9/27/08	0840012-10	South Face - East end at corner (scaffolding level)	9/27/08	0.57	Mercury	EPA 324/1631	BRL	9/30/08	< 26.0	No	No	
TotalHg-ST16-9/27/08	0840012-11	East Face - North end at corner (scaffolding level)	9/27/08	0.54	Mercury	EPA 324/1631	BRL	9/30/08	< 28.0	No	No	
TotalHg-ST17-9/27/08	0840012-12	North Face - West end at corner (scaffolding level)	9/27/08	0.54	Mercury	EPA 324/1631	BRL	9/30/08	< 28.0	No	No	
TotalHg-ST1-9/28/08	0840013-01	Southwest Area (sidewalk bridge level)	9/28/08	0.59	Mercury	EPA 324/1631	BRL	9/30/08	< 25.0	No	No	
TotalHg-ST2-9/28/08	0840013-02	Southeast Area (sidewalk bridge level)	9/28/08	0.57	Mercury	EPA 324/1631	BRL	9/30/08	< 26.0	No	No	
TotalHg-ST4-9/28/08	0840013-03	Northwest Area (street-level)	9/28/08	0.60	Mercury	EPA 324/1631	BRL	9/30/08	< 25.0	No	No	
TotalHg-ST5-9/28/08	0840013-04	Firehouse #10 (roof level)	9/28/08	0.54	Mercury	EPA 324/1631	BRL	9/30/08	< 28.0	No	No	
TotalHg-ST10-9/28/08	0840013-05	North Side Sidewalk Bridge	9/28/08	0.53	Mercury	EPA 324/1631	BRL	9/30/08	< 28.0	No	No	
TotalHg-ST11-9/28/08	0840013-06	90 Trinity Place (roof level)	9/28/08	0.53	Mercury	EPA 324/1631	BRL	9/30/08	< 28.0	No	No	
TotalHg-ST12-9/28/08	0840013-07	110 Greenwich Street (roof level)	9/28/08	0.60	Mercury	EPA 324/1631	BRL	9/30/08	< 25.0	No	No	
TotalHg-ST13-9/28/08	0840013-08	Marriott Hotel, 38th Floor (roof level)	9/28/08	0.56	Mercury	EPA 324/1631	BRL	9/30/08	< 27.0	No	No	
TotalHg-ST14-9/28/08	0840013-09	West Face - South end at corner (scaffolding level)	9/28/08	0.64	Mercury	EPA 324/1631	BRL	9/30/08	< 23.0	No	No	
TotalHg-ST15-9/28/08	0840013-10	South Face - East end at corner (scaffolding level)	9/28/08	0.58	Mercury	EPA 324/1631	BRL	9/30/08	< 26.0	No	No	
TotalHg-ST16-9/28/08	0840013-11	East Face - North end at corner (scaffolding level)	9/28/08	0.60	Mercury	EPA 324/1631	BRL	9/30/08	< 25.0	No	No	
TotalHg-ST17-9/28/08	0840013-12	North Face - West end at corner (scaffolding level)	9/28/08	0.58	Mercury	EPA 324/1631	BRL	9/30/08	< 26.0	No	No	