

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Mercury (Total) Concentration (ng/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
									300			
Target Air Quality Levels												
EPA Site Specific Trigger Levels									3,000			
TotalHg-ST1-10/6/05	05BR1504-1	Southwest Area (street-level)	10/6/2005	0.57	Mercury	EPA 324/1631	BRL	10/8/2005	< 26.3	No	No	Marriott Hotel, 38th Floor (roof level) sample result available in next report; reanalysis currently being performed.
TotalHg-ST2-10/6/05	05BR1504-2	Southeast Area (sidewalk bridge level)	10/6/2005	0.58	Mercury	EPA 324/1631	BRL	10/8/2005	< 25.9	No	No	
TotalHg-ST4-10/6/05	05BR1504-3	Northwest Area (street-level)	10/6/2005	0.55	Mercury	EPA 324/1631	BRL	10/8/2005	< 27.3	No	No	
TotalHg-ST5-10/6/05	05BR1504-4	Firehouse #10 (roof level)	10/6/2005	0.56	Mercury	EPA 324/1631	BRL	10/8/2005	< 26.8	No	No	
TotalHg-ST10-10/6/05	05BR1504-5	North Side Sidewalk Bridge	10/6/2005	0.55	Mercury	EPA 324/1631	BRL	10/8/2005	< 27.3	No	No	
TotalHg-ST11-10/6/05	05BR1504-6	90 Trinity Place (roof level)	10/6/2005	0.57	Mercury	EPA 324/1631	BRL	10/8/2005	< 26.3	No	No	
TotalHg-ST12-10/6/05	05BR1504-7	110 Greenwich Street (roof level)	10/6/2005	0.56	Mercury	EPA 324/1631	BRL	10/8/2005	< 26.8	No	No	
TotalHg-ST1-10/7/05	05BR1509-1	Southwest Area (street-level)	10/7/2005	0.57	Mercury	EPA 324/1631	BRL	10/11/2005	< 26.0	No	No	
TotalHg-ST2-10/7/05	05BR1509-2	Southeast Area (sidewalk bridge level)	10/7/2005	0.50	Mercury	EPA 324/1631	BRL	10/11/2005	< 30.0	No	No	
TotalHg-ST4-10/7/05	05BR1509-3	Northwest Area (street-level)	10/7/2005	0.58	Mercury	EPA 324/1631	BRL	10/11/2005	< 26.0	No	No	
TotalHg-ST5-10/7/05	05BR1509-4	Firehouse #10 (roof level)	10/7/2005	0.58	Mercury	EPA 324/1631	BRL	10/11/2005	< 26.0	No	No	
TotalHg-ST10-10/7/05	05BR1509-5	North Side Sidewalk Bridge	10/7/2005	0.58	Mercury	EPA 324/1631	BRL	10/11/2005	< 26.0	No	No	
TotalHg-ST11-10/7/05	05BR1509-6	90 Trinity Place (roof level)	10/7/2005	0.58	Mercury	EPA 324/1631	BRL	10/11/2005	< 26.0	No	No	
TotalHg-ST12-10/7/05	05BR1509-7	110 Greenwich Street (roof level)	10/7/2005	0.58	Mercury	EPA 324/1631	BRL	10/11/2005	< 26.0	No	No	
TotalHg-ST13-10/7/05	05BR1509-8	Marriott Hotel, 38th Floor (roof level)	10/7/2005	0.58	Mercury	EPA 324/1631	BRL	10/11/2005	< 26.0	No	No	
TotalHg-ST1-10/8/2005	05BR1510-1	Southwest Area (street-level)	10/8/2005	0.57	Mercury	EPA 324/1631	BRL	10/11/2005	< 26.0	No	No	
TotalHg-ST2-10/8/2005	05BR1510-2	Southeast Area (sidewalk bridge level)	10/8/2005	0.57	Mercury	EPA 324/1631	BRL	10/11/2005	< 26.0	No	No	
TotalHg-ST4-10/8/2005	05BR1510-3	Northwest Area (street-level)	10/8/2005	0.57	Mercury	EPA 324/1631	BRL	10/11/2005	< 26.0	No	No	
TotalHg-ST5-10/8/2005	05BR1510-4	Firehouse #10 (roof level)	10/8/2005	0.57	Mercury	EPA 324/1631	BRL	10/11/2005	< 26.0	No	No	
TotalHg-ST10-10/8/2005	05BR1510-5	North Side Sidewalk Bridge	10/8/2005	0.56	Mercury	EPA 324/1631	BRL	10/11/2005	< 27.0	No	No	
TotalHg-ST11-10/8/2005	05BR1510-6	90 Trinity Place (roof level)	10/8/2005	0.33	Mercury	EPA 324/1631	BRL	10/11/2005	< 45.0	No	No	
TotalHg-ST12-10/8/2005	05BR1510-7	110 Greenwich Street (roof level)	10/8/2005	0.59	Mercury	EPA 324/1631	BRL	10/11/2005	< 25.0	No	No	
TotalHg-ST13-10/8/2005	05BR1510-8	Marriott Hotel, 38th Floor (roof level)	10/8/2005	0.57	Mercury	EPA 324/1631	BRL	10/11/2005	< 26.0	No	No	
TotalHg-ST1-10/9/05	05BR1511-1	Southwest Area (street-level)	10/9/2005	0.58	Mercury	EPA 324/1631	BRL	10/11/2005	< 26.0	No	No	
TotalHg-ST2-10/9/05	05BR1511-2	Southeast Area (sidewalk bridge level)	10/9/2005	0.57	Mercury	EPA 324/1631	BRL	10/11/2005	< 26.0	No	No	
TotalHg-ST4-10/9/05	05BR1511-3	Northwest Area (street-level)	10/9/2005	0.56	Mercury	EPA 324/1631	BRL	10/11/2005	< 27.0	No	No	
TotalHg-ST5-10/9/05	05BR1511-4	Firehouse #10 (roof level)	10/9/2005	0.58	Mercury	EPA 324/1631	BRL	10/11/2005	< 26.0	No	No	
TotalHg-ST10-10/9/05	05BR1511-5	North Side Sidewalk Bridge	10/9/2005	0.57	Mercury	EPA 324/1631	BRL	10/11/2005	< 26.0	No	No	
TotalHg-ST11-10/9/05	05BR1511-6	90 Trinity Place (roof level)	10/9/2005	0.57	Mercury	EPA 324/1631	BRL	10/11/2005	< 26.0	No	No	
TotalHg-ST12-10/9/05	05BR1511-7	110 Greenwich Street (roof level)	10/9/2005	0.56	Mercury	EPA 324/1631	BRL	10/11/2005	< 27.0	No	No	
TotalHg-ST13-10/9/05	05BR1511-8	Marriott Hotel, 38th Floor (roof level)	10/9/2005	0.57	Mercury	EPA 324/1631	BRL	10/11/2005	< 26.0	No	No	