

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Mercury (Total) Concentration (ng/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
									300			
									3,000			
TotalHg-ST1-10/09/06	06BR1635-01	Southwest Area (sidewalk bridge level)	10/9/06	0.56	Mercury	EPA 324/1631	BRL	10/11/06	< 27.0	No	No	
TotalHg-ST2-10/09/06	06BR1635-02	Southeast Area (sidewalk bridge level)	10/9/06	0.56	Mercury	EPA 324/1631	BRL	10/11/06	< 27.0	No	No	
TotalHg-ST4-10/09/06	06BR1635-03	Northwest Area (street-level)	10/9/06	0.54	Mercury	EPA 324/1631	BRL	10/11/06	< 28.0	No	No	
TotalHg-ST5-10/09/06	06BR1635-04	Firehouse #10 (roof level)	10/9/06	0.56	Mercury	EPA 324/1631	BRL	10/11/06	< 27.0	No	No	
TotalHg-ST10-10/09/06	06BR1635-05	North Side Sidewalk Bridge	10/9/06	0.56	Mercury	EPA 324/1631	BRL	10/11/06	< 27.0	No	No	
TotalHg-ST11-10/09/06	06BR1635-06	90 Trinity Place (roof level)	10/9/06	0.57	Mercury	EPA 324/1631	BRL	10/11/06	< 26.0	No	No	
TotalHg-ST12-10/09/06	06BR1635-07	110 Greenwich Street (roof level)	10/9/06	0.55	Mercury	EPA 324/1631	BRL	10/11/06	< 27.0	No	No	
TotalHg-ST13-10/09/06	06BR1635-08	Marriott Hotel, 38th Floor (roof level)	10/9/06	0.57	Mercury	EPA 324/1631	BRL	10/11/06	< 26.0	No	No	
TotalHg-ST14-10/09/06	06BR1635-09	West Face - South end at corner (scaffolding level)	10/9/06	0.57	Mercury	EPA 324/1631	BRL	10/11/06	< 26.0	No	No	
TotalHg-ST15-10/09/06	06BR1635-10	South Face - East end at corner (scaffolding level)	10/9/06	0.58	Mercury	EPA 324/1631	BRL	10/11/06	< 26.0	No	No	
TotalHg-ST16-10/09/06	06BR1635-11	East Face - North end at corner (scaffolding level)	10/9/06	0.58	Mercury	EPA 324/1631	BRL	10/11/06	< 26.0	No	No	
TotalHg-ST17-10/09/06	06BR1635-12	North Face - West end at corner (scaffolding level)	10/9/06	0.58	Mercury	EPA 324/1631	BRL	10/11/06	< 26.0	No	No	
TotalHg-ST1-10/10/06	06BR1638-01	Southwest Area (sidewalk bridge level)	10/10/06	0.57	Mercury	EPA 324/1631	BRL	10/12/06	< 26.0	No	No	
TotalHg-ST2-10/10/06	06BR1638-02	Southeast Area (sidewalk bridge level)	10/10/06	0.58	Mercury	EPA 324/1631	BRL	10/12/06	< 26.0	No	No	
TotalHg-ST4-10/10/06	06BR1638-03	Northwest Area (street-level)	10/10/06	0.57	Mercury	EPA 324/1631	BRL	10/12/06	< 26.0	No	No	
TotalHg-ST5-10/10/06	06BR1638-04	Firehouse #10 (roof level)	10/10/06	0.56	Mercury	EPA 324/1631	BRL	10/12/06	< 27.0	No	No	
TotalHg-ST10-10/10/06	06BR1638-05	North Side Sidewalk Bridge	10/10/06	0.55	Mercury	EPA 324/1631	BRL	10/12/06	< 27.0	No	No	
TotalHg-ST11-10/10/06	06BR1638-06	90 Trinity Place (roof level)	10/10/06	0.57	Mercury	EPA 324/1631	BRL	10/12/06	< 26.0	No	No	
TotalHg-ST12-10/10/06	06BR1638-07	110 Greenwich Street (roof level)	10/10/06	0.53	Mercury	EPA 324/1631	BRL	10/12/06	< 28.0	No	No	
TotalHg-ST13-10/10/06	06BR1638-08	Marriott Hotel, 38th Floor (roof level)	10/10/06	0.58	Mercury	EPA 324/1631	BRL	10/12/06	< 26.0	No	No	
TotalHg-ST14-10/10/06	06BR1638-09	West Face - South end at corner (scaffolding level)	10/10/06	0.57	Mercury	EPA 324/1631	BRL	10/12/06	< 26.0	No	No	
TotalHg-ST15-10/10/06	06BR1638-10	South Face - East end at corner (scaffolding level)	10/10/06	0.57	Mercury	EPA 324/1631	BRL	10/12/06	< 26.0	No	No	
TotalHg-ST16-10/10/06	06BR1638-11	East Face - North end at corner (scaffolding level)	10/10/06	0.53	Mercury	EPA 324/1631	BRL	10/12/06	< 28.0	No	No	
TotalHg-ST17-10/10/06	06BR1638-12	North Face - West end at corner (scaffolding level)	10/10/06	0.55	Mercury	EPA 324/1631	BRL	10/12/06	< 27.0	No	No	