

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m <sup>3</sup> )	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Mercury (Total) Concentration (ng/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
<b>Target Air Quality Levels</b>									<b>300</b>			
<b>EPA Site Specific Trigger Levels</b>									<b>3,000</b>			
TotalHg-ST1-10/10/05	05BR1519-1	Southwest Area (street-level)	10/10/2005	0.57	Mercury	EPA 324/1631	BRL	10/12/2005	< 26.0	No	No	
TotalHg-ST2-10/10/05	05BR1519-2	Southeast Area (sidewalk bridge level)	10/10/2005	0.57	Mercury	EPA 324/1631	BRL	10/12/2005	< 26.0	No	No	
TotalHg-ST4-10/10/05	05BR1519-3	Northwest Area (street-level)	10/10/2005	0.61	Mercury	EPA 324/1631	BRL	10/12/2005	< 25.0	No	No	
TotalHg-ST5-10/10/05	05BR1519-4	Firehouse #10 (roof level)	10/10/2005	0.57	Mercury	EPA 324/1631	BRL	10/12/2005	< 26.0	No	No	
TotalHg-ST10-10/10/05	05BR1519-5	North Side Sidewalk Bridge	10/10/2005	0.60	Mercury	EPA 324/1631	BRL	10/12/2005	< 25.0	No	No	
TotalHg-ST11-10/10/05	05BR1519-6	90 Trinity Place (roof level)	10/10/2005	0.56	Mercury	EPA 324/1631	BRL	10/12/2005	< 27.0	No	No	
TotalHg-ST12-10/10/05	05BR1519-7	110 Greenwich Street (roof level)	10/10/2005	0.58	Mercury	EPA 324/1631	BRL	10/12/2005	< 26.0	No	No	
TotalHg-ST13-10/10/05	05BR1519-8	Marriott Hotel, 38th Floor (roof level)	10/10/2005	0.58	Mercury	EPA 324/1631	BRL	10/12/2005	< 26.0	No	No	
TotalHg-ST1-10/11/05	05BR1523-1	Southwest Area (street-level)	10/11/2005	0.57	Mercury	EPA 324/1631	BRL	10/13/2005	< 26.0	No	No	
TotalHg-ST2-10/11/05	05BR1523-2	Southeast Area (sidewalk bridge level)	10/11/2005	0.57	Mercury	EPA 324/1631	BRL	10/13/2005	< 26.0	No	No	
TotalHg-ST4-10/11/05	05BR1523-3	Northwest Area (street-level)	10/11/2005	0.53	Mercury	EPA 324/1631	BRL	10/13/2005	< 28.0	No	No	
TotalHg-ST5-10/11/05	05BR1523-4	Firehouse #10 (roof level)	10/11/2005	0.58	Mercury	EPA 324/1631	BRL	10/13/2005	< 26.0	No	No	
TotalHg-ST10-10/11/05	05BR1523-5	North Side Sidewalk Bridge	10/11/2005	0.54	Mercury	EPA 324/1631	BRL	10/13/2005	< 28.0	No	No	
TotalHg-ST11-10/11/05	05BR1523-6	90 Trinity Place (roof level)	10/11/2005	0.58	Mercury	EPA 324/1631	BRL	10/13/2005	< 26.0	No	No	
TotalHg-ST12-10/11/05	05BR1523-7	110 Greenwich Street (roof level)	10/11/2005	0.56	Mercury	EPA 324/1631	BRL	10/13/2005	< 27.0	No	No	
TotalHg-ST13-10/11/05	05BR1523-8	Marriott Hotel, 38th Floor (roof level)	10/11/2005	0.56	Mercury	EPA 324/1631	BRL	10/13/2005	< 27.0	No	No	
TotalHg-ST1-10/12/05	05BR1536-1	Southwest Area (street-level)	10/12/2005	0.57	Mercury	EPA 324/1631	BRL	10/14/2005	< 26.0	No	No	
TotalHg-ST2-10/12/05	05BR1536-2	Southeast Area (sidewalk bridge level)	10/12/2005	0.57	Mercury	EPA 324/1631	BRL	10/14/2005	< 26.0	No	No	
TotalHg-ST4-10/12/05	05BR1536-3	Northwest Area (street-level)	10/12/2005	0.58	Mercury	EPA 324/1631	BRL	10/14/2005	< 26.0	No	No	
TotalHg-ST5-10/12/05	05BR1536-4	Firehouse #10 (roof level)	10/12/2005	0.57	Mercury	EPA 324/1631	BRL	10/14/2005	< 26.0	No	No	
TotalHg-ST10-10/12/05	05BR1536-5	North Side Sidewalk Bridge	10/12/2005	0.58	Mercury	EPA 324/1631	BRL	10/14/2005	< 26.0	No	No	
TotalHg-ST11-10/12/05	05BR1536-6	90 Trinity Place (roof level)	10/12/2005	0.60	Mercury	EPA 324/1631	BRL	10/14/2005	< 25.0	No	No	
TotalHg-ST12-10/12/05	05BR1536-7	110 Greenwich Street (roof level)	10/12/2005	0.58	Mercury	EPA 324/1631	BRL	10/14/2005	< 26.0	No	No	
TotalHg-ST13-10/12/05	05BR1536-8	Marriott Hotel, 38th Floor (roof level)	10/12/2005	0.57	Mercury	EPA 324/1631	BRL	10/14/2005	< 26.0	No	No	
TotalHg-ST1-10/13/05	05BR1540-1	Southwest Area (street-level)	10/13/2005	0.57	Mercury	EPA 324/1631	BRL	10/15/2005	< 26.0	No	No	
TotalHg-ST2-10/13/05	05BR1540-2	Southeast Area (sidewalk bridge level)	10/13/2005	0.58	Mercury	EPA 324/1631	BRL	10/15/2005	< 26.0	No	No	
TotalHg-ST4-10/13/05	05BR1540-3	Northwest Area (street-level)	10/13/2005	0.58	Mercury	EPA 324/1631	BRL	10/15/2005	< 26.0	No	No	
TotalHg-ST5-10/13/05	05BR1540-4	Firehouse #10 (roof level)	10/13/2005	0.57	Mercury	EPA 324/1631	BRL	10/15/2005	< 26.0	No	No	
TotalHg-ST10-10/13/05	05BR1540-5	North Side Sidewalk Bridge	10/13/2005	0.58	Mercury	EPA 324/1631	BRL	10/15/2005	< 26.0	No	No	
TotalHg-ST11-10/13/05	05BR1540-6	90 Trinity Place (roof level)	10/13/2005	0.55	Mercury	EPA 324/1631	BRL	10/15/2005	< 27.0	No	No	
TotalHg-ST12-10/13/05	05BR1540-7	110 Greenwich Street (roof level)	10/13/2005	0.58	Mercury	EPA 324/1631	BRL	10/15/2005	< 26.0	No	No	
TotalHg-ST13-10/13/05	05BR1540-8	Marriott Hotel, 38th Floor (roof level)	10/13/2005	0.59	Mercury	EPA 324/1631	BRL	10/15/2005	< 25.0	No	No	