

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Mercury (Total) Concentration (ng/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
Target Air Quality Levels									300			
EPA Site Specific Trigger Levels									3,000			
TotalHg-ST1-10/21/05	05BR1602-1	Southwest Area (street-level)	10/21/2005	0.58	Mercury	EPA 324/1631	BRL	10/25/2005	< 26.0	No	No	
TotalHg-ST2-10/21/05	05BR1602-2	Southeast Area (sidewalk bridge level)	10/21/2005	0.58	Mercury	EPA 324/1631	BRL	10/25/2005	< 26.0	No	No	
TotalHg-ST4-10/21/05	05BR1602-3	Northwest Area (street-level)	10/21/2005	0.59	Mercury	EPA 324/1631	BRL	10/25/2005	< 25.0	No	No	
TotalHg-ST5-10/21/05	05BR1602-4	Firehouse #10 (roof level)	10/21/2005	0.56	Mercury	EPA 324/1631	BRL	10/25/2005	< 27.0	No	No	
TotalHg-ST10-10/21/05	05BR1602-5	North Side Sidewalk Bridge	10/21/2005	0.56	Mercury	EPA 324/1631	BRL	10/25/2005	< 27.0	No	No	
TotalHg-ST11-10/21/05	05BR1602-6	90 Trinity Place (roof level)	10/21/2005	0.58	Mercury	EPA 324/1631	BRL	10/25/2005	< 26.0	No	No	
TotalHg-ST12-10/21/05	05BR1602-7	110 Greenwich Street (roof level)	10/21/2005	0.56	Mercury	EPA 324/1631	BRL	10/25/2005	< 27.0	No	No	
TotalHg-ST13-10/21/05	05BR1602-8	Marriott Hotel, 38th Floor (roof level)	10/21/2005	0.56	Mercury	EPA 324/1631	BRL	10/25/2005	< 27.0	No	No	
TotalHg-ST1-10/22/05	05BR1603-1	Southwest Area (street-level)	10/22/2005	0.56	Mercury	EPA 324/1631	BRL	10/25/2005	< 27.0	No	No	
TotalHg-ST2-10/22/05	05BR1603-2	Southeast Area (sidewalk bridge level)	10/22/2005	0.56	Mercury	EPA 324/1631	BRL	10/25/2005	< 27.0	No	No	
TotalHg-ST4-10/22/05	05BR1603-3	Northwest Area (street-level)	10/22/2005	0.56	Mercury	EPA 324/1631	BRL	10/25/2005	< 27.0	No	No	
TotalHg-ST5-10/22/05	05BR1603-4	Firehouse #10 (roof level)	10/22/2005	0.57	Mercury	EPA 324/1631	BRL	10/25/2005	< 26.0	No	No	
TotalHg-ST10-10/22/05	05BR1603-5	North Side Sidewalk Bridge	10/22/2005	0.57	Mercury	EPA 324/1631	BRL	10/25/2005	< 26.0	No	No	
TotalHg-ST11-10/22/05	05BR1603-6	90 Trinity Place (roof level)	10/22/2005	0.57	Mercury	EPA 324/1631	BRL	10/25/2005	< 26.0	No	No	
TotalHg-ST12-10/22/05	05BR1603-7	110 Greenwich Street (roof level)	10/22/2005	0.57	Mercury	EPA 324/1631	BRL	10/25/2005	< 26.0	No	No	
TotalHg-ST13-10/22/05	05BR1603-8	Marriott Hotel, 38th Floor (roof level)	10/22/2005	0.57	Mercury	EPA 324/1631	BRL	10/25/2005	< 26.0	No	No	
TotalHg-ST1-10/23/05	05BR1604-1	Southwest Area (street-level)	10/23/2005	0.57	Mercury	EPA 324/1631	BRL	10/25/2005	< 26.0	No	No	
TotalHg-ST2-10/23/05	05BR1604-2	Southeast Area (sidewalk bridge level)	10/23/2005	0.57	Mercury	EPA 324/1631	BRL	10/25/2005	< 26.0	No	No	
TotalHg-ST4-10/23/05	05BR1604-3	Northwest Area (street-level)	10/23/2005	0.57	Mercury	EPA 324/1631	BRL	10/25/2005	< 26.0	No	No	
TotalHg-ST5-10/23/05	05BR1604-4	Firehouse #10 (roof level)	10/23/2005	0.57	Mercury	EPA 324/1631	BRL	10/25/2005	< 26.0	No	No	
TotalHg-ST10-10/23/05	05BR1604-5	North Side Sidewalk Bridge	10/23/2005	0.60	Mercury	EPA 324/1631	BRL	10/25/2005	< 25.0	No	No	
TotalHg-ST11-10/23/05	05BR1604-6	90 Trinity Place (roof level)	10/23/2005	0.57	Mercury	EPA 324/1631	BRL	10/25/2005	< 26.0	No	No	
TotalHg-ST12-10/23/05	05BR1604-7	110 Greenwich Street (roof level)	10/23/2005	0.58	Mercury	EPA 324/1631	BRL	10/25/2005	< 26.0	No	No	
TotalHg-ST13-10/23/05	05BR1604-8	Marriott Hotel, 38th Floor (roof level)	10/23/2005	0.60	Mercury	EPA 324/1631	BRL	10/25/2005	< 25.0	No	No	
TotalHg-ST1-10/24/05	05BR1606-1	Southwest Area (street-level)	10/24/2005	0.57	Mercury	EPA 324/1631	BRL	10/26/2005	< 26.0	No	No	
TotalHg-ST2-10/24/05	05BR1606-2	Southeast Area (sidewalk bridge level)	10/24/2005	0.58	Mercury	EPA 324/1631	BRL	10/26/2005	< 26.0	No	No	
TotalHg-ST4-10/24/05	05BR1606-3	Northwest Area (street-level)	10/24/2005	0.58	Mercury	EPA 324/1631	BRL	10/26/2005	< 26.0	No	No	
TotalHg-ST5-10/24/05	05BR1606-4	Firehouse #10 (roof level)	10/24/2005	0.57	Mercury	EPA 324/1631	BRL	10/26/2005	< 26.0	No	No	
TotalHg-ST10-10/24/05	05BR1606-5	North Side Sidewalk Bridge	10/24/2005	0.58	Mercury	EPA 324/1631	BRL	10/26/2005	< 26.0	No	No	
TotalHg-ST11-10/24/05	05BR1606-6	90 Trinity Place (roof level)	10/24/2005	0.57	Mercury	EPA 324/1631	BRL	10/26/2005	< 26.0	No	No	
TotalHg-ST12-10/24/05	05BR1606-7	110 Greenwich Street (roof level)	10/24/2005	0.54	Mercury	EPA 324/1631	BRL	10/26/2005	< 28.0	No	No	
TotalHg-ST13-10/24/05	05BR1606-8	Marriott Hotel, 38th Floor (roof level)	10/24/2005	0.55	Mercury	EPA 324/1631	BRL	10/26/2005	< 27.0	No	No	
TotalHg-ST1-10/25/05	05BR1611-1	Southwest Area (street-level)	10/25/2005	0.57	Mercury	EPA 324/1631	BRL	10/27/2005	< 26.0	No	No	
TotalHg-ST2-10/25/05	05BR1611-2	Southeast Area (sidewalk bridge level)	10/25/2005	0.59	Mercury	EPA 324/1631	BRL	10/27/2005	< 25.0	No	No	
TotalHg-ST4-10/25/05	05BR1611-3	Northwest Area (street-level)	10/25/2005	0.58	Mercury	EPA 324/1631	BRL	10/27/2005	< 26.0	No	No	
TotalHg-ST5-10/25/05	05BR1611-4	Firehouse #10 (roof level)	10/25/2005	0.57	Mercury	EPA 324/1631	BRL	10/27/2005	< 26.0	No	No	
TotalHg-ST10-10/25/05	05BR1611-5	North Side Sidewalk Bridge	10/25/2005	0.58	Mercury	EPA 324/1631	BRL	10/27/2005	< 26.0	No	No	
TotalHg-ST11-10/25/05	05BR1611-6	90 Trinity Place (roof level)	10/25/2005	0.57	Mercury	EPA 324/1631	BRL	10/27/2005	< 26.0	No	No	
TotalHg-ST12-10/25/05	05BR1611-7	110 Greenwich Street (roof level)	10/25/2005	0.57	Mercury	EPA 324/1631	BRL	10/27/2005	< 26.0	No	No	
TotalHg-ST13-10/25/05	05BR1611-8	Marriott Hotel, 38th Floor (roof level)	10/25/2005	0.57	Mercury	EPA 324/1631	BRL	10/27/2005	< 26.0	No	No	
TotalHg-ST1-10/26/05	05BR1616-1	Southwest Area (street-level)	10/26/2005	0.57	Mercury	EPA 324/1631	BRL	10/28/2005	< 26.0	No	No	
TotalHg-ST2-10/26/05	05BR1616-2	Southeast Area (sidewalk bridge level)	10/26/2005	0.55	Mercury	EPA 324/1631	BRL	10/28/2005	< 27.0	No	No	
TotalHg-ST4-10/26/05	05BR1616-3	Northwest Area (street-level)	10/26/2005	0.58	Mercury	EPA 324/1631	BRL	10/28/2005	< 26.0	No	No	
TotalHg-ST5-10/26/05	05BR1616-4	Firehouse #10 (roof level)	10/26/2005	0.60	Mercury	EPA 324/1631	BRL	10/28/2005	< 25.0	No	No	
TotalHg-ST10-10/26/05	05BR1616-5	North Side Sidewalk Bridge	10/26/2005	0.58	Mercury	EPA 324/1631	BRL	10/28/2005	< 26.0	No	No	
TotalHg-ST11-10/26/05	05BR1616-6	90 Trinity Place (roof level)	10/26/2005	0.57	Mercury	EPA 324/1631	BRL	10/28/2005	< 26.0	No	No	
TotalHg-ST12-10/26/05	05BR1616-7	110 Greenwich Street (roof level)	10/26/2005	0.59	Mercury	EPA 324/1631	BRL	10/28/2005	< 25.0	No	No	
TotalHg-ST13-10/26/05	05BR1616-8	Marriott Hotel, 38th Floor (roof level)	10/26/2005	0.56	Mercury	EPA 324/1631	BRL	10/28/2005	< 27.0	No	No	