

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m <sup>3</sup> )	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Mercury (Total) Concentration (ng/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
									300			
									3,000			
TotalHg-ST1-10/23/06	06BR1719-01	Southwest Area (sidewalk bridge level)	10/23/06	0.57	Mercury	EPA 324/1631	BRL	10/25/06	< 26.0	No	No	
TotalHg-ST2-10/23/06	06BR1719-02	Southeast Area (sidewalk bridge level)	10/23/06	0.57	Mercury	EPA 324/1631	BRL	10/25/06	< 26.0	No	No	
TotalHg-ST4-10/23/06	06BR1719-03	Northwest Area (street-level)	10/23/06	0.59	Mercury	EPA 324/1631	BRL	10/25/06	< 25.0	No	No	
TotalHg-ST5-10/23/06	06BR1719-04	Firehouse #10 (roof level)	10/23/06	0.57	Mercury	EPA 324/1631	BRL	10/25/06	< 26.0	No	No	
TotalHg-ST10-10/23/06	06BR1719-05	North Side Sidewalk Bridge	10/23/06	0.59	Mercury	EPA 324/1631	BRL	10/25/06	< 25.0	No	No	
TotalHg-ST100-10/23/06FD	06BR1719-13	Station 10 Field Duplicate	10/23/06	0.58	Mercury	EPA 324/1631	BRL	10/25/06	< 26.0	No	No	
TotalHg-ST11-10/23/06	06BR1719-06	90 Trinity Place (roof level)	10/23/06	0.59	Mercury	EPA 324/1631	BRL	10/25/06	< 25.0	No	No	
TotalHg-ST12-10/23/06	06BR1719-07	110 Greenwich Street (roof level)	10/23/06	0.59	Mercury	EPA 324/1631	BRL	10/25/06	< 25.0	No	No	
TotalHg-ST13-10/23/06	06BR1719-08	Marriott Hotel, 38th Floor (roof level)	10/23/06	0.56	Mercury	EPA 324/1631	BRL	10/25/06	< 27.0	No	No	
TotalHg-ST14-10/23/06	06BR1719-09	West Face - South end at corner (scaffolding level)	10/23/06	0.55	Mercury	EPA 324/1631	BRL	10/25/06	< 27.0	No	No	
TotalHg-ST15-10/23/06	06BR1719-10	South Face - East end at corner (scaffolding level)	10/23/06	0.58	Mercury	EPA 324/1631	BRL	10/25/06	< 26.0	No	No	
TotalHg-ST16-10/23/06	06BR1719-11	East Face - North end at corner (scaffolding level)	10/23/06	0.57	Mercury	EPA 324/1631	BRL	10/25/06	< 26.0	No	No	
TotalHg-ST17-10/23/06	06BR1719-12	North Face - West end at corner (scaffolding level)	10/23/06	0.57	Mercury	EPA 324/1631	BRL	10/25/06	< 26.0	No	No	
TotalHg-ST1-10/24/06	06BR1724-01	Southwest Area (sidewalk bridge level)	10/24/06	0.57	Mercury	EPA 324/1631	BRL	10/26/06	< 26.0	No	No	
TotalHg-ST2-10/24/06	06BR1724-02	Southeast Area (sidewalk bridge level)	10/24/06	0.57	Mercury	EPA 324/1631	BRL	10/26/06	< 26.0	No	No	
TotalHg-ST4-10/24/06	06BR1724-03	Northwest Area (street-level)	10/24/06	0.59	Mercury	EPA 324/1631	BRL	10/26/06	< 25.0	No	No	
TotalHg-ST5-10/24/06	06BR1724-04	Firehouse #10 (roof level)	10/24/06	0.58	Mercury	EPA 324/1631	BRL	10/26/06	< 26.0	No	No	
TotalHg-ST10-10/24/06	06BR1724-05	North Side Sidewalk Bridge	10/24/06	0.60	Mercury	EPA 324/1631	BRL	10/26/06	< 25.0	No	No	
TotalHg-ST11-10/24/06	06BR1724-06	90 Trinity Place (roof level)	10/24/06	0.58	Mercury	EPA 324/1631	BRL	10/26/06	< 26.0	No	No	
TotalHg-ST12-10/24/06	06BR1724-07	110 Greenwich Street (roof level)	10/24/06	0.59	Mercury	EPA 324/1631	BRL	10/26/06	< 25.0	No	No	
TotalHg-ST13-10/24/06	06BR1724-08	Marriott Hotel, 38th Floor (roof level)	10/24/06	0.58	Mercury	EPA 324/1631	BRL	10/26/06	< 26.0	No	No	
TotalHg-ST14-10/24/06	06BR1724-09	West Face - South end at corner (scaffolding level)	10/24/06	0.57	Mercury	EPA 324/1631	BRL	10/26/06	< 26.0	No	No	
TotalHg-ST15-10/24/06	06BR1724-10	South Face - East end at corner (scaffolding level)	10/24/06	0.57	Mercury	EPA 324/1631	BRL	10/26/06	< 26.0	No	No	
TotalHg-ST16-10/24/06	06BR1724-11	East Face - North end at corner (scaffolding level)	10/24/06	0.57	Mercury	EPA 324/1631	BRL	10/26/06	< 26.0	No	No	
TotalHg-ST17-10/24/06	06BR1724-12	North Face - West end at corner (scaffolding level)	10/24/06	0.56	Mercury	EPA 324/1631	BRL	10/26/06	< 27.0	No	No	