

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Mercury (Total) Concentration (ng/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
									300			
									3,000			
TotalHg-ST1-10/27/05	05BR1619-1	Southwest Area (street-level)	10/27/2005	0.28	Mercury	EPA 324/1631	BRL	10/29/2005	< 54.0	No	No	Reduced volume due to flow fault on SKC pump.
TotalHg-ST2-10/27/05	05BR1619-2	Southeast Area (sidewalk bridge level)	10/27/2005	0.55	Mercury	EPA 324/1631	BRL	10/29/2005	< 27.0	No	No	
TotalHg-ST4-10/27/05	05BR1619-3	Northwest Area (street-level)	10/27/2005	0.55	Mercury	EPA 324/1631	BRL	10/29/2005	< 27.0	No	No	
TotalHg-ST5-10/27/05	05BR1619-4	Firehouse #10 (roof level)	10/27/2005	0.55	Mercury	EPA 324/1631	BRL	10/29/2005	< 27.0	No	No	
TotalHg-ST10-10/27/05	05BR1619-5	North Side Sidewalk Bridge	10/27/2005	0.55	Mercury	EPA 324/1631	BRL	10/29/2005	< 27.0	No	No	
TotalHg-ST11-10/27/05	05BR1619-6	90 Trinity Place (roof level)	10/27/2005	0.56	Mercury	EPA 324/1631	BRL	10/29/2005	< 27.0	No	No	
TotalHg-ST12-10/27/05	05BR1619-7	110 Greenwich Street (roof level)	10/27/2005	0.55	Mercury	EPA 324/1631	BRL	10/29/2005	< 27.0	No	No	
TotalHg-ST13-10/27/05	05BR1619-8	Marriott Hotel, 38th Floor (roof level)	10/27/2005	0.59	Mercury	EPA 324/1631	BRL	10/29/2005	< 25.0	No	No	
TotalHg-ST1-10/28/05	05BR1622-1	Southwest Area (street-level)	10/28/2005	0.58	Mercury	EPA 324/1631	BRL	11/1/2005	< 26.0	No	No	
TotalHg-ST2-10/28/05	05BR1622-2	Southeast Area (sidewalk bridge level)	10/28/2005	0.59	Mercury	EPA 324/1631	BRL	11/1/2005	< 25.0	No	No	
TotalHg-ST4-10/28/05	05BR1622-3	Northwest Area (street-level)	10/28/2005	0.55	Mercury	EPA 324/1631	BRL	11/1/2005	< 27.0	No	No	
TotalHg-ST5-10/28/05	05BR1622-4	Firehouse #10 (roof level)	10/28/2005	0.58	Mercury	EPA 324/1631	BRL	11/1/2005	< 26.0	No	No	
TotalHg-ST10-10/28/05	05BR1622-5	North Side Sidewalk Bridge	10/28/2005	0.55	Mercury	EPA 324/1631	BRL	11/1/2005	< 27.0	No	No	
TotalHg-ST11-10/28/05	05BR1622-6	90 Trinity Place (roof level)	10/28/2005	0.58	Mercury	EPA 324/1631	BRL	11/1/2005	< 26.0	No	No	
TotalHg-ST12-10/28/05	05BR1622-7	110 Greenwich Street (roof level)	10/28/2005	0.58	Mercury	EPA 324/1631	BRL	11/1/2005	< 26.0	No	No	
TotalHg-ST13-10/28/05	05BR1622-8	Marriott Hotel, 38th Floor (roof level)	10/28/2005	0.58	Mercury	EPA 324/1631	BRL	11/1/2005	< 26.0	No	No	
TotalHg-ST1-10/29/05	05BR1623-1	Southwest Area (street-level)	10/29/2005	0.57	Mercury	EPA 324/1631	BRL	11/1/2005	< 26.0	No	No	
TotalHg-ST2-10/29/05	05BR1623-2	Southeast Area (sidewalk bridge level)	10/29/2005	0.57	Mercury	EPA 324/1631	BRL	11/1/2005	< 26.0	No	No	
TotalHg-ST4-10/29/05	05BR1623-3	Northwest Area (street-level)	10/29/2005	0.58	Mercury	EPA 324/1631	BRL	11/1/2005	< 26.0	No	No	
TotalHg-ST5-10/29/05	05BR1623-4	Firehouse #10 (roof level)	10/29/2005	0.59	Mercury	EPA 324/1631	BRL	11/1/2005	< 25.0	No	No	
TotalHg-ST10-10/29/05	05BR1623-5	North Side Sidewalk Bridge	10/29/2005	0.58	Mercury	EPA 324/1631	BRL	11/1/2005	< 26.0	No	No	
TotalHg-ST11-10/29/05	05BR1623-6	90 Trinity Place (roof level)	10/29/2005	0.60	Mercury	EPA 324/1631	BRL	11/1/2005	< 25.0	No	No	
TotalHg-ST12-10/29/05	05BR1623-7	110 Greenwich Street (roof level)	10/29/2005	0.60	Mercury	EPA 324/1631	BRL	11/1/2005	< 25.0	No	No	
TotalHg-ST13-10/29/05	05BR1623-8	Marriott Hotel, 38th Floor (roof level)	10/29/2005	0.57	Mercury	EPA 324/1631	BRL	11/1/2005	< 26.0	No	No	
TotalHg-ST1-10/30/05	05BR1624-1	Southwest Area (street-level)	10/30/2005	0.57	Mercury	EPA 324/1631	BRL	11/1/2005	< 26.0	No	No	
TotalHg-ST2-10/30/05	05BR1624-2	Southeast Area (sidewalk bridge level)	10/30/2005	0.57	Mercury	EPA 324/1631	BRL	11/1/2005	< 26.0	No	No	
TotalHg-ST4-10/30/05	05BR1624-3	Northwest Area (street-level)	10/30/2005	0.58	Mercury	EPA 324/1631	BRL	11/1/2005	< 26.0	No	No	
TotalHg-ST5-10/30/05	05BR1624-4	Firehouse #10 (roof level)	10/30/2005	0.55	Mercury	EPA 324/1631	BRL	11/1/2005	< 27.0	No	No	
TotalHg-ST10-10/30/05	05BR1624-5	North Side Sidewalk Bridge	10/30/2005	0.58	Mercury	EPA 324/1631	BRL	11/1/2005	< 26.0	No	No	
TotalHg-ST11-10/30/05	05BR1624-6	90 Trinity Place (roof level)	10/30/2005	0.56	Mercury	EPA 324/1631	BRL	11/1/2005	< 27.0	No	No	
TotalHg-ST12-10/30/05	05BR1624-7	110 Greenwich Street (roof level)	10/30/2005	0.58	Mercury	EPA 324/1631	BRL	11/1/2005	< 26.0	No	No	
TotalHg-ST13-10/30/05	05BR1624-8	Marriott Hotel, 38th Floor (roof level)	10/30/2005	0.59	Mercury	EPA 324/1631	BRL	11/1/2005	< 25.0	No	No	