

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Mercury (Total) Concentration (ng/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
Target Air Quality Levels									300			
EPA Site Specific Trigger Levels									3,000			
TotalHg-ST1-10/29/08	0844033-01	Southwest Area (sidewalk bridge level)	10/29/08	0.58	Mercury	EPA 324/1631	BRL	10/31/08	< 26.0	No	No	
TotalHg-ST2-10/29/08	0844033-02	Southeast Area (sidewalk bridge level)	10/29/08	0.59	Mercury	EPA 324/1631	BRL	10/31/08	< 25.0	No	No	
TotalHg-ST4-10/29/08	0844033-03	Northwest Area (street-level)	10/29/08	0.57	Mercury	EPA 324/1631	BRL	10/31/08	< 26.0	No	No	
TotalHg-ST5-10/29/08	0844033-04	Firehouse #10 (roof level)	10/29/08	0.58	Mercury	EPA 324/1631	BRL	10/31/08	< 26.0	No	No	
TotalHg-ST10-10/29/08	0844033-05	North Side Sidewalk Bridge	10/29/08	0.53	Mercury	EPA 324/1631	BRL	10/31/08	< 28.0	No	No	
TotalHg-ST11-10/29/08	0844033-06	90 Trinity Place (roof level)	10/29/08	0.55	Mercury	EPA 324/1631	BRL	10/31/08	< 27.0	No	No	
TotalHg-ST12-10/29/08	0844033-07	110 Greenwich Street (roof level)	10/29/08	0.54	Mercury	EPA 324/1631	BRL	10/31/08	< 28.0	No	No	
TotalHg-ST13-10/29/08	0844033-08	Marriott Hotel, 38th Floor (roof level)	10/29/08	0.57	Mercury	EPA 324/1631	BRL	10/31/08	< 26.0	No	No	
TotalHg-ST14-10/29/08	0844033-09	West Face - South end at corner (scaffolding level)	10/29/08	0.60	Mercury	EPA 324/1631	BRL	10/31/08	< 25.0	No	No	
TotalHg-ST15-10/29/08	0844033-10	South Face - East end at corner (scaffolding level)	10/29/08	0.60	Mercury	EPA 324/1631	BRL	10/31/08	< 25.0	No	No	
TotalHg-ST16-10/29/08	0844033-11	East Face - North end at corner (scaffolding level)	10/29/08	0.55	Mercury	EPA 324/1631	BRL	10/31/08	< 27.0	No	No	
TotalHg-ST17-10/29/08	0844033-12	North Face - West end at corner (scaffolding level)	10/29/08	0.55	Mercury	EPA 324/1631	BRL	10/31/08	< 27.0	No	No	
TotalHg-ST1-10/30/08	0844043-01	Southwest Area (sidewalk bridge level)	10/30/08	0.52	Mercury	EPA 324/1631	BRL	11/1/08	< 29.0	No	No	
TotalHg-ST2-10/30/08	0844043-02	Southeast Area (sidewalk bridge level)	10/30/08	0.58	Mercury	EPA 324/1631	BRL	11/1/08	< 26.0	No	No	
TotalHg-ST4-10/30/08	0844043-03	Northwest Area (street-level)	10/30/08	0.59	Mercury	EPA 324/1631	BRL	11/1/08	< 25.0	No	No	
TotalHg-ST5-10/30/08	0844043-04	Firehouse #10 (roof level)	10/30/08	0.55	Mercury	EPA 324/1631	BRL	11/1/08	< 27.0	No	No	
TotalHg-ST10-10/30/08	0844043-05	North Side Sidewalk Bridge	10/30/08	0.58	Mercury	EPA 324/1631	BRL	11/1/08	< 26.0	No	No	
TotalHg-ST11-10/30/08	0844043-06	90 Trinity Place (roof level)	10/30/08	0.56	Mercury	EPA 324/1631	BRL	11/1/08	< 27.0	No	No	
TotalHg-ST12-10/30/08	0844043-07	110 Greenwich Street (roof level)	10/30/08	0.55	Mercury	EPA 324/1631	BRL	11/1/08	< 27.0	No	No	
TotalHg-ST13-10/30/08	0844043-08	Marriott Hotel, 38th Floor (roof level)	10/30/08	0.56	Mercury	EPA 324/1631	BRL	11/1/08	< 27.0	No	No	
TotalHg-ST14-10/30/08	0844043-09	West Face - South end at corner (scaffolding level)	10/30/08	0.59	Mercury	EPA 324/1631	BRL	11/1/08	< 25.0	No	No	
TotalHg-ST15-10/30/08	0844043-10	South Face - East end at corner (scaffolding level)	10/30/08	0.53	Mercury	EPA 324/1631	BRL	11/1/08	< 28.0	No	No	
TotalHg-ST16-10/30/08	0844043-11	East Face - North end at corner (scaffolding level)	10/30/08	0.60	Mercury	EPA 324/1631	BRL	11/1/08	< 25.0	No	No	
TotalHg-ST17-10/30/08	0844043-12	North Face - West end at corner (scaffolding level)	10/30/08	0.56	Mercury	EPA 324/1631	BRL	11/1/08	< 27.0	No	No	
TotalHg-ST1-10/31/08	0845001-01	Southwest Area (sidewalk bridge level)	10/31/08	0.58	Mercury	EPA 324/1631	BRL	11/3/08	< 26.0	No	No	
TotalHg-ST2-10/31/08	0845001-02	Southeast Area (sidewalk bridge level)	10/31/08	0.62	Mercury	EPA 324/1631	BRL	11/3/08	< 24.0	No	No	
TotalHg-ST4-10/31/08	0845001-03	Northwest Area (street-level)	10/31/08	0.54	Mercury	EPA 324/1631	BRL	11/3/08	< 28.0	No	No	
TotalHg-ST5-10/31/08	0845001-04	Firehouse #10 (roof level)	10/31/08	0.59	Mercury	EPA 324/1631	BRL	11/3/08	< 25.0	No	No	
TotalHg-ST10-10/31/08	0845001-05	North Side Sidewalk Bridge	10/31/08	0.56	Mercury	EPA 324/1631	BRL	11/3/08	< 27.0	No	No	
TotalHg-ST11-10/31/08	0845001-06	90 Trinity Place (roof level)	10/31/08	0.60	Mercury	EPA 324/1631	BRL	11/3/08	< 25.0	No	No	
TotalHg-ST12-10/31/08	0845001-07	110 Greenwich Street (roof level)	10/31/08	0.56	Mercury	EPA 324/1631	BRL	11/3/08	< 27.0	No	No	
TotalHg-ST13-10/31/08	0845001-08	Marriott Hotel, 38th Floor (roof level)	10/31/08	0.59	Mercury	EPA 324/1631	BRL	11/3/08	< 25.0	No	No	
TotalHg-ST14-10/31/08	0845001-09	West Face - South end at corner (scaffolding level)	10/31/08	0.56	Mercury	EPA 324/1631	BRL	11/3/08	< 27.0	No	No	
TotalHg-ST15-10/31/08	0845001-10	South Face - East end at corner (scaffolding level)	10/31/08	0.54	Mercury	EPA 324/1631	BRL	11/3/08	< 28.0	No	No	
TotalHg-ST16-10/31/08	0845001-11	East Face - North end at corner (scaffolding level)	10/31/08	0.53	Mercury	EPA 324/1631	BRL	11/3/08	< 28.0	No	No	
TotalHg-ST17-10/31/08	0845001-12	North Face - West end at corner (scaffolding level)	10/31/08	0.56	Mercury	EPA 324/1631	BRL	11/3/08	< 27.0	No	No	