

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Mercury (Total) Concentration (ng/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
Target Air Quality Levels									300			
EPA Site Specific Trigger Levels									3,000			
TotalHg-ST1-10/31/05	05BR1626-1	Southwest Area (street-level)	10/31/2005	0.57	Mercury	EPA 324/1631	BRL	11/2/2005	< 26.3	No	No	
TotalHg-ST2-10/31/05	05BR1626-2	Southeast Area (sidewalk bridge level)	10/31/2005	0.58	Mercury	EPA 324/1631	BRL	11/2/2005	< 25.9	No	No	
TotalHg-ST4-10/31/05	05BR1626-3	Northwest Area (street-level)	10/31/2005	0.57	Mercury	EPA 324/1631	BRL	11/2/2005	< 26.3	No	No	
TotalHg-ST5-10/31/05	05BR1626-4	Firehouse #10 (roof level)	10/31/2005	0.58	Mercury	EPA 324/1631	BRL	11/2/2005	< 25.9	No	No	
TotalHg-ST10-10/31/05	05BR1626-5	North Side Sidewalk Bridge	10/31/2005	0.57	Mercury	EPA 324/1631	BRL	11/2/2005	< 26.3	No	No	
TotalHg-ST11-10/31/05	05BR1626-6	90 Trinity Place (roof level)	10/31/2005	0.58	Mercury	EPA 324/1631	BRL	11/2/2005	< 25.9	No	No	
TotalHg-ST12-10/31/05	05BR1626-7	110 Greenwich Street (roof level)	10/31/2005	0.58	Mercury	EPA 324/1631	BRL	11/2/2005	< 25.9	No	No	
TotalHg-ST13-10/31/05	05BR1626-8	Marriott Hotel, 38th Floor (roof level)	10/31/2005	0.56	Mercury	EPA 324/1631	BRL	11/2/2005	< 26.8	No	No	
TotalHg-ST1-11/1/05	05BR1633-1	Southwest Area (street-level)	11/1/2005	0.57	Mercury	EPA 324/1631	BRL	11/3/2005	< 26.0	No	No	
TotalHg-ST2-11/1/05	05BR1633-2	Southeast Area (sidewalk bridge level)	11/1/2005	0.57	Mercury	EPA 324/1631	BRL	11/3/2005	< 26.0	No	No	
TotalHg-ST4-11/1/05	05BR1633-3	Northwest Area (street-level)	11/1/2005	0.59	Mercury	EPA 324/1631	BRL	11/3/2005	< 25.0	No	No	
TotalHg-ST5-11/1/05	05BR1633-4	Firehouse #10 (roof level)	11/1/2005	0.57	Mercury	EPA 324/1631	BRL	11/3/2005	< 26.0	No	No	
TotalHg-ST10-11/1/05	05BR1633-5	North Side Sidewalk Bridge	11/1/2005	0.57	Mercury	EPA 324/1631	BRL	11/3/2005	< 26.0	No	No	
TotalHg-ST11-11/1/05	05BR1633-6	90 Trinity Place (roof level)	11/1/2005	0.57	Mercury	EPA 324/1631	BRL	11/3/2005	< 26.0	No	No	
TotalHg-ST12-11/1/05	05BR1633-7	110 Greenwich Street (roof level)	11/1/2005	0.57	Mercury	EPA 324/1631	BRL	11/3/2005	< 26.0	No	No	
TotalHg-ST13-11/1/05	05BR1633-8	Marriott Hotel, 38th Floor (roof level)	11/1/2005	0.57	Mercury	EPA 324/1631	BRL	11/3/2005	< 26.0	No	No	
TotalHg-ST100-11/1/05	05BR1633-9	Station 10 Field Duplicate	11/1/2005	0.57	Mercury	EPA 324/1631	BRL	11/3/2005	< 26.0	No	No	
TotalHg-ST1-11/2/05	05BR1655-1	Southwest Area (street-level)	11/2/2005	0.57	Mercury	EPA 324/1631	BRL	11/4/2005	< 26.0	No	No	
TotalHg-ST2-11/2/05	05BR1655-2	Southeast Area (sidewalk bridge level)	11/2/2005	0.58	Mercury	EPA 324/1631	BRL	11/4/2005	< 26.0	No	No	
TotalHg-ST4-11/2/05	05BR1655-3	Northwest Area (street-level)	11/2/2005	0.56	Mercury	EPA 324/1631	BRL	11/4/2005	< 27.0	No	No	
TotalHg-ST5-11/2/05	05BR1655-4	Firehouse #10 (roof level)	11/2/2005	0.57	Mercury	EPA 324/1631	BRL	11/4/2005	< 26.0	No	No	
TotalHg-ST10-11/2/05	05BR1655-5	North Side Sidewalk Bridge	11/2/2005	0.58	Mercury	EPA 324/1631	BRL	11/4/2005	< 26.0	No	No	
TotalHg-ST11-11/2/05	05BR1655-6	90 Trinity Place (roof level)	11/2/2005	0.57	Mercury	EPA 324/1631	BRL	11/4/2005	< 26.0	No	No	
TotalHg-ST12-11/2/05	05BR1655-7	110 Greenwich Street (roof level)	11/2/2005	0.56	Mercury	EPA 324/1631	BRL	11/4/2005	< 26.0	No	No	
TotalHg-ST13-11/2/05	05BR1655-8	Marriott Hotel, 38th Floor (roof level)	11/2/2005	0.57	Mercury	EPA 324/1631	BRL	11/4/2005	< 27.0	No	No	
TotalHg-ST1-11/3/05	05BR1656-1	Southwest Area (street-level)	11/3/2005	0.57	Mercury	EPA 324/1631	BRL	11/5/2005	< 26.0	No	No	
TotalHg-ST2-11/3/05	05BR1656-2	Southeast Area (sidewalk bridge level)	11/3/2005	0.57	Mercury	EPA 324/1631	BRL	11/5/2005	< 26.0	No	No	
TotalHg-ST4-11/3/05	05BR1656-3	Northwest Area (street-level)	11/3/2005	0.57	Mercury	EPA 324/1631	BRL	11/5/2005	< 26.0	No	No	
TotalHg-ST5-11/3/05	05BR1656-4	Firehouse #10 (roof level)	11/3/2005	0.60	Mercury	EPA 324/1631	BRL	11/5/2005	< 25.0	No	No	
TotalHg-ST10-11/3/05	05BR1656-5	North Side Sidewalk Bridge	11/3/2005	0.57	Mercury	EPA 324/1631	BRL	11/5/2005	< 26.0	No	No	
TotalHg-ST11-11/3/05	05BR1656-6	90 Trinity Place (roof level)	11/3/2005	0.57	Mercury	EPA 324/1631	BRL	11/5/2005	< 26.0	No	No	
TotalHg-ST12-11/3/05	05BR1656-7	110 Greenwich Street (roof level)	11/3/2005	0.58	Mercury	EPA 324/1631	BRL	11/5/2005	< 26.0	No	No	
TotalHg-ST13-11/3/05	05BR1656-8	Marriott Hotel, 38th Floor (roof level)	11/3/2005	0.57	Mercury	EPA 324/1631	BRL	11/5/2005	< 26.0	No	No	