

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Mercury (Total) Concentration (ng/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
									300			
									3,000			
TotalHg-ST1-11/21/06	06BR1874-01	Southwest Area (sidewalk bridge level)	11/21/06	0.55	Mercury	EPA 324/1631	BRL	11/24/06	< 27.0	No	No	
TotalHg-ST2-11/21/06	06BR1874-02	Southeast Area (sidewalk bridge level)	11/21/06	0.56	Mercury	EPA 324/1631	BRL	11/24/06	< 27.0	No	No	
TotalHg-ST4-11/21/06	06BR1874-03	Northwest Area (street-level)	11/21/06	0.54	Mercury	EPA 324/1631	BRL	11/24/06	< 28.0	No	No	
TotalHg-ST5-11/21/06	06BR1874-04	Firehouse #10 (roof level)	11/21/06	0.56	Mercury	EPA 324/1631	BRL	11/24/06	< 27.0	No	No	
TotalHg-ST10-11/21/06	06BR1874-05	North Side Sidewalk Bridge	11/21/06	0.55	Mercury	EPA 324/1631	BRL	11/24/06	< 27.0	No	No	
TotalHg-ST11-11/21/06	06BR1874-06	90 Trinity Place (roof level)	11/21/06	0.58	Mercury	EPA 324/1631	BRL	11/24/06	< 26.0	No	No	
TotalHg-ST12-11/21/06	06BR1874-07	110 Greenwich Street (roof level)	11/21/06	0.58	Mercury	EPA 324/1631	BRL	11/24/06	< 26.0	No	No	
TotalHg-ST13-11/21/06	06BR1874-08	Marriott Hotel, 38th Floor (roof level)	11/21/06	0.60	Mercury	EPA 324/1631	BRL	11/24/06	< 25.0	No	No	
TotalHg-ST14-11/21/06	06BR1874-09	West Face - South end at corner (scaffolding level)	11/21/06	0.58	Mercury	EPA 324/1631	BRL	11/24/06	< 26.0	No	No	
TotalHg-ST15-11/21/06	06BR1874-10	South Face - East end at corner (scaffolding level)	11/21/06	0.57	Mercury	EPA 324/1631	BRL	11/24/06	< 26.0	No	No	
TotalHg-ST16-11/21/06	06BR1874-11	East Face - North end at corner (scaffolding level)	11/21/06	0.58	Mercury	EPA 324/1631	BRL	11/24/06	< 26.0	No	No	
TotalHg-ST17-11/21/06	06BR1874-12	North Face - West end at corner (scaffolding level)	11/21/06	0.59	Mercury	EPA 324/1631	BRL	11/24/06	< 25.0	No	No	
TotalHg-ST1-11/22/06	06BR1876-01	Southwest Area (sidewalk bridge level)	11/22/06	0.56	Mercury	EPA 324/1631	BRL	11/27/06	< 27.0	No	No	
TotalHg-ST2-11/22/06	06BR1876-02	Southeast Area (sidewalk bridge level)	11/22/06	0.57	Mercury	EPA 324/1631	BRL	11/27/06	< 26.0	No	No	
TotalHg-ST4-11/22/06	06BR1876-03	Northwest Area (street-level)	11/22/06	0.57	Mercury	EPA 324/1631	BRL	11/27/06	< 26.0	No	No	
TotalHg-ST5-11/22/06	06BR1876-04	Firehouse #10 (roof level)	11/22/06	0.60	Mercury	EPA 324/1631	BRL	11/27/06	< 25.0	No	No	
TotalHg-ST10-11/22/06	06BR1876-05	North Side Sidewalk Bridge	11/22/06	0.54	Mercury	EPA 324/1631	BRL	11/27/06	< 28.0	No	No	
TotalHg-ST11-11/22/06	06BR1876-06	90 Trinity Place (roof level)	11/22/06	0.60	Mercury	EPA 324/1631	BRL	11/27/06	< 25.0	No	No	
TotalHg-ST12-11/22/06	06BR1876-07	110 Greenwich Street (roof level)	11/22/06	0.55	Mercury	EPA 324/1631	BRL	11/27/06	< 27.0	No	No	
TotalHg-ST13-11/22/06	06BR1876-08	Marriott Hotel, 38th Floor (roof level)	11/22/06	0.54	Mercury	EPA 324/1631	BRL	11/27/06	< 28.0	No	No	
TotalHg-ST14-11/22/06	06BR1876-09	West Face - South end at corner (scaffolding level)	11/22/06	0.51	Mercury	EPA 324/1631	BRL	11/27/06	< 29.0	No	No	
TotalHg-ST15-11/22/06	06BR1876-10	South Face - East end at corner (scaffolding level)	11/22/06	0.51	Mercury	EPA 324/1631	BRL	11/27/06	< 29.0	No	No	
TotalHg-ST16-11/22/06	06BR1876-11	East Face - North end at corner (scaffolding level)	11/22/06	0.52	Mercury	EPA 324/1631	BRL	11/27/06	< 29.0	No	No	
TotalHg-ST17-11/22/06	06BR1876-12	North Face - West end at corner (scaffolding level)	11/22/06	0.52	Mercury	EPA 324/1631	BRL	11/27/06	< 29.0	No	No	
TotalHg-ST1-11/23/06	06BR1877-01	Southwest Area (sidewalk bridge level)	11/23/06	0.58	Mercury	EPA 324/1631	BRL	11/27/06	< 26.0	No	No	
TotalHg-ST2-11/23/06	06BR1877-02	Southeast Area (sidewalk bridge level)	11/23/06	0.58	Mercury	EPA 324/1631	BRL	11/27/06	< 26.0	No	No	
TotalHg-ST4-11/23/06	06BR1877-03	Northwest Area (street-level)	11/23/06	0.56	Mercury	EPA 324/1631	BRL	11/27/06	< 27.0	No	No	
TotalHg-ST5-11/23/06	06BR1877-04	Firehouse #10 (roof level)	11/23/06	0.56	Mercury	EPA 324/1631	BRL	11/27/06	< 27.0	No	No	
TotalHg-ST10-11/23/06	06BR1877-05	North Side Sidewalk Bridge	11/23/06	0.59	Mercury	EPA 324/1631	BRL	11/27/06	< 25.0	No	No	
TotalHg-ST11-11/23/06	06BR1877-06	90 Trinity Place (roof level)	11/23/06	0.55	Mercury	EPA 324/1631	BRL	11/27/06	< 27.0	No	No	
TotalHg-ST12-11/23/06	06BR1877-07	110 Greenwich Street (roof level)	11/23/06	0.52	Mercury	EPA 324/1631	BRL	11/27/06	< 29.0	No	No	
TotalHg-ST13-11/23/06	06BR1877-08	Marriott Hotel, 38th Floor (roof level)	11/23/06	0.53	Mercury	EPA 324/1631	BRL	11/27/06	< 28.0	No	No	
TotalHg-ST14-11/23/06	06BR1877-09	West Face - South end at corner (scaffolding level)	11/23/06	0.62	Mercury	EPA 324/1631	BRL	11/27/06	< 24.0	No	No	
TotalHg-ST15-11/23/06	06BR1877-10	South Face - East end at corner (scaffolding level)	11/23/06	0.60	Mercury	EPA 324/1631	BRL	11/27/06	< 25.0	No	No	
TotalHg-ST16-11/23/06	06BR1877-11	East Face - North end at corner (scaffolding level)	11/23/06	0.59	Mercury	EPA 324/1631	BRL	11/27/06	< 25.0	No	No	
TotalHg-ST17-11/23/06	06BR1877-12	North Face - West end at corner (scaffolding level)	11/23/06	0.59	Mercury	EPA 324/1631	BRL	11/27/06	< 25.0	No	No	