

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m <sup>3</sup> )	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Mercury (Total) Concentration (ng/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
									<b>300</b>			
<b>Target Air Quality Levels</b>												
<b>EPA Site Specific Trigger Levels</b>									<b>3,000</b>			
TotalHg-ST1-12/3/08	0849046-01	Southwest Area (sidewalk bridge level)	12/3/08	0.55	Mercury	EPA 324/1631	BRL	12/5/08	< 27.0	No	No	
TotalHg-ST2-12/3/08	0849046-02	Southeast Area (sidewalk bridge level)	12/3/08	0.53	Mercury	EPA 324/1631	BRL	12/5/08	< 28.0	No	No	
TotalHg-ST4-12/3/08	0849046-03	Northwest Area (street-level)	12/3/08	0.55	Mercury	EPA 324/1631	BRL	12/5/08	< 27.0	No	No	
TotalHg-ST5-12/3/08	0849046-04	Firehouse #10 (roof level)	12/3/08	0.56	Mercury	EPA 324/1631	BRL	12/5/08	< 27.0	No	No	
TotalHg-ST10-12/3/08	0849046-05	North Side Sidewalk Bridge	12/3/08	0.53	Mercury	EPA 324/1631	BRL	12/5/08	< 28.0	No	No	
TotalHg-ST11-12/3/08	0849046-06	90 Trinity Place (roof level)	12/3/08	0.53	Mercury	EPA 324/1631	BRL	12/5/08	< 28.0	No	No	
TotalHg-ST12-12/3/08	0849046-07	110 Greenwich Street (roof level)	12/3/08	0.54	Mercury	EPA 324/1631	BRL	12/5/08	< 28.0	No	No	
TotalHg-ST13-12/3/08	0849046-08	Marriott Hotel, 38th Floor (roof level)	12/3/08	0.56	Mercury	EPA 324/1631	BRL	12/5/08	< 27.0	No	No	
TotalHg-ST14-12/3/08	0849046-09	West Face - South end at corner (scaffolding level)	12/3/08	0.58	Mercury	EPA 324/1631	BRL	12/5/08	< 26.0	No	No	
TotalHg-ST15-12/3/08	0849046-10	South Face - East end at corner (scaffolding level)	12/3/08	0.54	Mercury	EPA 324/1631	BRL	12/5/08	< 28.0	No	No	
TotalHg-ST16-12/3/08	0849046-11	East Face - North end at corner (scaffolding level)	12/3/08	0.55	Mercury	EPA 324/1631	BRL	12/5/08	< 27.0	No	No	
TotalHg-ST17-12/3/08	0849046-12	North Face - West end at corner (scaffolding level)	12/3/08	0.59	Mercury	EPA 324/1631	BRL	12/5/08	< 25.0	No	No	
TotalHg-ST1-12/4/08	0849054-01	Southwest Area (sidewalk bridge level)	12/4/08	0.60	Mercury	EPA 324/1631	BRL	12/6/08	< 25.0	No	No	
TotalHg-ST2-12/4/08	0849054-02	Southeast Area (sidewalk bridge level)	12/4/08	0.63	Mercury	EPA 324/1631	BRL	12/6/08	< 24.0	No	No	
TotalHg-ST4-12/4/08	0849054-03	Northwest Area (street-level)	12/4/08	0.57	Mercury	EPA 324/1631	BRL	12/6/08	< 26.0	No	No	
TotalHg-ST5-12/4/08	0849054-04	Firehouse #10 (roof level)	12/4/08	0.59	Mercury	EPA 324/1631	BRL	12/6/08	< 25.0	No	No	
TotalHg-ST10-12/4/08	0849054-05	North Side Sidewalk Bridge	12/4/08	0.57	Mercury	EPA 324/1631	BRL	12/6/08	< 26.0	No	No	
TotalHg-ST11-12/4/08	0849054-06	90 Trinity Place (roof level)	12/4/08	0.56	Mercury	EPA 324/1631	BRL	12/6/08	< 27.0	No	No	
TotalHg-ST12-12/4/08	0849054-07	110 Greenwich Street (roof level)	12/4/08	0.55	Mercury	EPA 324/1631	BRL	12/6/08	< 27.0	No	No	
TotalHg-ST13-12/4/08	0849054-08	Marriott Hotel, 38th Floor (roof level)	12/4/08	0.57	Mercury	EPA 324/1631	BRL	12/6/08	< 32.0	No	No	
TotalHg-ST14-12/4/08	0849054-09	West Face - South end at corner (scaffolding level)	12/4/08	0.61	Mercury	EPA 324/1631	BRL	12/6/08	< 25.0	No	No	
TotalHg-ST15-12/4/08	0849054-10	South Face - East end at corner (scaffolding level)	12/4/08	0.56	Mercury	EPA 324/1631	BRL	12/6/08	< 27.0	No	No	
TotalHg-ST16-12/4/08	0849054-11	East Face - North end at corner (scaffolding level)	12/4/08	0.54	Mercury	EPA 324/1631	BRL	12/6/08	< 28.0	No	No	
TotalHg-ST17-12/4/08	0849054-12	North Face - West end at corner (scaffolding level)	12/4/08	0.54	Mercury	EPA 324/1631	BRL	12/6/08	< 28.0	No	No	
TotalHg-ST1-12/5/08	0850001-01	Southwest Area (sidewalk bridge level)	12/5/08	0.55	Mercury	EPA 324/1631	BRL	12/8/08	< 27.0	No	No	
TotalHg-ST2-12/5/08	0850001-02	Southeast Area (sidewalk bridge level)	12/5/08	0.58	Mercury	EPA 324/1631	BRL	12/8/08	< 26.0	No	No	
TotalHg-ST4-12/5/08	0850001-03	Northwest Area (street-level)	12/5/08	0.53	Mercury	EPA 324/1631	BRL	12/8/08	< 28.0	No	No	
TotalHg-ST5-12/5/08	0850001-04	Firehouse #10 (roof level)	12/5/08	0.55	Mercury	EPA 324/1631	BRL	12/8/08	< 27.0	No	No	
TotalHg-ST10-12/5/08	0850001-05	North Side Sidewalk Bridge	12/5/08	0.56	Mercury	EPA 324/1631	BRL	12/8/08	< 27.0	No	No	
TotalHg-ST11-12/5/08	0850001-06	90 Trinity Place (roof level)	12/5/08	0.54	Mercury	EPA 324/1631	BRL	12/8/08	< 28.0	No	No	
TotalHg-ST12-12/5/08	0850001-07	110 Greenwich Street (roof level)	12/5/08	0.57	Mercury	EPA 324/1631	BRL	12/8/08	< 26.0	No	No	
TotalHg-ST13-12/5/08	0850001-08	Marriott Hotel, 38th Floor (roof level)	12/5/08	0.57	Mercury	EPA 324/1631	BRL	12/8/08	< 26.0	No	No	
TotalHg-ST14-12/5/08	0850001-09	West Face - South end at corner (scaffolding level)	12/5/08	0.55	Mercury	EPA 324/1631	BRL	12/8/08	< 27.0	No	No	
TotalHg-ST15-12/5/08	0850001-10	South Face - East end at corner (scaffolding level)	12/5/08	0.52	Mercury	EPA 324/1631	BRL	12/8/08	< 29.0	No	No	
TotalHg-ST16-12/5/08	0850001-11	East Face - North end at corner (scaffolding level)	12/5/08	0.54	Mercury	EPA 324/1631	BRL	12/8/08	< 28.0	No	No	
TotalHg-ST17-12/5/08	0850001-12	North Face - West end at corner (scaffolding level)	12/5/08	0.54	Mercury	EPA 324/1631	BRL	12/8/08	< 28.0	No	No	