

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Mercury (Total) Concentration (ng/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
									300			
									3,000			
TotalHg-ST1-12/5/05	05BR1840-1	Southwest Area (sidewalk bridge level)	12/5/05	0.59	Mercury	EPA 324/1631	BRL	12/7/05	< 25.0	No	No	
TotalHg-ST2-12/5/05	05BR1840-2	Southeast Area (sidewalk bridge level)	12/5/05	0.60	Mercury	EPA 324/1631	BRL	12/7/05	< 25.0	No	No	
TotalHg-ST4-12/5/05	05BR1840-3	Northwest Area (street-level)	12/5/05	0.57	Mercury	EPA 324/1631	BRL	12/7/05	< 26.0	No	No	
TotalHg-ST5-12/5/05	05BR1840-4	Firehouse #10 (roof level)	12/5/05	0.57	Mercury	EPA 324/1631	BRL	12/7/05	< 26.0	No	No	
TotalHg-ST10-12/5/05	05BR1840-5	North Side Sidewalk Bridge	12/5/05	0.60	Mercury	EPA 324/1631	BRL	12/7/05	< 25.0	No	No	
TotalHg-ST11-12/5/05	05BR1840-6	90 Trinity Place (roof level)	12/5/05	0.57	Mercury	EPA 324/1631	BRL	12/7/05	< 26.0	No	No	
TotalHg-ST12-12/5/05	05BR1840-7	110 Greenwich Street (roof level)	12/5/05	0.57	Mercury	EPA 324/1631	BRL	12/7/05	< 26.0	No	No	
TotalHg-ST13-12/5/05	05BR1840-8	Marriott Hotel, 38th Floor (roof level)	12/5/05	0.57	Mercury	EPA 324/1631	BRL	12/7/05	< 26.0	No	No	
TotalHg-ST14-12/5/05	05BR1840-9	West Face - South end at corner (scaffolding level)	12/5/05	0.58	Mercury	EPA 324/1631	BRL	12/7/05	< 26.0	No	No	
TotalHg-ST15-12/5/05	05BR1840-10	South Face - East end at corner (scaffolding level)	12/5/05	0.57	Mercury	EPA 324/1631	BRL	12/7/05	< 26.0	No	No	
TotalHg-ST16-12/5/05	05BR1840-11	East Face - North end at corner (scaffolding level)	12/5/05	0.59	Mercury	EPA 324/1631	BRL	12/7/05	< 25.0	No	No	
TotalHg-ST17-12/5/05	05BR1840-12	North Face - West end at corner (scaffolding level)	12/5/05	0.59	Mercury	EPA 324/1631	BRL	12/7/05	< 25.0	No	No	
TotalHg-ST1-12/6/05	05BR1846-1	Southwest Area (sidewalk bridge level)	12/6/05	0.56	Mercury	EPA 324/1631	BRL	12/8/05	< 27.0	No	No	
TotalHg-ST2-12/6/05	05BR1846-2	Southeast Area (sidewalk bridge level)	12/6/05	0.56	Mercury	EPA 324/1631	BRL	12/8/05	< 27.0	No	No	
TotalHg-ST4-12/6/05	05BR1846-3	Northwest Area (street-level)	12/6/05	0.52	Mercury	EPA 324/1631	BRL	12/8/05	< 29.0	No	No	
TotalHg-ST5-12/6/05	05BR1846-4	Firehouse #10 (roof level)	12/6/05	0.58	Mercury	EPA 324/1631	BRL	12/8/05	< 26.0	No	No	
TotalHg-ST10-12/6/05	05BR1846-5	North Side Sidewalk Bridge	12/6/05	0.54	Mercury	EPA 324/1631	BRL	12/8/05	< 28.0	No	No	
TotalHg-ST100-12/6/05	05BR1846-13	Station 10 Field Duplicate	12/6/05	0.55	Mercury	EPA 324/1631	BRL	12/8/05	< 27.0	No	No	
TotalHg-ST11-12/6/05	05BR1846-6	90 Trinity Place (roof level)	12/6/05	0.57	Mercury	EPA 324/1631	BRL	12/8/05	< 26.0	No	No	
TotalHg-ST12-12/6/05	05BR1846-7	110 Greenwich Street (roof level)	12/6/05	0.58	Mercury	EPA 324/1631	BRL	12/8/05	< 26.0	No	No	
TotalHg-ST13-12/6/05	05BR1846-8	Marriott Hotel, 38th Floor (roof level)	12/6/05	0.58	Mercury	EPA 324/1631	BRL	12/8/05	< 26.0	No	No	
TotalHg-ST14-12/6/05	05BR1846-9	West Face - South end at corner (scaffolding level)	12/6/05	0.54	Mercury	EPA 324/1631	BRL	12/8/05	< 28.0	No	No	
TotalHg-ST15-12/6/05	05BR1846-10	South Face - East end at corner (scaffolding level)	12/6/05	0.54	Mercury	EPA 324/1631	BRL	12/8/05	< 28.0	No	No	
TotalHg-ST16-12/6/05	05BR1846-11	East Face - North end at corner (scaffolding level)	12/6/05	0.54	Mercury	EPA 324/1631	BRL	12/8/05	< 28.0	No	No	
TotalHg-ST17-12/6/05	05BR1846-12	North Face - West end at corner (scaffolding level)	12/6/05	0.55	Mercury	EPA 324/1631	BRL	12/8/05	< 27.0	No	No	