

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Mercury (Total) Concentration (ng/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
									300			
									3,000			
TotalHg-ST1-12/14/05	05BR1889-1	Southwest Area (sidewalk bridge level)	12/14/05	0.56	Mercury	EPA 324/1631	BRL	12/16/05	< 27.0	No	No	
TotalHg-ST2-12/14/05	05BR1889-2	Southeast Area (sidewalk bridge level)	12/14/05	0.57	Mercury	EPA 324/1631	BRL	12/16/05	< 26.0	No	No	
TotalHg-ST4-12/14/05	05BR1889-3	Northwest Area (street-level)	12/14/05	0.56	Mercury	EPA 324/1631	BRL	12/16/05	< 27.0	No	No	
TotalHg-ST5-12/14/05	05BR1889-4	Firehouse #10 (roof level)	12/14/05	0.56	Mercury	EPA 324/1631	BRL	12/16/05	< 27.0	No	No	
TotalHg-ST10-12/14/05	05BR1889-5	North Side Sidewalk Bridge	12/14/05	0.57	Mercury	EPA 324/1631	BRL	12/16/05	< 26.0	No	No	
TotalHg-ST11-12/14/05	05BR1889-6	90 Trinity Place (roof level)	12/14/05	0.52	Mercury	EPA 324/1631	BRL	12/16/05	< 29.0	No	No	
TotalHg-ST12-12/14/05	05BR1889-7	110 Greenwich Street (roof level)	12/14/05	0.53	Mercury	EPA 324/1631	BRL	12/16/05	< 28.0	No	No	
TotalHg-ST13-12/14/05	05BR1889-8	Marriott Hotel, 38th Floor (roof level)	12/14/05	0.55	Mercury	EPA 324/1631	BRL	12/16/05	< 27.0	No	No	
TotalHg-ST14-12/14/05	05BR1889-9	West Face - South end at corner (scaffolding level)	12/14/05	0.58	Mercury	EPA 324/1631	BRL	12/16/05	< 26.0	No	No	
TotalHg-ST15-12/14/05	05BR1889-10	South Face - East end at corner (scaffolding level)	12/14/05	0.58	Mercury	EPA 324/1631	BRL	12/16/05	< 26.0	No	No	
TotalHg-ST16-12/14/05	05BR1889-11	East Face - North end at corner (scaffolding level)	12/14/05	0.66	Mercury	EPA 324/1631	BRL	12/16/05	< 23.0	No	No	
TotalHg-ST17-12/14/05	05BR1889-12	North Face - West end at corner (scaffolding level)	12/14/05	0.58	Mercury	EPA 324/1631	BRL	12/16/05	< 26.0	No	No	
TotalHg-ST1-12/15/05	05BR1898-1	Southwest Area (sidewalk bridge level)	12/15/05	0.57	Mercury	EPA 324/1631	BRL	12/17/05	< 26.0	No	No	
TotalHg-ST2-12/15/05	05BR1898-2	Southeast Area (sidewalk bridge level)	12/15/05	0.57	Mercury	EPA 324/1631	BRL	12/17/05	< 26.0	No	No	
TotalHg-ST4-12/15/05	05BR1898-3	Northwest Area (street-level)	12/15/05	0.57	Mercury	EPA 324/1631	BRL	12/17/05	< 26.0	No	No	
TotalHg-ST5-12/15/05	05BR1898-4	Firehouse #10 (roof level)	12/15/05	0.58	Mercury	EPA 324/1631	BRL	12/17/05	< 26.0	No	No	
TotalHg-ST10-12/15/05	05BR1898-5	North Side Sidewalk Bridge	12/15/05	0.57	Mercury	EPA 324/1631	BRL	12/17/05	< 26.0	No	No	
TotalHg-ST12-12/15/05	05BR1898-6	110 Greenwich Street (roof level)	12/15/05	0.56	Mercury	EPA 324/1631	BRL	12/17/05	< 27.0	No	No	
TotalHg-ST13-12/15/05	05BR1898-7	Marriott Hotel, 38th Floor (roof level)	12/15/05	0.58	Mercury	EPA 324/1631	BRL	12/17/05	< 26.0	No	No	
TotalHg-ST14-12/15/05	05BR1898-8	West Face - South end at corner (scaffolding level)	12/15/05	0.57	Mercury	EPA 324/1631	BRL	12/17/05	< 26.0	No	No	
TotalHg-ST15-12/15/05	05BR1898-9	South Face - East end at corner (scaffolding level)	12/15/05	0.57	Mercury	EPA 324/1631	BRL	12/17/05	< 26.0	No	No	
TotalHg-ST16-12/15/05	05BR1898-10	East Face - North end at corner (scaffolding level)	12/15/05	0.57	Mercury	EPA 324/1631	BRL	12/17/05	< 26.0	No	No	
TotalHg-ST17-12/15/05	05BR1898-11	North Face - West end at corner (scaffolding level)	12/15/05	0.57	Mercury	EPA 324/1631	BRL	12/17/05	< 26.0	No	No	

Note:

1. Mercury sample at Station 11 (90 Trinity Place [roof level]) on December 15, 2005 was not available for analysis on account of pump failure.