

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Antimony Concentration (ng/m ³)	Barium Concentration (ng/m ³)	Beryllium Concentration (ng/m ³)	Cadmium Concentration (ng/m ³)	Chromium (Total) Concentration (ng/m ³)	Copper Concentration (ng/m ³)	Lead Concentration (ng/m ³)	Manganese Concentration (ng/m ³)	Nickel Concentration (ng/m ³)	Zinc Concentration (ng/m ³)	Exceeds Target	Exceeds EPA	Comments
Target Air Quality Levels									5,000	5,000	20	40	600	10,000	1,500	500	200	16,000	Air Quality	Site Specific	
EPA Site Specific Trigger Levels									14,000	5,000	200	2,000	600	100,000	5,000	500	28,000	160,000	Levels	Trigger Levels	Comments
METALS-ST1-5/15/10	G0E180452001	Southwest Area (sidewalk bridge level)	5/15/10	1775.2	Metals	6020	TestAmerica-SAC	5/18/10	1.4	< 67.6	< 0.66	< 0.66	< 6.6	79.0	5.8	11.4	< 3.4	43.7	No	No	
METALS-ST2-5/15/10	G0E180452002	Southwest Area (sidewalk bridge level)	5/15/10	1813.6	Metals	6020	TestAmerica-SAC	5/18/10	1.5	< 66.2	< 0.66	< 0.66	< 6.6	80.4	5.5	16.1	< 3.3	45.3	No	No	
METALS-ST4-5/15/10	G0E180452003	Northwest Area (street-level)	5/15/10	1824.6	Metals	6020	TestAmerica-SAC	5/18/10	1.3	< 65.8	< 0.66	< 0.66	< 6.6	60.3	5.7	13.8	< 3.3	39.0	No	No	
METALS-ST5-5/15/10	G0E180452004	Firehouse #10 (roof level)	5/15/10	1834.5	Metals	6020	TestAmerica-SAC	5/18/10	< 1.3	< 65.4	< 0.65	< 0.65	< 6.5	40.2	7.2	21.9	< 3.3	54.3	No	No	
METALS-ST11-5/15/10	G0E180452006	90 Trinity Place (roof level)	5/15/10	1773.4	Metals	6020	TestAmerica-SAC	5/18/10	< 1.4	< 67.7	< 0.66	< 0.66	< 6.8	24.7	4.1	9.8	< 3.4	30.0	No	No	
METALS-ST12-5/15/10	G0E180452007	110 Greenwich Street (roof level)	5/15/10	1792.2	Metals	6020	TestAmerica-SAC	5/18/10	< 1.3	< 67.0	< 0.67	< 0.67	< 6.7	42.0	5.8	10.7	< 3.3	33.7	No	No	
METALS-ST20-5/15/10	G0E180452005	Northwest Area, Sidewalk Bridgt	5/15/10	1806.7	Metals	6020	TestAmerica-SAC	5/18/10	< 1.3	< 66.4	< 0.66	< 0.66	< 6.6	46.7	6.4	19.6	< 3.3	47.9	No	No	
METALS-ST21-5/15/10	G0E180452008	Mariott Hotel, 4th Floor	5/15/10	1830.2	Metals	6020	TestAmerica-SAC	5/18/10	< 1.3	< 65.6	< 0.66	< 0.66	< 6.6	132	6.1	11.9	< 3.3	34.6	No	No	
METALS-ST1-5/16/10	G0E180455001	Southwest Area (sidewalk bridge level)	5/16/10	1851.2	Metals	6020	TestAmerica-SAC	5/18/10	3.0	< 64.8	< 0.65	< 0.65	< 6.5	71.3	17.9	39.4	4.6	114	No	No	
METALS-ST2-5/16/10	G0E180455002	Southwest Area (sidewalk bridge level)	5/16/10	1869.7	Metals	6020	TestAmerica-SAC	5/18/10	3.1	< 64.2	< 0.64	< 0.64	< 6.4	102	19.5	31.7	4.1	111	No	No	
METALS-ST4-5/16/10	G0E180455003	Northwest Area (street-level)	5/16/10	1903.4	Metals	6020	TestAmerica-SAC	5/18/10	3.0	< 63.0	< 0.63	< 0.63	< 6.3	62.0	20.1	40.9	5.0	161	No	No	
METALS-ST5-5/16/10	G0E180455004	Firehouse #10 (roof level)	5/16/10	1828.8	Metals	6020	TestAmerica-SAC	5/18/10	2.4	< 65.6	< 0.66	< 0.66	< 6.6	39.6	7.4	28.0	4.0	106	No	No	
METALS-ST11-5/16/10	G0E180455006	90 Trinity Place (roof level)	5/16/10	1774.6	Metals	6020	TestAmerica-SAC	5/18/10	2.0	< 67.6	< 0.66	< 0.66	< 6.8	40.3	4.9	14.9	3.4	56.5	No	No	
METALS-ST12-5/16/10	G0E180455007	110 Greenwich Street (roof level)	5/16/10	1781.1	Metals	6020	TestAmerica-SAC	5/18/10	2.1	< 67.4	< 0.67	< 0.67	< 6.7	37.8	5.2	16.9	< 3.4	52.9	No	No	
METALS-ST20-5/16/10	G0E180455005	Northwest Area, Sidewalk Bridgt	5/16/10	1866.9	Metals	6020	TestAmerica-SAC	5/18/10	3.1	< 64.3	< 0.64	< 0.64	7.5	69.2	21.0	73.3	6.7	303	No	No	
METALS-ST21-5/16/10	G0E180455008	Mariott Hotel, 4th Floor	5/16/10	1827.3	Metals	6020	TestAmerica-SAC	5/18/10	2.9	< 65.7	< 0.66	< 0.66	< 6.6	109	7.0	15.7	< 3.3	57.3	No	No	