

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Antimony Concentration (ng/m ³)	Barium Concentration (ng/m ³)	Beryllium Concentration (ng/m ³)	Cadmium Concentration (ng/m ³)	Chromium (Total) Concentration (ng/m ³)	Copper Concentration (ng/m ³)	Lead Concentration (ng/m ³)	Manganese Concentration (ng/m ³)	Nickel Concentration (ng/m ³)	Zinc Concentration (ng/m ³)	Exceeds Target Air Quality	Exceeds EPA Site Specific Trigger Levels	Comments
									5,000	5,000	200	40	600	10,000	1,500	500	200	16,000			
									14,000	5,000	200	2,000	600	100,000	5,000	500	28,000	160,000			
METALS-ST11-6/13/09	G9F160118001	Southwest Area (sidewalk bridge leve	6/13/09	1786.3	Metals	6020	STL-SAC	6/16/09	4.4	179	< 0.67	< 0.67	< 6.7	78.5	23.3	16.4	4.7	51.6	No	No	
METALS-ST2-6/13/09	G9F160118002	Southeast Area (sidewalk bridge leve	6/13/09	1760.5	Metals	6020	STL-SAC	6/16/09	4.6	184	< 0.68	< 0.68	< 6.8	91.7	22.4	24.6	5.0	67.5	No	No	
METALS-ST4-6/13/09	G9F160118003	Northwest Area (street-level	6/13/09	1772.2	Metals	6020	STL-SAC	6/16/09	4.0	186	< 0.68	< 0.68	< 6.8	97.0	23.6	18.4	4.5	46.4	No	No	
METALS-ST5-6/13/09	G9F160118004	Firehouse #10 (roof level	6/13/09	1784.7	Metals	6020	STL-SAC	6/16/09	3.9	181	< 0.67	< 0.67	< 6.7	89.3	20.0	21.7	5.2	40.4	No	No	
METALS-ST10-6/13/09	G9F160118005	North Side Sidewalk Bridg	6/13/09	1765	Metals	6020	STL-SAC	6/16/09	4.0	196	< 0.68	< 0.68	< 6.8	78.0	21.6	21.6	5.2	42.2	No	No	
METALS-ST11-6/13/09	G9F160118006	90 Trinity Place (roof level	6/13/09	1760.1	Metals	6020	STL-SAC	6/16/09	4.2	174	< 0.68	< 0.68	< 6.8	78.7	19.8	12.8	4.5	35.2	No	No	
METALS-ST12-6/13/09	G9F160118007	110 Greenwich Street (roof level	6/13/09	1765.8	Metals	6020	STL-SAC	6/16/09	4.1	194	< 0.68	< 0.68	< 6.8	77.4	23.1	11.9	3.9	35.3	No	No	
METALS-ST13-6/13/09	G9F160118008	Mariott Hotel, 38th Floor (roof leve	6/13/09	1784.5	Metals	6020	STL-SAC	6/16/09	3.8	173	< 0.68	< 0.68	< 6.8	120	19.2	10.3	3.9	28.5	No	No	
METALS-ST1-6/14/09	G9F160119001	Southwest Area (sidewalk bridge leve	6/14/09	1786.4	Metals	6020	STL-SAC	6/16/09	4.5	146	< 0.67	< 0.67	< 6.7	44.9	5.6	20.9	9.7	87.3	No	No	
METALS-ST2-6/14/09	G9F160119002	Southeast Area (sidewalk bridge leve	6/14/09	1815.1	Metals	6020	STL-SAC	6/16/09	4.4	99.2	< 0.66	< 0.66	< 6.6	59.7	6.0	23.7	9.1	79.9	No	No	
METALS-ST4-6/14/09	G9F160119003	Northwest Area (street-level	6/14/09	1864.3	Metals	6020	STL-SAC	6/16/09	4.2	156	< 0.64	< 0.64	< 6.4	70.1	5.0	21.0	9.7	93.0	No	No	
METALS-ST5-6/14/09	G9F160119004	Firehouse #10 (roof level	6/14/09	1769.4	Metals	6020	STL-SAC	6/16/09	4.5	118	< 0.68	< 0.68	< 6.8	64.2	6.1	22.6	10.3	101	No	No	
METALS-ST10-6/14/09	G9F160119005	North Side Sidewalk Bridg	6/14/09	1885.4	Metals	6020	STL-SAC	6/16/09	4.5	177	< 0.64	< 0.64	< 6.4	51.7	5.3	30.7	10.9	150	No	No	
METALS-ST11-6/14/09	G9F160119006	90 Trinity Place (roof level	6/14/09	1763	Metals	6020	STL-SAC	6/16/09	3.8	< 68.1	< 0.68	< 0.68	< 6.8	34.3	3.9	7.5	6.9	38.9	No	No	
METALS-ST12-6/14/09	G9F160119007	110 Greenwich Street (roof level	6/14/09	1788.3	Metals	6020	STL-SAC	6/16/09	3.8	< 67.1	< 0.67	< 0.67	< 6.7	26.0	4.1	9.0	7.3	47.4	No	No	
METALS-ST13-6/14/09	G9F160119008	Mariott Hotel, 38th Floor (roof leve	6/14/09	1772.7	Metals	6020	STL-SAC	6/16/09	3.9	< 67.7	< 0.68	< 0.68	< 6.8	87.0	3.8	7.6	7.7	41.0	No	No	