

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m <sup>3</sup> )	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Antimony Concentration (ng/m <sup>3</sup> )	Barium Concentration (ng/m <sup>3</sup> )	Beryllium Concentration (ng/m <sup>3</sup> )	Cadmium Concentration (ng/m <sup>3</sup> )	Chromium (Total) Concentration (ng/m <sup>3</sup> )	Copper Concentration (ng/m <sup>3</sup> )	Lead Concentration (ng/m <sup>3</sup> )	Manganese Concentration (ng/m <sup>3</sup> )	Nickel Concentration (ng/m <sup>3</sup> )	Zinc Concentration (ng/m <sup>3</sup> )	Exceeds Target Air Quality	Exceeds EPA Site Specific Trigger Levels	Comments
									5,000	5,000	200	40	600	10,000	1,500	500	200	16,000			
									14,000	5,000	200	2,000	600	100,000	5,000	500	28,000	160,000			
METALS-ST11-6/27/09	G9F300179001	Southwest Area (sidewalk bridge leve	6/27/09	1783.5	Metals	6020	STL-SAC	6/30/09	2.3	< 67.3	< 0.67	< 0.67	< 6.7	42.7	10.1	15.4	3.5	102	No	No	
METALS-ST2-6/27/09	G9F300179002	Southeast Area (sidewalk bridge leve	6/27/09	1760.7	Metals	6020	STL-SAC	6/30/09	2.6	< 68.2	< 0.68	< 0.68	< 6.8	156	7.7	18.7	3.9	93.0	No	No	
METALS-ST4-6/27/09	G9F300179003	Northwest Area (street-level	6/27/09	1787	Metals	6020	STL-SAC	6/30/09	2.0	< 67.2	< 0.67	< 0.67	< 6.7	65.9	8.9	16.0	3.4	106	No	No	
METALS-ST5-6/27/09	G9F300179004	Firehouse #10 (roof level	6/27/09	1757	Metals	6020	STL-SAC	6/30/09	1.9	< 68.3	< 0.68	< 0.68	< 6.8	54.6	5.0	18.2	4.2	137	No	No	
METALS-ST10-6/27/09	G9F300179005	North Side Sidewalk Bridg	6/27/09	1782.7	Metals	6020	STL-SAC	6/30/09	1.9	< 67.3	< 0.67	< 0.67	< 6.7	51.6	5.7	19.8	4.1	176	No	No	
METALS-ST11-6/27/09	G9F300179006	90 Trinity Place (roof level	6/27/09	1762.4	Metals	6020	STL-SAC	6/30/09	1.6	< 68.1	< 0.68	< 0.68	< 6.8	59.7	4.2	10.2	< 3.4	85.8	No	No	
METALS-ST12-6/27/09	G9F300179007	110 Greenwich Street (roof level	6/27/09	1768.4	Metals	6020	STL-SAC	6/30/09	1.6	< 67.8	< 0.68	< 0.68	< 6.8	84.4	4.4	9.1	< 3.4	56.7	No	No	
METALS-ST13-6/27/09	G9F300179008	Mariott Hotel, 38th Floor (roof leve	6/27/09	1751.9	Metals	6020	STL-SAC	6/30/09	1.4	< 68.1	< 0.68	< 0.68	< 6.8	71.0	4.3	6.5	< 3.4	34.5	No	No	
METALS-ST1-6/28/09	G9F300181001	Southwest Area (sidewalk bridge leve	6/28/09	1810	Metals	6020	STL-SAC	6/30/09	2.6	< 66.3	< 0.66	< 0.66	< 6.6	54.5	8.4	11.6	7.1	47.6	No	No	
METALS-ST2-6/28/09	G9F300181002	Southeast Area (sidewalk bridge leve	6/28/09	1805.3	Metals	6020	STL-SAC	6/30/09	2.7	< 66.5	< 0.66	< 0.66	< 6.6	142	8.1	18.0	7.3	57.2	No	No	
METALS-ST4-6/28/09	G9F300181003	Northwest Area (street-level	6/28/09	1836	Metals	6020	STL-SAC	6/30/09	2.5	< 65.4	< 0.65	< 0.65	< 6.5	127	11.0	15.2	7.6	61.2	No	No	
METALS-ST5-6/28/09	G9F300181004	Firehouse #10 (roof level	6/28/09	1780.2	Metals	6020	STL-SAC	6/30/09	2.7	< 67.4	< 0.67	< 0.67	< 6.7	71.9	6.1	23.6	8.6	57.0	No	No	
METALS-ST10-6/28/09	G9F300181005	North Side Sidewalk Bridg	6/28/09	1838.4	Metals	6020	STL-SAC	6/30/09	2.5	120	< 0.65	< 0.65	< 6.5	51.1	6.1	32.6	8.5	33.2	No	No	
METALS-ST11-6/28/09	G9F300181006	90 Trinity Place (roof level	6/28/09	1767.9	Metals	6020	STL-SAC	6/30/09	2.4	< 67.9	< 0.68	< 0.68	< 6.8	63.4	4.9	6.9	6.6	26.8	No	No	
METALS-ST12-6/28/09	G9F300181007	110 Greenwich Street (roof level	6/28/09	1786	Metals	6020	STL-SAC	6/30/09	2.5	< 67.2	< 0.67	< 0.67	< 6.7	59.6	4.9	6.8	6.9	27.2	No	No	
METALS-ST13-6/28/09	G9F300181008	Mariott Hotel, 38th Floor (roof leve	6/28/09	1776.2	Metals	6020	STL-SAC	6/30/09	2.4	< 67.6	< 0.68	0.74	< 6.8	157	4.5	5.9	6.9	24.1	No	No	