

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
										0.0009			
										NA			
ASBESTOS-ST1-1/2/09	030900170-0001	Southwest Area (sidewalk bridge level)	1/2/09	1	3.050	Asbestos	PCME	EMSL	1/3/09	< 0.00081	No	No	
ASBESTOS-ST2-1/2/09	030900170-0002	Southeast Area (sidewalk bridge level)	1/2/09	1	3.090	Asbestos	PCME	EMSL	1/3/09	< 0.00080	No	No	
ASBESTOS-ST4-1/2/09	030900170-0003	Northwest Area (street-level)	1/2/09	1	3.010	Asbestos	PCME	EMSL	1/3/09	< 0.00082	No	No	
ASBESTOS-ST5-1/2/09	030900170-0004	Firehouse #10 (roof level)	1/2/09	1	3.140	Asbestos	PCME	EMSL	1/3/09	< 0.00079	No	No	
ASBESTOS-ST10-1/2/09	030900170-0005	North Side Sidewalk Bridge	1/2/09	1	3.080	Asbestos	PCME	EMSL	1/3/09	< 0.00080	No	No	
ASBESTOS-ST11-1/2/09	030900170-0006	90 Trinity Place (roof level)	1/2/09	1	3.010	Asbestos	PCME	EMSL	1/3/09	< 0.00082	No	No	
ASBESTOS-ST12-1/2/09	030900170-0007	110 Greenwich Street (roof level)	1/2/09	1	3.050	Asbestos	PCME	EMSL	1/3/09	< 0.00081	No	No	
ASBESTOS-ST13-1/2/09	030900170-0008	Marriott Hotel, 38th Floor (roof level)	1/2/09	1	3.020	Asbestos	PCME	EMSL	1/3/09	< 0.00082	No	No	
ASBESTOS-ST14-1/2/09	030900170-0009	West Face - South end at corner (scaffolding level)	1/2/09	1	2.900	Asbestos	PCME	EMSL	1/3/09	< 0.00085	No	No	
ASBESTOS-ST15-1/2/09	030900170-0010	South Face - East end at corner (scaffolding level)	1/2/09	1	2.910	Asbestos	PCME	EMSL	1/3/09	< 0.00085	No	No	
ASBESTOS-ST16-1/2/09	030900170-0011	East Face - North end at corner (scaffolding level)	1/2/09	1	2.880	Asbestos	PCME	EMSL	1/3/09	< 0.00086	No	No	
ASBESTOS-ST17-1/2/09	030900170-0012	North Face - West end at corner (scaffolding level)	1/2/09	1	2.850	Asbestos	PCME	EMSL	1/3/09	< 0.00087	No	No	
ASBESTOS-ST1-1/3/09	030900309-0001	Southwest Area (sidewalk bridge level)	1/3/09	1	3.000	Asbestos	PCME	EMSL	1/5/09	< 0.00082	No	No	
ASBESTOS-ST2-1/3/09	030900309-0002	Southeast Area (sidewalk bridge level)	1/3/09	1	3.030	Asbestos	PCME	EMSL	1/5/09	< 0.00081	No	No	
ASBESTOS-ST4-1/3/09	030900309-0003	Northwest Area (street-level)	1/3/09	1	3.020	Asbestos	PCME	EMSL	1/5/09	< 0.00082	No	No	
ASBESTOS-ST5-1/3/09	030900309-0004	Firehouse #10 (roof level)	1/3/09	1	3.000	Asbestos	PCME	EMSL	1/5/09	< 0.00082	No	No	
ASBESTOS-ST10-1/3/09	030900309-0005	North Side Sidewalk Bridge	1/3/09	1	3.000	Asbestos	PCME	EMSL	1/5/09	< 0.00082	No	No	
ASBESTOS-ST11-1/3/09	030900309-0006	90 Trinity Place (roof level)	1/3/09	1	2.970	Asbestos	PCME	EMSL	1/5/09	< 0.00083	No	No	
ASBESTOS-ST12-1/3/09	030900309-0007	110 Greenwich Street (roof level)	1/3/09	1	3.060	Asbestos	PCME	EMSL	1/5/09	< 0.00081	No	No	
ASBESTOS-ST13-1/3/09	030900309-0008	Marriott Hotel, 38th Floor (roof level)	1/3/09	1	2.960	Asbestos	PCME	EMSL	1/5/09	< 0.00083	No	No	
ASBESTOS-ST14-1/3/09	030900309-0009	West Face - South end at corner (scaffolding level)	1/3/09	1	2.960	Asbestos	PCME	EMSL	1/5/09	< 0.00083	No	No	
ASBESTOS-ST15-1/3/09	030900309-0010	South Face - East end at corner (scaffolding level)	1/3/09	1	3.010	Asbestos	PCME	EMSL	1/5/09	< 0.00082	No	No	
ASBESTOS-ST16-1/3/09	030900309-0011	East Face - North end at corner (scaffolding level)	1/3/09	1	2.980	Asbestos	PCME	EMSL	1/5/09	< 0.00083	No	No	
ASBESTOS-ST17-1/3/09	030900309-0012	North Face - West end at corner (scaffolding level)	1/3/09	1	3.030	Asbestos	PCME	EMSL	1/5/09	< 0.00081	No	No	
ASBESTOS-ST1-1/4/09	030900304-0001	Southwest Area (sidewalk bridge level)	1/4/09	1	3.070	Asbestos	PCME	EMSL	1/5/09	< 0.00088	No	No	
ASBESTOS-ST2-1/4/09	030900304-0002	Southeast Area (sidewalk bridge level)	1/4/09	1	3.110	Asbestos	PCME	EMSL	1/5/09	< 0.00087	No	No	
ASBESTOS-ST4-1/4/09	030900304-0003	Northwest Area (street-level)	1/4/09	1	3.000	Asbestos	PCME	EMSL	1/5/09	< 0.00082	No	No	
ASBESTOS-ST5-1/4/09	030900304-0004	Firehouse #10 (roof level)	1/4/09	1	3.050	Asbestos	PCME	EMSL	1/5/09	< 0.00081	No	No	
ASBESTOS-ST10-1/4/09	030900304-0005	North Side Sidewalk Bridge	1/4/09	1	2.990	Asbestos	PCME	EMSL	1/5/09	< 0.00083	No	No	
ASBESTOS-ST11-1/4/09	030900304-0006	90 Trinity Place (roof level)	1/4/09	1	2.970	Asbestos	PCME	EMSL	1/5/09	< 0.00083	No	No	
ASBESTOS-ST12-1/4/09	030900304-0007	110 Greenwich Street (roof level)	1/4/09	1	3.090	Asbestos	PCME	EMSL	1/5/09	< 0.00087	No	No	
ASBESTOS-ST13-1/4/09	030900304-0008	Marriott Hotel, 38th Floor (roof level)	1/4/09	1	3.000	Asbestos	PCME	EMSL	1/5/09	< 0.00082	No	No	
ASBESTOS-ST14-1/4/09	030900304-0009	West Face - South end at corner (scaffolding level)	1/4/09	1	3.330	Asbestos	PCME	EMSL	1/5/09	< 0.00081	No	No	
ASBESTOS-ST15-1/4/09	030900304-0010	South Face - East end at corner (scaffolding level)	1/4/09	1	3.250	Asbestos	PCME	EMSL	1/5/09	< 0.00083	No	No	
ASBESTOS-ST16-1/4/09	030900304-0011	East Face - North end at corner (scaffolding level)	1/4/09	1	3.200	Asbestos	PCME	EMSL	1/5/09	< 0.00084	No	No	
ASBESTOS-ST17-1/4/09	030900304-0012	North Face - West end at corner (scaffolding level)	1/4/09	1	3.250	Asbestos	PCME	EMSL	1/5/09	< 0.00083	No	No	