

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
										0.0009			
										NA			
ASBESTOS-ST1-1/3/07	030700247-0001	Southwest Area (sidewalk bridge level)	1/3/07	1	3.020	Asbestos	PCME	EMSL	1/4/07	< 0.00082	No	No	
ASBESTOS-ST2-1/3/07	030700247-0002	Southeast Area (sidewalk bridge level)	1/3/07	1	3.020	Asbestos	PCME	EMSL	1/4/07	< 0.00082	No	No	
ASBESTOS-ST4-1/3/07	030700247-0003	Northwest Area (street-level)	1/3/07	1	3.080	Asbestos	PCME	EMSL	1/4/07	< 0.00087	No	No	
ASBESTOS-ST5-1/3/07	030700247-0004	Firehouse #10 (roof level)	1/3/07	1	3.030	Asbestos	PCME	EMSL	1/4/07	< 0.00081	No	No	
ASBESTOS-ST10-1/3/07	030700247-0005	North Side Sidewalk Bridge	1/3/07	1	3.020	Asbestos	PCME	EMSL	1/4/07	< 0.00082	No	No	
ASBESTOS-ST11-1/3/07	030700247-0006	90 Trinity Place (roof level)	1/3/07	1	3.020	Asbestos	PCME	EMSL	1/4/07	< 0.00082	No	No	
ASBESTOS-ST12-1/3/07	030700247-0007	110 Greenwich Street (roof level)	1/3/07	1	3.020	Asbestos	PCME	EMSL	1/4/07	< 0.00082	No	No	
ASBESTOS-ST13-1/3/07	030700247-0008	Marriott Hotel, 38th Floor (roof level)	1/3/07	1	3.020	Asbestos	PCME	EMSL	1/4/07	< 0.00082	No	No	
ASBESTOS-ST14-1/3/07	030700247-0009	West Face - South end at corner (scaffolding level)	1/3/07	1	3.050	Asbestos	PCME	EMSL	1/4/07	< 0.00081	No	No	
ASBESTOS-ST15-1/3/07	030700247-0010	South Face - East end at corner (scaffolding level)	1/3/07	1	3.020	Asbestos	PCME	EMSL	1/4/07	< 0.00082	No	No	
ASBESTOS-ST16-1/3/07	030700247-0011	East Face - North end at corner (scaffolding level)	1/3/07	1	3.040	Asbestos	PCME	EMSL	1/4/07	< 0.00081	No	No	
ASBESTOS-ST17-1/3/07	030700247-0012	North Face - West end at corner (scaffolding level)	1/3/07	1	3.020	Asbestos	PCME	EMSL	1/4/07	< 0.00082	No	No	
ASBESTOS-ST1-1/4/07	030700375-0001	Southwest Area (sidewalk bridge level)	1/4/07	1	3.050	Asbestos	PCME	EMSL	1/5/07	< 0.00088	No	No	
ASBESTOS-ST2-1/4/07	030700375-0002	Southeast Area (sidewalk bridge level)	1/4/07	1	3.020	Asbestos	PCME	EMSL	1/5/07	< 0.00082	No	No	
ASBESTOS-ST4-1/4/07	030700375-0003	Northwest Area (street-level)	1/4/07	1	3.410	Asbestos	PCME	EMSL	1/5/07	< 0.00079	No	No	Note 1.
ASBESTOS-ST5-1/4/07	030700375-0004	Firehouse #10 (roof level)	1/4/07	1	3.010	Asbestos	PCME	EMSL	1/5/07	< 0.00082	No	No	
ASBESTOS-ST10-1/4/07	030700375-0005	North Side Sidewalk Bridge	1/4/07	1	3.140	Asbestos	PCME	EMSL	1/5/07	< 0.00086	No	No	
ASBESTOS-ST11-1/4/07	030700375-0006	90 Trinity Place (roof level)	1/4/07	1	3.030	Asbestos	PCME	EMSL	1/5/07	< 0.00081	No	No	
ASBESTOS-ST12-1/4/07	030700375-0007	110 Greenwich Street (roof level)	1/4/07	1	3.020	Asbestos	PCME	EMSL	1/5/07	< 0.00082	No	No	
ASBESTOS-ST13-1/4/07	030700375-0008	Marriott Hotel, 38th Floor (roof level)	1/4/07	1	3.020	Asbestos	PCME	EMSL	1/5/07	< 0.00082	No	No	
ASBESTOS-ST14-1/4/07	030700375-0009	West Face - South end at corner (scaffolding level)	1/4/07	1	3.020	Asbestos	PCME	EMSL	1/5/07	< 0.00082	No	No	
ASBESTOS-ST15-1/4/07	030700375-0010	South Face - East end at corner (scaffolding level)	1/4/07	1	3.030	Asbestos	PCME	EMSL	1/5/07	< 0.00081	No	No	
ASBESTOS-ST16-1/4/07	030700375-0011	East Face - North end at corner (scaffolding level)	1/4/07	1	3.040	Asbestos	PCME	EMSL	1/5/07	< 0.00089	No	No	
ASBESTOS-ST17-1/4/07	030700375-0012	North Face - West end at corner (scaffolding level)	1/4/07	1	2.990	Asbestos	PCME	EMSL	1/5/07	< 0.00083	No	No	

Note:

1. Due to flow rate RPD exceedance (22.9%) for asbestos at Station 4 (Northwest Area [street-level]) on January 4, 2007, the sample volume and subsequent sample result are estimated.