

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm3)	Exceeds Target	Exceeds EPA	Comments
										0.0009	Air Quality Levels	Site Specific Trigger Levels	
										NA			
Target Air Quality Levels													
EPA Site Specific Trigger Levels													
ASBESTOS-ST1-1/18/08	030801610-0001	Southwest Area (sidewalk bridge level)	1/18/08	1	3.060	Asbestos	PCME	EMSL	1/19/08	< 0.00081	No	No	
ASBESTOS-ST2-1/18/08	030801610-0002	Southeast Area (sidewalk bridge level)	1/18/08	1	3.060	Asbestos	PCME	EMSL	1/19/08	0.00081	No	No	
ASBESTOS-ST4-1/18/08	030801610-0003	Northwest Area (street-level)	1/18/08	1	3.060	Asbestos	PCME	EMSL	1/19/08	< 0.00081	No	No	
ASBESTOS-ST5-1/18/08	030801610-0004	Firehouse #10 (roof level)	1/18/08	1	3.040	Asbestos	PCME	EMSL	1/19/08	< 0.00081	No	No	
ASBESTOS-ST10-1/18/08	030801610-0005	North Side Sidewalk Bridge	1/18/08	1	3.040	Asbestos	PCME	EMSL	1/19/08	< 0.00081	No	No	
ASBESTOS-ST11-1/18/08	030801610-0006	90 Trinity Place (roof level)	1/18/08	1	3.050	Asbestos	PCME	EMSL	1/19/08	< 0.00081	No	No	
ASBESTOS-ST12-1/18/08	030801610-0007	110 Greenwich Street (roof level)	1/18/08	1	3.040	Asbestos	PCME	EMSL	1/19/08	< 0.00081	No	No	
ASBESTOS-ST13-1/18/08	030801610-0008	Marriott Hotel, 38th Floor (roof level)	1/18/08	1	3.020	Asbestos	PCME	EMSL	1/19/08	< 0.00082	No	No	
ASBESTOS-ST14-1/18/08	030801610-0009	West Face - South end at corner (scaffolding level)	1/18/08	1	3.040	Asbestos	PCME	EMSL	1/19/08	< 0.00081	No	No	
ASBESTOS-ST15-1/18/08	030801610-0010	South Face - East end at corner (scaffolding level)	1/18/08	1	3.060	Asbestos	PCME	EMSL	1/19/08	< 0.00081	No	No	
ASBESTOS-ST16-1/18/08	030801610-0011	East Face - North end at corner (scaffolding level)	1/18/08	1	3.020	Asbestos	PCME	EMSL	1/19/08	< 0.00082	No	No	
ASBESTOS-ST17-1/18/08	030801610-0012	North Face - West end at corner (scaffolding level)	1/18/08	1	3.050	Asbestos	PCME	EMSL	1/19/08	< 0.00081	No	No	
ASBESTOS-ST1-1/19/08	030801727-0001	Southwest Area (sidewalk bridge level)	1/19/08	1	3.060	Asbestos	PCME	EMSL	1/21/08	< 0.00081	No	No	
ASBESTOS-ST2-1/19/08	030801727-0002	Southeast Area (sidewalk bridge level)	1/19/08	1	3.020	Asbestos	PCME	EMSL	1/21/08	< 0.00082	No	No	
ASBESTOS-ST4-1/19/08	030801727-0003	Northwest Area (street-level)	1/19/08	1	3.010	Asbestos	PCME	EMSL	1/21/08	< 0.00082	No	No	
ASBESTOS-ST5-1/19/08	030801727-0004	Firehouse #10 (roof level)	1/19/08	1	3.120	Asbestos	PCME	EMSL	1/21/08	< 0.00086	No	No	
ASBESTOS-ST10-1/19/08	030801727-0005	North Side Sidewalk Bridge	1/19/08	1	3.060	Asbestos	PCME	EMSL	1/21/08	< 0.00081	No	No	
ASBESTOS-ST11-1/19/08	030801727-0006	90 Trinity Place (roof level)	1/19/08	1	3.010	Asbestos	PCME	EMSL	1/21/08	< 0.00082	No	No	
ASBESTOS-ST12-1/19/08	030801727-0007	110 Greenwich Street (roof level)	1/19/08	1	2.990	Asbestos	PCME	EMSL	1/21/08	< 0.00083	No	No	
ASBESTOS-ST13-1/19/08	030801727-0008	Marriott Hotel, 38th Floor (roof level)	1/19/08	1	2.970	Asbestos	PCME	EMSL	1/21/08	< 0.00083	No	No	
ASBESTOS-ST14-1/19/08	030801727-0009	West Face - South end at corner (scaffolding level)	1/19/08	1	3.070	Asbestos	PCME	EMSL	1/21/08	< 0.00080	No	No	
ASBESTOS-ST15-1/19/08	030801727-0010	South Face - East end at corner (scaffolding level)	1/19/08	1	3.040	Asbestos	PCME	EMSL	1/21/08	< 0.00081	No	No	
ASBESTOS-ST16-1/19/08	030801727-0011	East Face - North end at corner (scaffolding level)	1/19/08	1	3.010	Asbestos	PCME	EMSL	1/21/08	< 0.00082	No	No	
ASBESTOS-ST17-1/19/08	030801727-0012	North Face - West end at corner (scaffolding level)	1/19/08	1	3.080	Asbestos	PCME	EMSL	1/21/08	< 0.00080	No	No	
ASBESTOS-ST1-1/20/08	030801732-0001	Southwest Area (sidewalk bridge level)	1/20/08	1	3.030	Asbestos	PCME	EMSL	1/21/08	< 0.00081	No	No	
ASBESTOS-ST2-1/20/08	030801732-0002	Southeast Area (sidewalk bridge level)	1/20/08	1	3.010	Asbestos	PCME	EMSL	1/21/08	< 0.00082	No	No	
ASBESTOS-ST4-1/20/08	030801732-0003	Northwest Area (street-level)	1/20/08	1	3.060	Asbestos	PCME	EMSL	1/21/08	< 0.00081	No	No	
ASBESTOS-ST5-1/20/08	030801732-0004	Firehouse #10 (roof level)	1/20/08	1	3.080	Asbestos	PCME	EMSL	1/21/08	< 0.00080	No	No	
ASBESTOS-ST10-1/20/08	030801732-0005	North Side Sidewalk Bridge	1/20/08	1	3.060	Asbestos	PCME	EMSL	1/21/08	< 0.00081	No	No	
ASBESTOS-ST11-1/20/08	030801732-0006	90 Trinity Place (roof level)	1/20/08	1	3.000	Asbestos	PCME	EMSL	1/21/08	< 0.00082	No	No	
ASBESTOS-ST12-1/20/08	030801732-0007	110 Greenwich Street (roof level)	1/20/08	1	2.990	Asbestos	PCME	EMSL	1/21/08	< 0.00083	No	No	
ASBESTOS-ST13-1/20/08	030801732-0008	Marriott Hotel, 38th Floor (roof level)	1/20/08	1	2.970	Asbestos	PCME	EMSL	1/21/08	< 0.00083	No	No	
ASBESTOS-ST14-1/20/08	030801732-0009	West Face - South end at corner (scaffolding level)	1/20/08	1	3.010	Asbestos	PCME	EMSL	1/21/08	< 0.00082	No	No	
ASBESTOS-ST15-1/20/08	030801732-0010	South Face - East end at corner (scaffolding level)	1/20/08	1	3.020	Asbestos	PCME	EMSL	1/21/08	< 0.00082	No	No	
ASBESTOS-ST16-1/20/08	030801732-0011	East Face - North end at corner (scaffolding level)	1/20/08	1	2.990	Asbestos	PCME	EMSL	1/21/08	< 0.00083	No	No	
ASBESTOS-ST17-1/20/08	030801732-0012	North Face - West end at corner (scaffolding level)	1/20/08	1	3.000	Asbestos	PCME	EMSL	1/21/08	< 0.00082	No	No	