

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm3)	Exceeds Target	Exceeds EPA	Comments
										0.0009	Air Quality Levels	Site Specific Trigger Levels	
										NA			
ASBESTOS-ST1-1/29/09	030902877-0001	Southwest Area (sidewalk bridge level)	1/29/09	1	3.030	Asbestos	PCME	EMSL	1/30/09	< 0.00081	No	No	
ASBESTOS-ST2-1/29/09	030902877-0002	Southeast Area (sidewalk bridge level)	1/29/09	1	2.990	Asbestos	PCME	EMSL	1/30/09	< 0.00083	No	No	
ASBESTOS-ST4-1/29/09	030902877-0003	Northwest Area (street-level)	1/29/09	1	3.020	Asbestos	PCME	EMSL	1/30/09	< 0.00082	No	No	
ASBESTOS-ST5-1/29/09	030902877-0004	Firehouse #10 (roof level)	1/29/09	1	2.990	Asbestos	PCME	EMSL	1/30/09	< 0.00083	No	No	
ASBESTOS-ST10-1/29/09	030902877-0005	North Side Sidewalk Bridge	1/29/09	1	3.080	Asbestos	PCME	EMSL	1/30/09	< 0.00080	No	No	
ASBESTOS-ST11-1/29/09	030902877-0006	90 Trinity Place (roof level)	1/29/09	1	2.990	Asbestos	PCME	EMSL	1/30/09	< 0.00083	No	No	
ASBESTOS-ST12-1/29/09	030902877-0007	110 Greenwich Street (roof level)	1/29/09	1	3.090	Asbestos	PCME	EMSL	1/30/09	< 0.00080	No	No	
ASBESTOS-ST13-1/29/09	030902877-0008	Marriott Hotel, 38th Floor (roof level)	1/29/09	1	3.030	Asbestos	PCME	EMSL	1/30/09	< 0.00081	No	No	
ASBESTOS-ST14-1/29/09	030902877-0009	West Face - South end at corner (scaffolding level)	1/29/09	1	3.120	Asbestos	PCME	EMSL	1/30/09	< 0.00079	No	No	
ASBESTOS-ST15-1/29/09	030902877-0010	South Face - East end at corner (scaffolding level)	1/29/09	1	3.100	Asbestos	PCME	EMSL	1/30/09	< 0.00080	No	No	
ASBESTOS-ST17-1/29/09	030902877-0011	North Face - West end at corner (scaffolding level)	1/29/09	1	3.170	Asbestos	PCME	EMSL	1/30/09	< 0.00078	No	No	
ASBESTOS-ST1-1/30/09	030902997-0001	Southwest Area (sidewalk bridge level)	1/30/09	1	3.050	Asbestos	PCME	EMSL	1/31/09	< 0.00081	No	No	
ASBESTOS-ST2-1/30/09	030902997-0002	Southeast Area (sidewalk bridge level)	1/30/09	1	3.030	Asbestos	PCME	EMSL	1/31/09	< 0.00081	No	No	
ASBESTOS-ST4-1/30/09	030902997-0003	Northwest Area (street-level)	1/30/09	1	2.970	Asbestos	PCME	EMSL	1/31/09	< 0.00083	No	No	
ASBESTOS-ST5-1/30/09	030902997-0004	Firehouse #10 (roof level)	1/30/09	1	3.020	Asbestos	PCME	EMSL	1/31/09	< 0.00082	No	No	
ASBESTOS-ST10-1/30/09	030902997-0005	North Side Sidewalk Bridge	1/30/09	1	3.030	Asbestos	PCME	EMSL	1/31/09	< 0.00081	No	No	
ASBESTOS-ST100-1/30/09	030902997-0013	Station 10 Field Duplicate	1/30/09	1	3.070	Asbestos	PCME	EMSL	1/31/09	< 0.00080	No	No	
ASBESTOS-ST11-1/30/09	030902997-0006	90 Trinity Place (roof level)	1/30/09	1	3.040	Asbestos	PCME	EMSL	1/31/09	< 0.00081	No	No	
ASBESTOS-ST12-1/30/09	030902997-0007	110 Greenwich Street (roof level)	1/30/09	1	3.070	Asbestos	PCME	EMSL	1/31/09	< 0.00080	No	No	
ASBESTOS-ST13-1/30/09	030902997-0008	Marriott Hotel, 38th Floor (roof level)	1/30/09	1	3.070	Asbestos	PCME	EMSL	1/31/09	< 0.00080	No	No	
ASBESTOS-ST14-1/30/09	030902997-0009	West Face - South end at corner (scaffolding level)	1/30/09	1	2.950	Asbestos	PCME	EMSL	1/31/09	< 0.00084	No	No	
ASBESTOS-ST15-1/30/09	030902997-0010	South Face - East end at corner (scaffolding level)	1/30/09	1	2.940	Asbestos	PCME	EMSL	1/31/09	< 0.00084	No	No	
ASBESTOS-ST16-1/30/09	030902997-0011	East Face - North end at corner (scaffolding level)	1/30/09	1	2.870	Asbestos	PCME	EMSL	1/31/09	< 0.00086	No	No	
ASBESTOS-ST17-1/30/09	030902997-0012	North Face - West end at corner (scaffolding level)	1/30/09	1	2.900	Asbestos	PCME	EMSL	1/31/09	< 0.00085	No	No	
ASBESTOS-ST1-1/31/09	030903100-0001	Southwest Area (sidewalk bridge level)	1/31/09	1	3.050	Asbestos	PCME	EMSL	2/2/09	< 0.00081	No	No	
ASBESTOS-ST2-1/31/09	030903100-0002	Southeast Area (sidewalk bridge level)	1/31/09	1	3.040	Asbestos	PCME	EMSL	2/2/09	< 0.00081	No	No	
ASBESTOS-ST4-1/31/09	030903100-0003	Northwest Area (street-level)	1/31/09	1	3.010	Asbestos	PCME	EMSL	2/2/09	< 0.00082	No	No	
ASBESTOS-ST5-1/31/09	030903100-0004	Firehouse #10 (roof level)	1/31/09	1	3.040	Asbestos	PCME	EMSL	2/2/09	< 0.00081	No	No	
ASBESTOS-ST10-1/31/09	030903100-0005	North Side Sidewalk Bridge	1/31/09	1	3.030	Asbestos	PCME	EMSL	2/2/09	< 0.00081	No	No	
ASBESTOS-ST11-1/31/09	030903100-0006	90 Trinity Place (roof level)	1/31/09	1	2.970	Asbestos	PCME	EMSL	2/2/09	< 0.00083	No	No	
ASBESTOS-ST12-1/31/09	030903100-0007	110 Greenwich Street (roof level)	1/31/09	1	3.030	Asbestos	PCME	EMSL	2/2/09	< 0.00081	No	No	
ASBESTOS-ST13-1/31/09	030903100-0008	Marriott Hotel, 38th Floor (roof level)	1/31/09	1	3.000	Asbestos	PCME	EMSL	2/2/09	< 0.00082	No	No	
ASBESTOS-ST14-1/31/09	030903100-0009	West Face - South end at corner (scaffolding level)	1/31/09	1	2.880	Asbestos	PCME	EMSL	2/2/09	< 0.00086	No	No	
ASBESTOS-ST15-1/31/09	030903100-0010	South Face - East end at corner (scaffolding level)	1/31/09	1	2.860	Asbestos	PCME	EMSL	2/2/09	< 0.00086	No	No	
ASBESTOS-ST16-1/31/09	030903100-0011	East Face - North end at corner (scaffolding level)	1/31/09	1	2.930	Asbestos	PCME	EMSL	2/2/09	< 0.00084	No	No	
ASBESTOS-ST17-1/31/09	030903100-0012	North Face - West end at corner (scaffolding level)	1/31/09	1	2.870	Asbestos	PCME	EMSL	2/2/09	< 0.00086	No	No	
ASBESTOS-ST1-2/1/09	030903097-0001	Southwest Area (sidewalk bridge level)	2/1/09	1	3.110	Asbestos	PCME	EMSL	2/2/09	< 0.00079	No	No	
ASBESTOS-ST2-2/1/09	030903097-0002	Southeast Area (sidewalk bridge level)	2/1/09	1	3.110	Asbestos	PCME	EMSL	2/2/09	< 0.00079	No	No	
ASBESTOS-ST4-2/1/09	030903097-0003	Northwest Area (street-level)	2/1/09	1	3.010	Asbestos	PCME	EMSL	2/2/09	< 0.00082	No	No	
ASBESTOS-ST5-2/1/09	030903097-0004	Firehouse #10 (roof level)	2/1/09	1	3.100	Asbestos	PCME	EMSL	2/2/09	< 0.00080	No	No	
ASBESTOS-ST10-2/1/09	030903097-0005	North Side Sidewalk Bridge	2/1/09	1	3.120	Asbestos	PCME	EMSL	2/2/09	< 0.00079	No	No	
ASBESTOS-ST11-2/1/09	030903097-0006	90 Trinity Place (roof level)	2/1/09	1	3.010	Asbestos	PCME	EMSL	2/2/09	< 0.00082	No	No	
ASBESTOS-ST12-2/1/09	030903097-0007	110 Greenwich Street (roof level)	2/1/09	1	2.990	Asbestos	PCME	EMSL	2/2/09	< 0.00083	No	No	
ASBESTOS-ST13-2/1/09	030903097-0008	Marriott Hotel, 38th Floor (roof level)	2/1/09	1	2.950	Asbestos	PCME	EMSL	2/2/09	< 0.00084	No	No	
ASBESTOS-ST14-2/1/09	030903097-0009	West Face - South end at corner (scaffolding level)	2/1/09	1	3.300	Asbestos	PCME	EMSL	2/2/09	< 0.00075	No	No	
ASBESTOS-ST15-2/1/09	030903097-0010	South Face - East end at corner (scaffolding level)	2/1/09	1	3.200	Asbestos	PCME	EMSL	2/2/09	< 0.00077	No	No	
ASBESTOS-ST16-2/1/09	030903097-0011	East Face - North end at corner (scaffolding level)	2/1/09	1	3.290	Asbestos	PCME	EMSL	2/2/09	< 0.00075	No	No	
ASBESTOS-ST17-2/1/09	030903097-0012	North Face - West end at corner (scaffolding level)	2/1/09	1	3.460	Asbestos	PCME	EMSL	2/2/09	< 0.00071	No	No	

Note:

1. The asbestos sample from Station 16 (East Face - North end at corner [scaffolding level]) on January 29, 2009 was not available for analysis on account of pump failure.