

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
										0.0009			
										NA			
EPA Site Specific Trigger Levels													
ASBESTOS-ST1-2/20/08	030804501-0001	Southwest Area (sidewalk bridge level)	2/20/08	1	2.950	Asbestos	PCME	EMSL	2/21/08	< 0.00084	No	No	
ASBESTOS-ST2-2/20/08	030804501-0002	Southeast Area (sidewalk bridge level)	2/20/08	1	2.920	Asbestos	PCME	EMSL	2/21/08	< 0.00085	No	No	
ASBESTOS-ST4-2/20/08	030804501-0003	Northwest Area (street-level)	2/20/08	1	3.170	Asbestos	PCME	EMSL	2/21/08	< 0.00078	No	No	
ASBESTOS-ST5-2/20/08	030804501-0004	Firehouse #10 (roof level)	2/20/08	1	3.130	Asbestos	PCME	EMSL	2/21/08	< 0.00079	No	No	
ASBESTOS-ST10-2/20/08	030804501-0005	North Side Sidewalk Bridge	2/20/08	1	2.970	Asbestos	PCME	EMSL	2/21/08	< 0.00083	No	No	
ASBESTOS-ST11-2/20/08	030804501-0006	90 Trinity Place (roof level)	2/20/08	1	3.000	Asbestos	PCME	EMSL	2/21/08	0.00082	No	No	
ASBESTOS-ST12-2/20/08	030804501-0007	110 Greenwich Street (roof level)	2/20/08	1	3.010	Asbestos	PCME	EMSL	2/21/08	< 0.00082	No	No	
ASBESTOS-ST13-2/20/08	030804501-0008	Marriott Hotel, 38th Floor (roof level)	2/20/08	1	3.140	Asbestos	PCME	EMSL	2/21/08	< 0.00079	No	No	
ASBESTOS-ST14-2/20/08	030804501-0009	West Face - South end at corner (scaffolding level)	2/20/08	1	3.010	Asbestos	PCME	EMSL	2/21/08	< 0.00082	No	No	
ASBESTOS-ST15-2/20/08	030804501-0010	South Face - East end at corner (scaffolding level)	2/20/08	1	2.990	Asbestos	PCME	EMSL	2/21/08	< 0.00083	No	No	
ASBESTOS-ST16-2/20/08	030804501-0011	East Face - North end at corner (scaffolding level)	2/20/08	1	3.090	Asbestos	PCME	EMSL	2/21/08	< 0.00080	No	No	
ASBESTOS-ST17-2/20/08	030804501-0012	North Face - West end at corner (scaffolding level)	2/20/08	1	3.120	Asbestos	PCME	EMSL	2/21/08	< 0.00079	No	No	
ASBESTOS-ST1-2/21/08	030804567-0001	Southwest Area (sidewalk bridge level)	2/21/08	1	2.940	Asbestos	PCME	EMSL	2/22/08	< 0.00084	No	No	
ASBESTOS-ST2-2/21/08	030804567-0002	Southeast Area (sidewalk bridge level)	2/21/08	1	2.980	Asbestos	PCME	EMSL	2/22/08	< 0.00083	No	No	
ASBESTOS-ST4-2/21/08	030804567-0003	Northwest Area (street-level)	2/21/08	1	3.020	Asbestos	PCME	EMSL	2/22/08	< 0.00082	No	No	
ASBESTOS-ST5-2/21/08	030804567-0004	Firehouse #10 (roof level)	2/21/08	1	3.010	Asbestos	PCME	EMSL	2/22/08	< 0.00082	No	No	
ASBESTOS-ST10-2/21/08	030804567-0005	North Side Sidewalk Bridge	2/21/08	1	3.210	Asbestos	PCME	EMSL	2/22/08	< 0.00077	No	No	
ASBESTOS-ST11-2/21/08	030804567-0006	90 Trinity Place (roof level)	2/21/08	1	3.070	Asbestos	PCME	EMSL	2/22/08	< 0.00080	No	No	
ASBESTOS-ST12-2/21/08	030804567-0007	110 Greenwich Street (roof level)	2/21/08	1	3.000	Asbestos	PCME	EMSL	2/22/08	< 0.00082	No	No	
ASBESTOS-ST13-2/21/08	030804567-0008	Marriott Hotel, 38th Floor (roof level)	2/21/08	1	2.920	Asbestos	PCME	EMSL	2/22/08	< 0.00085	No	No	
ASBESTOS-ST14-2/21/08	030804567-0009	West Face - South end at corner (scaffolding level)	2/21/08	1	2.980	Asbestos	PCME	EMSL	2/22/08	< 0.00083	No	No	
ASBESTOS-ST16-2/21/08	030804567-0010	East Face - North end at corner (scaffolding level)	2/21/08	1	3.050	Asbestos	PCME	EMSL	2/22/08	0.00081	No	No	
ASBESTOS-ST17-2/21/08	030804567-0011	North Face - West end at corner (scaffolding level)	2/21/08	1	3.010	Asbestos	PCME	EMSL	2/22/08	< 0.00082	No	No	
ASBESTOS-ST1-2/22/08	030804638-0001	Southwest Area (sidewalk bridge level)	2/22/08	1	3.090	Asbestos	PCME	EMSL	2/23/08	< 0.00080	No	No	
ASBESTOS-ST2-2/22/08	030804638-0002	Southeast Area (sidewalk bridge level)	2/22/08	1	3.100	Asbestos	PCME	EMSL	2/23/08	< 0.00080	No	No	
ASBESTOS-ST4-2/22/08	030804638-0003	Northwest Area (street-level)	2/22/08	1	3.180	Asbestos	PCME	EMSL	2/23/08	< 0.00078	No	No	
ASBESTOS-ST5-2/22/08	030804638-0004	Firehouse #10 (roof level)	2/22/08	1	3.070	Asbestos	PCME	EMSL	2/23/08	< 0.00080	No	No	
ASBESTOS-ST10-2/22/08	030804638-0005	North Side Sidewalk Bridge	2/22/08	1	2.970	Asbestos	PCME	EMSL	2/23/08	< 0.00083	No	No	
ASBESTOS-ST11-2/22/08	030804638-0006	90 Trinity Place (roof level)	2/22/08	1	3.060	Asbestos	PCME	EMSL	2/23/08	< 0.00081	No	No	
ASBESTOS-ST12-2/22/08	030804638-0007	110 Greenwich Street (roof level)	2/22/08	1	3.070	Asbestos	PCME	EMSL	2/23/08	< 0.00080	No	No	
ASBESTOS-ST13-2/22/08	030804638-0008	Marriott Hotel, 38th Floor (roof level)	2/22/08	1	3.020	Asbestos	PCME	EMSL	2/23/08	< 0.00082	No	No	
ASBESTOS-ST14-2/22/08	030804638-0009	West Face - South end at corner (scaffolding level)	2/22/08	1	3.090	Asbestos	PCME	EMSL	2/23/08	< 0.00080	No	No	
ASBESTOS-ST16-2/22/08	030804638-0010	East Face - North end at corner (scaffolding level)	2/22/08	1	2.980	Asbestos	PCME	EMSL	2/23/08	< 0.00083	No	No	
ASBESTOS-ST17-2/22/08	030804638-0011	North Face - West end at corner (scaffolding level)	2/22/08	1	3.040	Asbestos	PCME	EMSL	2/23/08	< 0.00081	No	No	
ASBESTOS-ST1-2/23/08	030804738-0001	Southwest Area (sidewalk bridge level)	2/23/08	1	2.820	Asbestos	PCME	EMSL	2/25/08	< 0.00088	No	No	
ASBESTOS-ST2-2/23/08	030804738-0002	Southeast Area (sidewalk bridge level)	2/23/08	1	2.800	Asbestos	PCME	EMSL	2/25/08	< 0.00088	No	No	
ASBESTOS-ST4-2/23/08	030804738-0003	Northwest Area (street-level)	2/23/08	1	2.760	Asbestos	PCME	EMSL	2/25/08	< 0.00089	No	No	
ASBESTOS-ST5-2/23/08	030804738-0004	Firehouse #10 (roof level)	2/23/08	1	3.070	Asbestos	PCME	EMSL	2/25/08	< 0.00080	No	No	
ASBESTOS-ST10-2/23/08	030804738-0005	North Side Sidewalk Bridge	2/23/08	1	3.230	Asbestos	PCME	EMSL	2/25/08	< 0.00076	No	No	
ASBESTOS-ST11-2/23/08	030804738-0006	90 Trinity Place (roof level)	2/23/08	1	2.990	Asbestos	PCME	EMSL	2/25/08	< 0.00083	No	No	
ASBESTOS-ST12-2/23/08	030804738-0007	110 Greenwich Street (roof level)	2/23/08	1	3.070	Asbestos	PCME	EMSL	2/25/08	< 0.00080	No	No	
ASBESTOS-ST13-2/23/08	030804738-0008	Marriott Hotel, 38th Floor (roof level)	2/23/08	1	3.010	Asbestos	PCME	EMSL	2/25/08	< 0.00082	No	No	
ASBESTOS-ST14-2/23/08	030804738-0009	West Face - South end at corner (scaffolding level)	2/23/08	1	3.130	Asbestos	PCME	EMSL	2/25/08	< 0.00079	No	No	
ASBESTOS-ST15-2/23/08	030804738-0010	South Face - East end at corner (scaffolding level)	2/23/08	1	3.040	Asbestos	PCME	EMSL	2/25/08	< 0.00081	No	No	
ASBESTOS-ST16-2/23/08	030804738-0011	East Face - North end at corner (scaffolding level)	2/23/08	1	3.000	Asbestos	PCME	EMSL	2/25/08	< 0.00082	No	No	
ASBESTOS-ST17-2/23/08	030804738-0012	North Face - West end at corner (scaffolding level)	2/23/08	1	3.030	Asbestos	PCME	EMSL	2/25/08	< 0.00081	No	No	
ASBESTOS-ST1-2/24/08	030804731-0001	Southwest Area (sidewalk bridge level)	2/24/08	1	3.080	Asbestos	PCME	EMSL	2/25/08	< 0.00080	No	No	
ASBESTOS-ST2-2/24/08	030804731-0002	Southeast Area (sidewalk bridge level)	2/24/08	1	3.040	Asbestos	PCME	EMSL	2/25/08	< 0.00081	No	No	
ASBESTOS-ST4-2/24/08	030804731-0003	Northwest Area (street-level)	2/24/08	1	3.140	Asbestos	PCME	EMSL	2/25/08	< 0.00079	No	No	
ASBESTOS-ST5-2/24/08	030804731-0004	Firehouse #10 (roof level)	2/24/08	1	3.140	Asbestos	PCME	EMSL	2/25/08	< 0.00079	No	No	
ASBESTOS-ST10-2/24/08	030804731-0005	North Side Sidewalk Bridge	2/24/08	1	3.150	Asbestos	PCME	EMSL	2/25/08	< 0.00078	No	No	
ASBESTOS-ST11-2/24/08	030804731-0006	90 Trinity Place (roof level)	2/24/08	1	2.990	Asbestos	PCME	EMSL	2/25/08	< 0.00083	No	No	
ASBESTOS-ST12-2/24/08	030804731-0007	110 Greenwich Street (roof level)	2/24/08	1	3.070	Asbestos	PCME	EMSL	2/25/08	< 0.00080	No	No	
ASBESTOS-ST13-2/24/08	030804731-0008	Marriott Hotel, 38th Floor (roof level)	2/24/08	1	3.040	Asbestos	PCME	EMSL	2/25/08	< 0.00081	No	No	
ASBESTOS-ST14-2/24/08	030804731-0009	West Face - South end at corner (scaffolding level)	2/24/08	1	2.990	Asbestos	PCME	EMSL	2/25/08	< 0.00083	No	No	
ASBESTOS-ST15-2/24/08	030804731-0010	South Face - East end at corner (scaffolding level)	2/24/08	1	3.010	Asbestos	PCME	EMSL	2/25/08	< 0.00082	No	No	
ASBESTOS-ST16-2/24/08	030804731-0011	East Face - North end at corner (scaffolding level)	2/24/08	1	3.010	Asbestos	PCME	EMSL	2/25/08	< 0.00082	No	No	
ASBESTOS-ST17-2/24/08	030804731-0012	North Face - West end at corner (scaffolding level)	2/24/08	1	3.090	Asbestos	PCME	EMSL	2/25/08	< 0.00080	No	No	

Note:

1. The asbestos samples at Station 15 (South Face - East end at corner (scaffolding level) on February 21 and 22, 2008 were not available for analysis on account of power failure.