

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m <sup>3</sup> )	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
										<b>0.0009</b>			
										<b>NA</b>			
ABBESTOS-ST1-2/23/06	030605868-0001	Southwest Area (sidewalk bridge level)	2/23/06	1	2.970	Asbestos	PCME	EMSL	2/24/06	< 0.00083	No	No	
ABBESTOS-ST2-2/23/06	030605868-0002	Southeast Area (sidewalk bridge level)	2/23/06	1	2.970	Asbestos	PCME	EMSL	2/24/06	< 0.00083	No	No	
ABBESTOS-ST4-2/23/06	030605868-0003	Northwest Area (street-level)	2/23/06	1	2.970	Asbestos	PCME	EMSL	2/24/06	< 0.00083	No	No	
ABBESTOS-ST5-2/23/06	030605868-0004	Firehouse #10 (roof level)	2/23/06	1	2.970	Asbestos	PCME	EMSL	2/24/06	< 0.00083	No	No	
ABBESTOS-ST10-2/23/06	030605868-0005	North Side Sidewalk Bridge	2/23/06	1	2.970	Asbestos	PCME	EMSL	2/24/06	< 0.00083	No	No	
ABBESTOS-ST11-2/23/06	030605868-0006	90 Trinity Place (roof level)	2/23/06	1	2.970	Asbestos	PCME	EMSL	2/24/06	< 0.00083	No	No	
ABBESTOS-ST12-2/23/06	030605868-0007	110 Greenwich Street (roof level)	2/23/06	1	2.970	Asbestos	PCME	EMSL	2/24/06	< 0.00083	No	No	
ABBESTOS-ST13-2/23/06	030605868-0008	Marriott Hotel, 38th Floor (roof level)	2/23/06	1	2.970	Asbestos	PCME	EMSL	2/24/06	< 0.00083	No	No	
ABBESTOS-ST14-2/23/06	030605868-0009	West Face - South end at corner (scaffolding level)	2/23/06	1	2.970	Asbestos	PCME	EMSL	2/24/06	< 0.00083	No	No	
ABBESTOS-ST15-2/23/06	030605868-0010	South Face - East end at corner (scaffolding level)	2/23/06	1	2.970	Asbestos	PCME	EMSL	2/24/06	< 0.00083	No	No	
ABBESTOS-ST16-2/23/06	030605868-0011	East Face - North end at corner (scaffolding level)	2/23/06	1	2.970	Asbestos	PCME	EMSL	2/24/06	< 0.00083	No	No	
ABBESTOS-ST17-2/23/06	030605868-0012	North Face - West end at corner (scaffolding level)	2/23/06	1	2.970	Asbestos	PCME	EMSL	2/24/06	< 0.00083	No	No	
ASBESTOS-ST1-2/24/06	030606070-0001	Southwest Area (sidewalk bridge level)	2/24/06	1	2.970	Asbestos	PCME	EMSL	2/27/06	< 0.00083	No	No	
ASBESTOS-ST2-2/24/06	030606070-0002	Southeast Area (sidewalk bridge level)	2/24/06	1	2.970	Asbestos	PCME	EMSL	2/27/06	< 0.00083	No	No	
ASBESTOS-ST4-2/24/06	030606070-0003	Northwest Area (street-level)	2/24/06	1	2.970	Asbestos	PCME	EMSL	2/27/06	< 0.00083	No	No	
ASBESTOS-ST5-2/24/06	030606070-0004	Firehouse #10 (roof level)	2/24/06	1	2.970	Asbestos	PCME	EMSL	2/27/06	< 0.00083	No	No	
ASBESTOS-ST10-2/24/06	030606070-0005	North Side Sidewalk Bridge	2/24/06	1	2.970	Asbestos	PCME	EMSL	2/27/06	< 0.00083	No	No	
ASBESTOS-ST11-2/24/06	030606070-0006	90 Trinity Place (roof level)	2/24/06	1	2.970	Asbestos	PCME	EMSL	2/27/06	< 0.00083	No	No	
ASBESTOS-ST12-2/24/06	030606070-0007	110 Greenwich Street (roof level)	2/24/06	1	2.970	Asbestos	PCME	EMSL	2/27/06	< 0.00083	No	No	
ASBESTOS-ST13-2/24/06	030606070-0008	Marriott Hotel, 38th Floor (roof level)	2/24/06	1	2.970	Asbestos	PCME	EMSL	2/27/06	< 0.00083	No	No	
ASBESTOS-ST14-2/24/06	030606070-0009	West Face - South end at corner (scaffolding level)	2/24/06	1	2.970	Asbestos	PCME	EMSL	2/27/06	< 0.00083	No	No	
ASBESTOS-ST15-2/24/06	030606070-0010	South Face - East end at corner (scaffolding level)	2/24/06	1	2.970	Asbestos	PCME	EMSL	2/27/06	< 0.00083	No	No	
ASBESTOS-ST16-2/24/06	030606070-0011	East Face - North end at corner (scaffolding level)	2/24/06	1	2.970	Asbestos	PCME	EMSL	2/27/06	0.00083	No	No	
ASBESTOS-ST17-2/24/06	030606070-0012	North Face - West end at corner (scaffolding level)	2/24/06	1	2.970	Asbestos	PCME	EMSL	2/27/06	< 0.00083	No	No	
ASBESTOS-ST1-2/25/06	030606066-0001	Southwest Area (sidewalk bridge level)	2/25/06	1	2.970	Asbestos	PCME	EMSL	2/27/06	< 0.00083	No	No	
ASBESTOS-ST2-2/25/06	030606066-0002	Southeast Area (sidewalk bridge level)	2/25/06	1	2.970	Asbestos	PCME	EMSL	2/27/06	< 0.00083	No	No	
ASBESTOS-ST4-2/25/06	030606066-0003	Northwest Area (street-level)	2/25/06	1	2.970	Asbestos	PCME	EMSL	2/27/06	< 0.00083	No	No	
ASBESTOS-ST5-2/25/06	030606066-0004	Firehouse #10 (roof level)	2/25/06	1	2.970	Asbestos	PCME	EMSL	2/27/06	< 0.00083	No	No	
ASBESTOS-ST10-2/25/06	030606066-0005	North Side Sidewalk Bridge	2/25/06	1	2.970	Asbestos	PCME	EMSL	2/27/06	< 0.00083	No	No	
ASBESTOS-ST11-2/25/06	030606066-0006	90 Trinity Place (roof level)	2/25/06	1	2.970	Asbestos	PCME	EMSL	2/27/06	< 0.00083	No	No	
ASBESTOS-ST12-2/25/06	030606066-0007	110 Greenwich Street (roof level)	2/25/06	1	2.970	Asbestos	PCME	EMSL	2/27/06	< 0.00083	No	No	
ASBESTOS-ST13-2/25/06	030606066-0008	Marriott Hotel, 38th Floor (roof level)	2/25/06	1	2.970	Asbestos	PCME	EMSL	2/27/06	< 0.00083	No	No	
ASBESTOS-ST14-2/25/06	030606066-0009	West Face - South end at corner (scaffolding level)	2/25/06	1	2.970	Asbestos	PCME	EMSL	2/27/06	< 0.00083	No	No	
ASBESTOS-ST15-2/25/06	030606066-0010	South Face - East end at corner (scaffolding level)	2/25/06	1	2.970	Asbestos	PCME	EMSL	2/27/06	< 0.00083	No	No	
ASBESTOS-ST16-2/25/06	030606066-0011	East Face - North end at corner (scaffolding level)	2/25/06	1	2.970	Asbestos	PCME	EMSL	2/27/06	< 0.00083	No	No	
ASBESTOS-ST17-2/25/06	030606066-0012	North Face - West end at corner (scaffolding level)	2/25/06	1	2.970	Asbestos	PCME	EMSL	2/27/06	< 0.00083	No	No	
ASBESTOS-ST1-2/26/06	030606073-0001	Southwest Area (sidewalk bridge level)	2/26/06	1	2.970	Asbestos	PCME	EMSL	2/27/06	< 0.00083	No	No	
ASBESTOS-ST2-2/26/06	030606073-0002	Southeast Area (sidewalk bridge level)	2/26/06	1	2.970	Asbestos	PCME	EMSL	2/27/06	< 0.00083	No	No	
ASBESTOS-ST4-2/26/06	030606073-0003	Northwest Area (street-level)	2/26/06	1	2.970	Asbestos	PCME	EMSL	2/27/06	< 0.00083	No	No	
ASBESTOS-ST5-2/26/06	030606073-0004	Firehouse #10 (roof level)	2/26/06	1	2.970	Asbestos	PCME	EMSL	2/27/06	< 0.00083	No	No	
ASBESTOS-ST10-2/26/06	030606073-0005	North Side Sidewalk Bridge	2/26/06	1	2.970	Asbestos	PCME	EMSL	2/27/06	< 0.00083	No	No	
ASBESTOS-ST11-2/26/06	030606073-0006	90 Trinity Place (roof level)	2/26/06	1	2.970	Asbestos	PCME	EMSL	2/27/06	< 0.00083	No	No	
ASBESTOS-ST12-2/26/06	030606073-0007	110 Greenwich Street (roof level)	2/26/06	1	2.970	Asbestos	PCME	EMSL	2/27/06	< 0.00083	No	No	
ASBESTOS-ST13-2/26/06	030606073-0008	Marriott Hotel, 38th Floor (roof level)	2/26/06	1	2.970	Asbestos	PCME	EMSL	2/27/06	< 0.00083	No	No	
ASBESTOS-ST14-2/26/06	030606073-0009	West Face - South end at corner (scaffolding level)	2/26/06	1	2.970	Asbestos	PCME	EMSL	2/27/06	< 0.00083	No	No	
ASBESTOS-ST15-2/26/06	030606073-0010	South Face - East end at corner (scaffolding level)	2/26/06	1	2.970	Asbestos	PCME	EMSL	2/27/06	< 0.00083	No	No	
ASBESTOS-ST16-2/26/06	030606073-0011	East Face - North end at corner (scaffolding level)	2/26/06	1	2.970	Asbestos	PCME	EMSL	2/27/06	< 0.00083	No	No	
ASBESTOS-ST17-2/26/06	030606073-0012	North Face - West end at corner (scaffolding level)	2/26/06	1	2.970	Asbestos	PCME	EMSL	2/27/06	< 0.00083	No	No	
ASBESTOS-ST1-2/27/06	030606199-0001	Southwest Area (sidewalk bridge level)	2/27/06	1	2.970	Asbestos	PCME	EMSL	2/28/06	< 0.00083	No	No	
ASBESTOS-ST2-2/27/06	030606199-0002	Southeast Area (sidewalk bridge level)	2/27/06	1	2.970	Asbestos	PCME	EMSL	2/28/06	< 0.00083	No	No	
ASBESTOS-ST4-2/27/06	030606199-0003	Northwest Area (street-level)	2/27/06	1	2.970	Asbestos	PCME	EMSL	2/28/06	< 0.00083	No	No	
ASBESTOS-ST5-2/27/06	030606199-0004	Firehouse #10 (roof level)	2/27/06	1	2.970	Asbestos	PCME	EMSL	2/28/06	< 0.00083	No	No	
ASBESTOS-ST10-2/27/06	030606199-0005	North Side Sidewalk Bridge	2/27/06	1	2.970	Asbestos	PCME	EMSL	2/28/06	< 0.00083	No	No	
ASBESTOS-ST100-2/27/06	030606199-0013	Station 10 Field Duplicate	2/27/06	1	2.970	Asbestos	PCME	EMSL	2/28/06	0.00083	No	No	
ASBESTOS-ST11-2/27/06	030606199-0006	90 Trinity Place (roof level)	2/27/06	1	2.970	Asbestos	PCME	EMSL	2/28/06	< 0.00083	No	No	
ASBESTOS-ST12-2/27/06	030606199-0007	110 Greenwich Street (roof level)	2/27/06	1	2.970	Asbestos	PCME	EMSL	2/28/06	< 0.00083	No	No	
ASBESTOS-ST13-2/27/06	030606199-0008	Marriott Hotel, 38th Floor (roof level)	2/27/06	1	2.970	Asbestos	PCME	EMSL	2/28/06	< 0.00083	No	No	
ASBESTOS-ST14-2/27/06	030606199-0009	West Face - South end at corner (scaffolding level)	2/27/06	1	2.970	Asbestos	PCME	EMSL	2/28/06	< 0.00083	No	No	
ASBESTOS-ST15-2/27/06	030606199-0010	South Face - East end at corner (scaffolding level)	2/27/06	1	2.970	Asbestos	PCME	EMSL	2/28/06	< 0.00083	No	No	
ASBESTOS-ST16-2/27/06	030606199-0011	East Face - North end at corner (scaffolding level)	2/27/06	1	2.970	Asbestos	PCME	EMSL	2/28/06	< 0.00083	No	No	
ASBESTOS-ST17-2/27/06	030606199-0012	North Face - West end at corner (scaffolding level)	2/27/06	1	2.970	Asbestos	PCME	EMSL	2/28/06	< 0.00083	No	No	