

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
Target Air Quality Levels										0.0009			
EPA Site Specific Trigger Levels										NA			
ASBESTOS-ST1-3/1/07	030706526-0001	Southwest Area (sidewalk bridge level)	3/1/07	1	3.020	Asbestos	PCME	EMSL	3/2/07	< 0.00082	No	No	
ASBESTOS-ST2-3/1/07	030706526-0002	Southeast Area (sidewalk bridge level)	3/1/07	1	3.020	Asbestos	PCME	EMSL	3/2/07	< 0.00082	No	No	
ASBESTOS-ST4-3/1/07	030706526-0003	Northwest Area (street-level)	3/1/07	1	3.020	Asbestos	PCME	EMSL	3/2/07	< 0.00082	No	No	
ASBESTOS-ST5-3/1/07	030706526-0004	Firehouse #10 (roof level)	3/1/07	1	3.070	Asbestos	PCME	EMSL	3/2/07	< 0.00080	No	No	
ASBESTOS-ST10-3/1/07	030706526-0005	North Side Sidewalk Bridge	3/1/07	1	3.020	Asbestos	PCME	EMSL	3/2/07	< 0.00082	No	No	
ASBESTOS-ST11-3/1/07	030706526-0006	90 Trinity Place (roof level)	3/1/07	1	3.040	Asbestos	PCME	EMSL	3/2/07	< 0.00081	No	No	
ASBESTOS-ST12-3/1/07	030706526-0007	110 Greenwich Street (roof level)	3/1/07	1	3.060	Asbestos	PCME	EMSL	3/2/07	< 0.00081	No	No	
ASBESTOS-ST13-3/1/07	030706526-0008	Marriott Hotel, 38th Floor (roof level)	3/1/07	1	3.040	Asbestos	PCME	EMSL	3/2/07	< 0.00081	No	No	
ASBESTOS-ST14-3/1/07	030706526-0009	West Face - South end at corner (scaffolding level)	3/1/07	1	3.060	Asbestos	PCME	EMSL	3/2/07	< 0.00081	No	No	
ASBESTOS-ST15-3/1/07	030706526-0010	South Face - East end at corner (scaffolding level)	3/1/07	1	3.020	Asbestos	PCME	EMSL	3/2/07	< 0.00082	No	No	
ASBESTOS-ST17-3/1/07	030706526-0012	North Face - West end at corner (scaffolding level)	3/1/07	1	3.020	Asbestos	PCME	EMSL	3/2/07	< 0.00082	No	No	
ASBESTOS-ST1-3/2/07	030706775-0001	Southwest Area (sidewalk bridge level)	3/2/07	1	3.020	Asbestos	PCME	EMSL	3/5/07	< 0.00082	No	No	
ASBESTOS-ST2-3/2/07	030706775-0002	Southeast Area (sidewalk bridge level)	3/2/07	1	3.020	Asbestos	PCME	EMSL	3/5/07	< 0.00082	No	No	
ASBESTOS-ST4-3/2/07	030706775-0003	Northwest Area (street-level)	3/2/07	1	3.000	Asbestos	PCME	EMSL	3/5/07	< 0.00082	No	No	
ASBESTOS-ST5-3/2/07	030706775-0004	Firehouse #10 (roof level)	3/2/07	1	3.020	Asbestos	PCME	EMSL	3/5/07	< 0.00082	No	No	
ASBESTOS-ST10-3/2/07	030706775-0005	North Side Sidewalk Bridge	3/2/07	1	3.240	Asbestos	PCME	EMSL	3/5/07	< 0.00076	No	No	
ASBESTOS-ST11-3/2/07	030706775-0006	90 Trinity Place (roof level)	3/2/07	1	3.020	Asbestos	PCME	EMSL	3/5/07	< 0.00082	No	No	
ASBESTOS-ST12-3/2/07	030706775-0007	110 Greenwich Street (roof level)	3/2/07	1	3.040	Asbestos	PCME	EMSL	3/5/07	< 0.00081	No	No	
ASBESTOS-ST13-3/2/07	030706775-0008	Marriott Hotel, 38th Floor (roof level)	3/2/07	1	3.040	Asbestos	PCME	EMSL	3/5/07	< 0.00081	No	No	
ASBESTOS-ST14-3/2/07	030706775-0009	West Face - South end at corner (scaffolding level)	3/2/07	1	3.020	Asbestos	PCME	EMSL	3/5/07	< 0.00082	No	No	
ASBESTOS-ST15-3/2/07	030706775-0010	South Face - East end at corner (scaffolding level)	3/2/07	1	3.010	Asbestos	PCME	EMSL	3/5/07	< 0.00082	No	No	
ASBESTOS-ST16-3/2/07	030706775-0011	East Face - North end at corner (scaffolding level)	3/2/07	1	3.020	Asbestos	PCME	EMSL	3/5/07	< 0.00082	No	No	
ASBESTOS-ST17-3/2/07	030706775-0012	North Face - West end at corner (scaffolding level)	3/2/07	1	3.020	Asbestos	PCME	EMSL	3/5/07	< 0.00082	No	No	
ASBESTOS-ST1-3/3/07	030706783-0001	Southwest Area (sidewalk bridge level)	3/3/07	1	3.090	Asbestos	PCME	EMSL	3/5/07	< 0.00080	No	No	
ASBESTOS-ST2-3/3/07	030706783-0002	Southeast Area (sidewalk bridge level)	3/3/07	1	3.020	Asbestos	PCME	EMSL	3/5/07	< 0.00082	No	No	
ASBESTOS-ST4-3/3/07	030706783-0003	Northwest Area (street-level)	3/3/07	1	3.110	Asbestos	PCME	EMSL	3/5/07	< 0.00079	No	No	
ASBESTOS-ST5-3/3/07	030706783-0004	Firehouse #10 (roof level)	3/3/07	1	3.010	Asbestos	PCME	EMSL	3/5/07	< 0.00082	No	No	
ASBESTOS-ST10-3/3/07	030706783-0005	North Side Sidewalk Bridge	3/3/07	1	3.010	Asbestos	PCME	EMSL	3/5/07	< 0.00082	No	No	
ASBESTOS-ST11-3/3/07	030706783-0006	90 Trinity Place (roof level)	3/3/07	1	3.010	Asbestos	PCME	EMSL	3/5/07	< 0.00082	No	No	
ASBESTOS-ST12-3/3/07	030706783-0007	110 Greenwich Street (roof level)	3/3/07	1	2.990	Asbestos	PCME	EMSL	3/5/07	< 0.00083	No	No	
ASBESTOS-ST13-3/3/07	030706783-0008	Marriott Hotel, 38th Floor (roof level)	3/3/07	1	3.220	Asbestos	PCME	EMSL	3/5/07	< 0.00077	No	No	
ASBESTOS-ST14-3/3/07	030706783-0009	West Face - South end at corner (scaffolding level)	3/3/07	1	3.030	Asbestos	PCME	EMSL	3/5/07	< 0.00081	No	No	
ASBESTOS-ST15-3/3/07	030706783-0010	South Face - East end at corner (scaffolding level)	3/3/07	1	3.020	Asbestos	PCME	EMSL	3/5/07	< 0.00082	No	No	
ASBESTOS-ST16-3/3/07	030706783-0011	East Face - North end at corner (scaffolding level)	3/3/07	1	3.010	Asbestos	PCME	EMSL	3/5/07	< 0.00082	No	No	
ASBESTOS-ST17-3/3/07	030706783-0012	North Face - West end at corner (scaffolding level)	3/3/07	1	2.980	Asbestos	PCME	EMSL	3/5/07	< 0.00083	No	No	
ASBESTOS-ST1-3/4/07	030706778-0001	Southwest Area (sidewalk bridge level)	3/4/07	1	3.020	Asbestos	PCME	EMSL	3/5/07	< 0.00082	No	No	
ASBESTOS-ST2-3/4/07	030706778-0002	Southeast Area (sidewalk bridge level)	3/4/07	1	3.040	Asbestos	PCME	EMSL	3/5/07	< 0.00081	No	No	
ASBESTOS-ST4-3/4/07	030706778-0003	Northwest Area (street-level)	3/4/07	1	2.950	Asbestos	PCME	EMSL	3/5/07	< 0.00084	No	No	
ASBESTOS-ST5-3/4/07	030706778-0004	Firehouse #10 (roof level)	3/4/07	1	3.020	Asbestos	PCME	EMSL	3/5/07	< 0.00082	No	No	
ASBESTOS-ST10-3/4/07	030706778-0005	North Side Sidewalk Bridge	3/4/07	1	3.000	Asbestos	PCME	EMSL	3/5/07	< 0.00082	No	No	
ASBESTOS-ST11-3/4/07	030706778-0006	90 Trinity Place (roof level)	3/4/07	1	3.040	Asbestos	PCME	EMSL	3/5/07	< 0.00081	No	No	
ASBESTOS-ST12-3/4/07	030706778-0007	110 Greenwich Street (roof level)	3/4/07	1	3.040	Asbestos	PCME	EMSL	3/5/07	< 0.00081	No	No	
ASBESTOS-ST13-3/4/07	030706778-0008	Marriott Hotel, 38th Floor (roof level)	3/4/07	1	3.020	Asbestos	PCME	EMSL	3/5/07	< 0.00082	No	No	
ASBESTOS-ST14-3/4/07	030706778-0009	West Face - South end at corner (scaffolding level)	3/4/07	1	3.060	Asbestos	PCME	EMSL	3/5/07	< 0.00081	No	No	
ASBESTOS-ST15-3/4/07	030706778-0010	South Face - East end at corner (scaffolding level)	3/4/07	1	3.040	Asbestos	PCME	EMSL	3/5/07	< 0.00081	No	No	
ASBESTOS-ST16-3/4/07	030706778-0011	East Face - North end at corner (scaffolding level)	3/4/07	1	3.020	Asbestos	PCME	EMSL	3/5/07	< 0.00082	No	No	
ASBESTOS-ST17-3/4/07	030706778-0012	North Face - West end at corner (scaffolding level)	3/4/07	1	3.010	Asbestos	PCME	EMSL	3/5/07	< 0.00082	No	No	

Note:

1. The asbestos sample at Station 16 (East Face - North end at corner [scaffolding level]) on March 1, 2007 was not available for analysis on account of sample damage.